



28-Aug-2014

**PCN #:**E-14-012058

**Subject:**M.2(NGFF) 0.5mm Pitch

**Description of Change:** matte tin changed to goldflash, adding core-out hole on 4.2H HSG This change is considered by TE Connectivity as a; . Location of change, see

**Reason:** Product Improvement. To solve poor soldering and pin sunk issue

**Impact of Change:**form - fit - function

**Key Dates:**

**Contact By Date:**31-Aug-2014

**Implementation Date:**31-Aug-2014

**Product Affected**

1-2199119-1

2199125-8

2199125-9

2199230-3

2199119-6

2199230-6

2199119-8

1-2199230-5

1-2199230-3

1-2199125-9

2-2199119-3

1-2199230-1

2-2199119-0

2199119-1

2-2199119-2

## **Product Affected**

1-2199125-5  
2199128-5  
1-2199119-3  
2199128-4  
2199125-4  
1-2199125-7  
1-2199119-2  
2199230-5  
2199230-2  
2199119-5  
2199125-7  
2199230-1  
1-2199119-6  
2199119-7  
1-2199230-4  
2199119-9  
2199230-7  
2-2199119-1  
2199230-9  
1-2199119-5  
2199128-3  
1-2199230-0  
2199125-5  
2199119-3  
1-2199125-6  
2199230-8  
2199125-6  
2199128-2  
2199125-2  
2199125-1  
1-2199119-0  
2199119-4  
1-2199125-4  
1-2199125-3  
1-2199125-8  
1-2199230-2  
1-2199230-6  
2199230-4  
2199128-1  
2199125-3

## Product Affected

1-2199119-4

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.