

Product/Process Change Notifications



PCN - 17 013

Release Date: March 27 2017

Product Name:	Millipacs		
	Millipacs 5 Row Right Angle Header		
Product Manager:	Verghese John		
Subject:	Notification of Change with Immediate Effectivity		
Distribution:	Global		
Type of Change:	Materials Change		
Change Description:	Change in Resin used in Position Bar <div style="text-align: center;"> </div>		
Reason for Change:	Reduction in material purchase lead time		
Affected Parts:	All Millipacs Right Angle Shielded Header Connector (Ref Affected Part Numbers list attached)		
Effective Date of Change:	April 17, 2017		
Last Time Buy Date:	NA		
Last Disty Return Date:	NA		
Last Time Shipment Date	NA		
Datasheet Attached?	No		
Qual/Test Data Attached?	No		
Samples Availability Date:	March	30	2017
Available Alternatives?	Select		
Questions?	<i>Contact your local AFCI Representative, or Product Manager</i>		
	<i>Verghese John</i>		
	<i>email: Verghese.John@fci.com Tel: +91 484 4090 814</i>		

Note:
 Customers should contact Product Manager (or their local AFCI Representative) directly regarding any concern on the PCN.
 Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .

PCN Reference	MPN	Change	Effective Date	Last Disty Return date	Last Shipment date	Alternative Parts	Product Family
PCN17013	HM2J07PE5118N9LF	DESIGN CHANGE	17-Apr-17				560-5HTF-MILLIPACS RA HEADER SIGNAL
PCN17013	HM2J07PE5128E9LF	DESIGN CHANGE	17-Apr-17				560-5HTF-MILLIPACS RA HEADER SIGNAL
PCN17013	HM2J07PE5128N9LF	DESIGN CHANGE	17-Apr-17				560-5HTF-MILLIPACS RA HEADER SIGNAL
PCN17013	HM2J07PE51A8N9LF	DESIGN CHANGE	17-Apr-17				560-5HTF-MILLIPACS RA HEADER SIGNAL
PCN17013	HM2J07PEE128N9LF	DESIGN CHANGE	17-Apr-17				560-5HTF-MILLIPACS RA HEADER SIGNAL
PCN17013	HM2J08PE5118N9LF	DESIGN CHANGE	17-Apr-17				560-5HTF-MILLIPACS RA HEADER SIGNAL
PCN17013	HM2J09PE5118L9LF	DESIGN CHANGE	17-Apr-17				560-5HTF-MILLIPACS RA HEADER SIGNAL
PCN17013	HM2J09PE5118N9LF	DESIGN CHANGE	17-Apr-17				560-5HTF-MILLIPACS RA HEADER SIGNAL
PCN17013	HM2J09PE5168N9LF	DESIGN CHANGE	17-Apr-17				560-5HTF-MILLIPACS RA HEADER SIGNAL
PCN17013	HM2J09PE51N8N9LF	DESIGN CHANGE	17-Apr-17				560-5HTF-MILLIPACS RA HEADER SIGNAL
PCN17013	HM2J09PE51R8N9LF	DESIGN CHANGE	17-Apr-17				560-5HTF-MILLIPACS RA HEADER SIGNAL
PCN17013	HM2J65PE5118L9LF	DESIGN CHANGE	17-Apr-17				560-5HTF-MILLIPACS RA HEADER SIGNAL
PCN17013	HM2J65PE5118N9LF	DESIGN CHANGE	17-Apr-17				560-5HTF-MILLIPACS RA HEADER SIGNAL
PCN17013	HM2J66PE5118N9LF	DESIGN CHANGE	17-Apr-17				560-5HTF-MILLIPACS RA HEADER SIGNAL
PCN17013	HM2J70PE5118N9LF	DESIGN CHANGE	17-Apr-17				560-5HTF-MILLIPACS RA HEADER SIGNAL
PCN17013	HM2J70PEE128E9LF	DESIGN CHANGE	17-Apr-17				560-5HTF-MILLIPACS RA HEADER SIGNAL
PCN17013	HM2J70PEE128N9LF	DESIGN CHANGE	17-Apr-17				560-5HTF-MILLIPACS RA HEADER SIGNAL
PCN17013	HM2J71PE5118N9LF	DESIGN CHANGE	17-Apr-17				560-5HTF-MILLIPACS RA HEADER SIGNAL
PCN17013	HM2J71PEE128N9LF	DESIGN CHANGE	17-Apr-17				560-5HTF-MILLIPACS RA HEADER SIGNAL