

Product Name:	HPL584	
	SD CARD READER	
Product Manager:	Wang , Jimmy	
Subject:	Notification of Change with Immediate Effectivity	
Distribution:	Affected customers	
Type of Change:	Documentation Change	
Change Description:	2D Drawing update to Rev L, adding the lubricating oil option (L8030 and L8005).	
Reason for Change:	Lubricating oil L8030 and L8005 is also used for production. Information missing on 2D drawing being updated.	
Affected Parts:	10067847*, see affected PN list	
Effective Date of Change:	July,31 2023	
Last Time Buy Date:		
Earliest Disty Return Date:		
Last Time Shipment Date		
Datasheet Attached?	Yes	
Qual/Test Data Attached?	Yes	
Samples Availability Date:	31 July ,2023	
Available Alternatives?		
Questions?	<i>Contact your local ACS Representative, or Product Manager</i>	
	<i>Wang , Jimmy / Product Manager</i>	
	<i>Jimmy.Wang@fci.com</i>	

Note:

Customers should contact Product Line Manager (or their local Amphenol Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .

