

Product Change Notice

Alps PCN: LO022823_Disti_Rev1_Remain Active

Date: March 17, 2023

Type of Change: Life Cycle Update

Title of Change: Revision of 2023 Notice of Discontinuation – Sensors, Switches, and Variable Resistors_Remain Active

Description of Change: Products that were identified as discontinued due to system error but remain Active

Contact Information: Sales and Marketing Contact
Sales@alps.com
Alps Alpine North America, Inc.

Product Affected: Variable Resistors

AFFECTED ALPS ALPINE PART NUMBERS

Part Number	Life Cycle
EC05E1220202	Active
EC05E1220203	Active
EC05E1220401	Active
EC09E1520407	Active
EC09E1524404	Active
EC09E1524418	Active
EC10E1220501	Active
EC10E1220503	Active
EC10E1260502	Active
EC10E1260507	Active
EC1110120005	Active
EC111012000U	Active
EC111012010H	Active
EC1110120201	Active
EC11E09204A4	Active
EC11E09244AQ	Active
EC11E09244BS	Active
EC11E0B2LB01	Active
EC11E15244B2	Active
EC11E15244G1	Active
EC11E1534408	Active
EC11E153440D	Active
EC11E1820402	Active
EC11E1834403	Active
EC11E183440C	Active

Part Number	Life Cycle
EC11E2434403	Active
EC11EBB24C03	Active
EC11J0920404	Active
EC11J0924411	Active
EC11J0925403	Active
EC11J152040F	Active
EC11J1524404	Active
EC11J1524413	Active
EC11J1525402	Active
EC11K0920404	Active
EC11K0924401	Active
EC11K0924404	Active
EC11K0925401	Active
EC11K1520401	Active
EC11K1524406	Active
EC11K1525413	Active
EC12D1524406	Active
EC12D1564402	Active
EC12D1564404	Active
EC12E1220301	Active
EC12E1220405	Active
EC12E1220406	Active
EC12E1220407	Active
EC12E1220813	Active
EC12E1240301	Active

Note: Lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

AFFECTED ALPS ALPINE PART NUMBERS

Part Number	Life Cycle
EC12E1240405	Active
EC12E1240406	Active
EC12E24104A6	Active
EC12E2420301	Active
EC12E24204A2	Active
EC12E24204A7	Active
EC12E24204A9	Active
EC12E2420801	Active
EC12E2420802	Active
EC12E2420803	Active
EC12E2430401	Active
EC12E2430404	Active
EC12E2430803	Active
EC12E2430804	Active
EC12E2440301	Active
EC12E24404A8	Active
EC12E2460802	Active
EC18AGA20402	Active
EC18AGA20403	Active
EC18AGB20401	Active
EC21A0920401	Active
EC21A0950402	Active
EC21A1520401	Active
EC21A1520407	Active
EC21C1520402	Active
EC28A1520401	Active
EC28A1550407	Active
EC28A1560401	Active
EC28A1560501	Active
EC28A1850402	Active
EC35A1520402	Active
EC35A1550502	Active
EC35AH120401	Active
EC35AH220403	Active
EC35AH220502	Active
EC35CH120401	Active
EC40A1520403	Active
EC40A1520405	Active
EC50A0920404	Active

Part Number	Life Cycle
EM11B16140A4	Active
EM11B16140AE	Active
EM20B4014000	Active
RD6R1A0008	Active
RD7081015A	Active
RD708A029A	Active
RD7091008A	Active
RD7121008A	Active
RD712A028A	Active
RDC1010A12	Active
RDC1014A09	Active
RDC1022A05	Active
RDC10320RB	Active
RDC1047A03	Active
RDC501015A	Active
RDC502012A	Active
RDC503051A	Active
RDC503052A	Active
RDC506002A	Active
RDC803101A	Active
RDC9010006	Active
RDC9010007	Active
RK08H11100UD	Active
RK08H11100X7	Active
RK08H11100XC	Active
RK08H1110A04	Active
RK08H1120A05	Active
RK08H113003G	Active
RK08H12100GP	Active
RK08H122005A	Active
RK08H123002K	Active
RK09711100F8	Active
RK09711100RA	Active
RK097111020N	Active
RK097111080R	Active
RK0971110909	Active
RK097111091M	Active
RK0971110D7F	Active
RK0971110D88	Active

Note: Lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

AFFECTED ALPS ALPINE PART NUMBERS

Part Number	Life Cycle
RK09711110AL	Active
RK09711110EL	Active
RK0971111Z0P	Active
RK0971111Z32	Active
RK097111202Q	Active
RK097111401U	Active
RK0971114D0B	Active
RK0971114Z07	Active
RK0971114Z1J	Active
RK097111T064	Active
RK097111TD44	Active
RK097111TZ17	Active
RK097111TZ29	Active
RK097111U00S	Active
RK097111UZ03	Active
RK0971210097	Active
RK09712100AV	Active
RK0971210Z2M	Active
RK0971214Z06	Active
RK097121TD57	Active
RK097122008T	Active
RK09712200HA	Active
RK09712200MC	Active
RK09712200MT	Active
RK09712200MY	Active
RK0971221Z05	Active
RK0971221Z11	Active
RK097122200G	Active
RK0971224Z01	Active
RK097122T017	Active
RK097122TZ0A	Active
RK097221004C	Active
RK097221005C	Active
RK09D1130A1N	Active
RK09D1130C2P	Active
RK09D117000B	Active
RK09D117000C	Active
RK09K11100E9	Active
RK09K1110A2S	Active

Part Number	Life Cycle
RK09K1110AK4	Active
RK09K1110AY2	Active
RK09K1110B1R	Active
RK09K1110B26	Active
RK09K113004U	Active
RK09K1130081	Active
RK09K1130A5R	Active
RK09K1130A6S	Active
RK09K1130A70	Active
RK09K1130A8G	Active
RK09K1130AAU	Active
RK09K1130ACL	Active
RK09K1130ACM	Active
RK09K1130AH1	Active
RK09K1130AJ3	Active
RK09K1130AP5	Active
RK09K1130AU2	Active
RK09K1130BM4	Active
RK09K1130D1U	Active
RK09K1130D62	Active
RK09K12A0A6R	Active
RK09K12A0B0W	Active
RK09K12C0A19	Active
RK09K12C0A8K	Active
RK09K12C0A8P	Active
RK09L112003P	Active
RK09L1120A2S	Active
RK09L1120A69	Active
RK09L114001T	Active
RK09L1140A2U	Active
RK09L1140A5E	Active
RK09L1140A5P	Active
RK09L1140A65	Active
RK09L1140A66	Active
RK09L122002M	Active
RK09L1220A1B	Active
RK09L124000Z	Active
RK09L1240A12	Active
RK09L1240C2K	Active

Note: Lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

AFFECTED ALPS ALPINE PART NUMBERS

Part Number	Life Cycle
RK09L12B0A31	Active
RK09L12B0A3Z	Active
RK09L12D0A1T	Active
RK09L12D0A1W	Active
RK09L12D0C0G	Active
RK09L12D0C1L	Active
RK09L12D0C1M	Active
RK09Y11L0001	Active
RK10J11E002Y	Active
RK10J11E0034	Active
RK10J11E0A0A	Active
RK10J11R0A0H	Active
RK10J12E0024	Active
RK10J12E002L	Active
RK10J12E0A0A	Active
RK10J12R0052	Active
RK10J12R0A0B	Active
RK1191114001	Active
RK1191124001	Active
RK11K1110A3D	Active
RK11K1120060	Active
RK11K1120A31	Active
RK11K1120A5T	Active
RK11K1130040	Active
RK11K1130A07	Active
RK11K1130A0M	Active
RK11K1130A2X	Active
RK11K114001Z	Active
RK11K114003Y	Active
RK11K1140A23	Active
RK11K1140A2S	Active
RK11K1140A3L	Active
RK11K1140A4Q	Active
RK11K1140A9L	Active
RK12L1210C0R	Active
RK12L1210C1N	Active
RK12L123000E	Active
RK12L1230C0K	Active
RK12L1230C1M	Active

Part Number	Life Cycle
RK12L1270009	Active
RK12L12C0A0A	Active
RK12L12C0A0E	Active
RK12L12C0A0G	Active
RK12L12C0C0V	Active
RK14K1210A1B	Active
RK14K122001W	Active
RK14K1220024	Active
RK14K1220A0F	Active
RK14K1220A25	Active
RK14K1230A0X	Active
RK14K1230A2X	Active
RK14K1240036	Active
RK14K1240062	Active
RK14K1240A4R	Active
RK14K1240D04	Active
RK14K12A0A3C	Active
RK14K12B0A0E	Active
RK14K12B0A0R	Active
RK14K12C0A1S	Active
RK14K12D0A18	Active
RK14K12D0A1X	Active
RK1631110TBK	Active
RK1631110TNP	Active
RK1631110TT3	Active
RK1631110U0Q	Active
RK1631110U1Q	Active
RK16312101A2	Active
RK1631210AWN	Active
RK1631210AX9	Active
RK16312A0B85	Active
RK16312A0BKH	Active
RK16312A0BKR	Active
RK16812MG097	Active
RK16812MG099	Active
RK16812MG09T	Active
RK16812MG0AQ	Active
RK16812MGA14	Active
RK16814MGA0K	Active

Note: Lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

AFFECTED ALPS ALPINE PART NUMBERS

Part Number	Life Cycle
RK271111001T	Active
RK2711120026	Active
RK27112A00AK	Active
RK27112A00B9	Active
RK27112A00CC	Active
RK27112B0A19	Active
RK27114A0A0A	Active
RK27114A0A0F	Active
RK39A1A00007	Active
RK39A1A00027	Active
RK39A1A00028	Active
RK45C1A00003	Active
RKJXM1015001	Active
RKJXS1004001	Active
RKJXU1210006	Active
RKJXV1220001	Active
RKJXV1224005	Active
RKJXW1014002	Active
RS08U11AZ001	Active
RS15111A900B	Active
RS15H111CA04	Active
RS15H113C001	Active
RS15H113CA05	Active
RS15H11AA008	Active
RS15H11AA00G	Active
RS15H11AA04M	Active
RS15H121A009	Active
RS15H12AA009	Active
RS15H12AA00F	Active
RS201111J011	Active
RS20111A9A03	Active
RS20H111C009	Active
RS20H113C008	Active
RS20H11AA015	Active
RS20H11AA019	Active
RS20H11AA01U	Active
RS20H11AA02T	Active
RS20H12AC002	Active
RS3011114A02	Active

Part Number	Life Cycle
RS301111A01G	Active
RS301111C01L	Active
RS301111J00P	Active
RS301111JA07	Active
RS30111A602N	Active
RS30111A9012	Active
RS30111AC00V	Active
RS30111AJ01K	Active
RS30111AJ01R	Active
RS3011246A02	Active
RS30112AC00J	Active
RS30112AJA02	Active
RS30H111A00D	Active
RS30H11AA009	Active
RS30H11AA00G	Active
RS30H11AA00P	Active
RS30H11AAA02	Active
RS30H11AAA0B	Active
RS30H121A00B	Active
RS30H12AA003	Active
RS4511166000	Active
RS45111A6A06	Active
RS45111A900F	Active
RS45111ABA02	Active
RS45111AJ00L	Active
RS45111F9002	Active
RS451121400A	Active
RS45112A400G	Active
RS45112A600J	Active
RS60112A600N	Active
RS60112A600U	Active
RS6011DP6002	Active
RS6011DP6003	Active
RS6011SP6003	Active
RS6011SP6004	Active
RS6011Y19004	Active
RS6011Y64005	Active
RS6011YA600M	Active
RS6011YA9A06	Active

Note: Lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

AFFECTED ALPS ALPINE PART NUMBERS

Part Number	Life Cycle
RS60K11A9010	Active
RS60K11K9A13	Active
RS60N11M9A0F	Active
RS60N11M9A0K	Active
RS60N1219A04	Active
RSA0K11A901L	Active
RSA0K11K9A16	Active

Part Number	Life Cycle
RSA0K11V901S	Active
RSA0K12A1013	Active
RSA0K12K9A14	Active
RSA0N111900Q	Active
RSA0N11M9A0J	Active
RSA0N1219A03	Active
RSA0N1269A04	Active

Alps Alpine Sites Affected: Americas

Effective Date: Immediately

Note: Lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.