

## Amphenol Canada Corp - Product Change Notice (PCN)

PCN Date	May 1 2019
Supplier Name:	Amphenol Canada Corp.
Amphenol Canada PCN Number	PCN-C1380
Description of Change	Change soldering pin area from matte tin to gold flash see the below picture.
Reason for Change	Optimize plating process and improve assembly process.
Summary of changes between new and old part	The termination is matte tin for old part number. The termination is gold flash for new part number.
Traceability guidelines (lot code / date code, markings, ship date...)	Pending
Last Time Buy Date	
Datasheet attached? & Filename(s)	
Qual Test data attached? & Filename(s)	

Customer Part Number	Amphenol Old Part Number	Amphenol New Part Number	PCN Effectivity Date	Samples Availability Date	Last Time Buy Date	Expected Supplier Qual Date
	UE76-A20-3000T	UE76-A20-2000T	May 1 2019	May 1 2019	NA	NA

# Amphenol-PCN-C1380


2019-05-01

Amphenol Information Communications  
and Commercial Products




# Amphenol ICC

Old part number



Plating gold flash on soldering pin area for new part number



New version, others are same with current product.