



18-May-2010
PCN #:E-10-010589

Subject:Product Change of 35 posn AMPSEAL header assembly

Description of Change:New process for DIP seal

Reason:Document clarification.

Impact of Change:Form-Fit-Function

Key Dates:

Contact By Date:24-May-2010

Implementation Date:24-May-2010

Product Affected

- 1-776087-1
- 1-776087-2
- 1-776087-4
- 1-776087-5
- 1-776163-1
- 1-776163-2
- 1-776163-4
- 1-776163-5
- 1-776163-6
- 1-776228-1
- 1-776228-2
- 1-776228-4
- 1-776228-5
- 1-776231-1
- 1-776231-2
- 1-776231-4
- 1-776231-5

Product Affected

1-776262-2
1-776262-4
1-776262-5
1-776267-1
1-776267-2
1-776267-4
1-776280-1
1-776280-2
776087-1
776087-2
776087-4
776087-5
776163-1
776163-2
776163-4
776163-5
776228-1
776228-2
776228-4
776228-5
776231-1
776231-2
776231-4
776231-5
776262-1
776262-4
776262-5
776267-1
776267-4
776280-1
776280-2
776280-6

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

Tyco Electronic's corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the Tyco Electronics Product Information Center at 800-522-6752 or your Tyco Electronics Sales Representative.