

## Product Change Notice

November 15, 2010

### PhotoMOS Relays: Change of Production Location



#### 1. Description:

Manufacturing transferred from Ise plant (Japan) to Panasonic Electric Works, Thailand Ltd. (Navanakorn, Thailand)

#### 2. Affected Products: A complete list of part numbers is attached.

DIP 4-pin

AQY211EH	AQY212GH
AQY211EHA	AQY212GHA
AQY211EHAX	AQY212GHAX
AQY211EHAZ	AQY212GHAZ

SOP 4-pin

AQY212GS
AQY212GSX
AQY212GSZ

#### 3. Reason: Production restructuring.

#### 4. Schedule: Effective February 2011 (production basis)

#### 5. Part Number and Performance: Remain unchanged.

Please contact Panasonic Electric Works representatives with any question.