

Product Change Notification

INDUCTIVE COMPONENTS



March, 2016

Bourns® Model FB2000 Series Wide-Band Chokes

Changes to Core Packaging and Minimum/Multiple Order Quantities

In February 2016, Bourns announced certain changes to the core material and manufacturing location of [Model FB2000](#) and on March 1, 2016, Bourns announced that such changes would be effective immediately. It has now come to our attention that the packaging, Minimum Order Quantity (MOQ) and Multiple Order Quantity (Mult) of the Bourns® Model FB2000 Series will also be changing as a result of the core material and manufacturing location change. The current bulk packaging will be changed to a tray design.

The change in packaging will affect the MOQ/Mult ordering quantities. For your convenience, Table 1 lists the affected part numbers and the corresponding existing and revised quantities.

The changes do not affect the form, fit or function of the components.

Part Number	Existing Packaging		Revised Packaging	
	MOQ	Mult	MOQ	Mult
FB20009-3B-RC	1200	300	1320	110
FB20019-4B-RC	1200	300	1320	110
FB20010-3B-RC	1200	300	1320	110
FB20020-4B-RC	1200	300	1320	110
FB20011-3B-RC	1200	300	1320	110
FB20021-4B-RC	1200	300	1320	110
FB20022-4B-RC	1200	300	2640	220

Implementation dates are as follows:

*Date that manufacturing of existing packaging and MOQ/Mult will cease: **Immediately***

*Date that manufacturing of revised packaging and MOQ/Mult will begin: **Immediately***

*First date code using the above changes: **1612***

If you have any questions or need additional information, please feel free to contact [Customer Service/ Inside Sales](#).

Part Number	Existing Packaging		Revised Packaging	
	MOQ	Mult	MOQ	Mult
FB20009-3B-RC	1200	300	1320	110
FB20019-4B-RC	1200	300	1320	110
FB20010-3B-RC	1200	300	1320	110
FB20020-4B-RC	1200	300	1320	110
FB20011-3B-RC	1200	300	1320	110
FB20021-4B-RC	1200	300	1320	110
FB20022-4B-RC	1200	300	2640	220