

Product Change Notification

INDUCTIVE COMPONENTS



December, 2016

Bourns® Model FB2000 Series Wide-Band Chokes

Change to Core Design

Bourns has changed the core design of the [Model FB2000 Series](#) Wide-Band Chokes starting with the manufacturing date code 1629. Chamfers are included at both ends of the core to reduce the possibility of material chipping during production assembly. See Table 1 for details.

This core modification will not affect the form, fit or function of the wide-band choke. However, the quality and reliability of the component should be enhanced.

Table 1		
Series	Current	Revised
FB2000	<p>Right Angle</p>	<p>0.25 mm (Ref.) Chamfers</p>

Affected Part Numbers	
FB20009-3B-RC	FB20011-3B-RC
FB20019-4B-RC	FB20021-4B-RC
FB20010-3B-RC	FB20022-4B-RC
FB20020-4B-RC	

If you have any questions or need additional information, please feel free to contact [Customer Service/ Inside Sales](#).

Part Numbers
FB20009-3B-RC
FB20019-4B-RC
FB20010-3B-RC
FB20020-4B-RC
FB20011-3B-RC
FB20021-4B-RC
FB20022-4B-RC