


# BOURNS® Product Update Memo

## TRIMMING POTENTIOMETERS

July, 2006

Bourns Manufacturers Representatives  
Corporate Distributor Product Managers  
Americas Sales Team  
Asia Sales Team  
Europe Sales Team  
Bourns Internal  
Bourns Plant Managers



## Trimmer Distributor Product Definition Change

Bourns® Trimpot® Division is pleased to announce a distributor product definition change on select resistance values of models 3266, 3269, 3296, 3299, 3306, 3309, 3314, 3352, 3361, 3362, 3364 and 3386. The change from a C to an A status was made to promote growth in our newest models and to improve our position with existing models. The additions are highlighted in Figure 1.

Feel free to contact me if you have any questions regarding this product update.

Best Regards,

[Emill Melliz](#)

Product Manager – Trimpot® Division  
Bourns, Inc.



Trimmer Distributor Product Definition Change

July, 2006

Page 3 of 3

MODEL	1 0 0	2 0 0	5 0 0	1 0 1	2 0 1	5 0 1	1 0 2	2 0 2	5 0 2	1 0 3	2 0 3	2 5 3	5 0 3	1 0 4	2 0 4	2 5 4	5 0 4	1 0 5	2 0 5	5 0 5	
3352T										A				A							
3361P						A		A	A	A	A										
3361S										A											
3362H						A	A	A	A	A	A	A	A								
3362P				A	A	A	A	A	A	A	A		A	A		A					
3362W				A	A	A	A	A	A	A	A		A	A							
3362X						A	A	A	A	A	A		A	A							
3362R										A											
3364W										A											
3386B					A	A	A	A	A	A	A										
3386C						A	A	A	A	A	A	A					A				
3386F			A	A	A	A	A	A	A	A	A	A	A	A	A	A	A	A			
3386H				A		A	A	A	A	A	A	A	A	A	A		A				
3386P			A	A	A	A	A	A	A	A	A	A	A	A	A	A	A	A	A	A	
3386W		A	A	A	A	A	A	A	A	A	A	A	A	A			A	A			
3386X				A	A	A	A	A	A	A	A		A	A	A	A	A	A			
RJ24FW							A	A	A	A	A		A	A							
RJ24FX									A												

Figure 1