


BOURNS®

Product Update Memo

TRIMMERS

October, 2006

Bourns Manufacturers Representatives
 Corporate Distributor Product Managers
 Americas Sales Team
 Asia Sales Team
 Europe Sales Team
 Bourns Internal
 Bourns Plant Managers



3214G/J and 3224G/J Product Improvement

Bourns® Trimpot® Division is updating the lead-frame configuration on Models [3214](#) and [3224](#). This change will only affect pin styles G and J. This modification is a design improvement to allow increased manufacturing automation. The changes are illustrated in figures 1 and 2. Shipments with this modification will commence on October 16, 2006 (Date Code: 0642). There will be a transition period where both types of lead-frames will be shipped.




Figure 1: J Pin Style




Figure 2: G Pin Style

Please feel free to contact Bourns if you have any questions or comments.

AMERICAS: [Anna Melissa Tiangco](#)Tel: 951-781-5114Fax: 951-781-2616

EUROPE: [Markus Bundschu](#)Tel: +353-21-4515-242Fax: +353-21-4515-292

ASIA: Asia Customer ServiceTel: +886(0)2-2562-4117

Best Regards,

[Emill Melliz](#)

Product Manager

Bourns® Trimpot® Division