


BOURNS®

Product Change Notification

TRIMPOT® TRIMMING POTENTIOMETERS


Bourns Manufacturers Representatives
Corporate Distributor Product Managers
Americas Sales Team
Asia Sales Team
Europe Sales Team

August, 2010




Bourns® Trimpot® Product Line Announces Model 3362 Product Change

Bourns® Trimpot® Product Line has updated the 3362 rotor detail. The rotor change was implemented in April 2005 for 3362 product manufactured in Costa Rica. For 3362 product manufactured in Taiwan, the new rotor was implemented with date code 024, or the week of June 19, 2010. This change does not affect fit, form or function of the product.



Old Rotor



New Rotor

Regards,
Christine Peterson
Applications Engineer
Bourns® Trimpot® Product Line