

## Product Change Notice

Date:	September 12, 2022
Overview:	The ACi4400 series is being discontinued
Reason for Change:	Cost increases have priced this series out of the market and a replacement series being launched in 2023 will offer updated technology
Affected Part No(s):	Please see attached part listing on page 2
Design Change Detail:	The ACi4400 series is being discontinued and will no longer be available to order
Effective Date:	Immediately; all existing orders will be filled, but no new orders can be accepted
Last Time Buy Deadline:	N/A
Pricing:	N/A
ebm-papst employee:	Jeannine Zenobi
Attachments:	Part number listing
Comments:	The AxiACi120 series launching in 2023 will replace this series

**Affected Part Numbers**

ACI4400/2HHP	ACI4400NHHR-003
ACI4400H	ACI4400NMLU
ACI4400HH	ACI4400NNU
ACI4400HHAU	ACI4410HH
ACI4400HHR-516	ACI4420H
ACI4400HHU-505	ACI4420HH
ACI4400HU-517	ACI4420HHR
ACI4400L	ACI4420ML
ACI4400MLR	ACI4420N

Form No: 1274	Quality Record - No	Page 1 of 1
Rev. – Orig, Released 08/28/14	Retention Period – 1 year	Dept. Owner – Sales/Marketing

<b>ebm-papst Part Numbers</b>
ACI4400/2HHP
ACI4400H
ACI4400HH
ACI4400HHAU
ACI4400HHR-516
ACI4400HHU-505
ACI4400HU-517
ACI4400L
ACI4400MLR
ACI4400NHHR-003
ACI4400NMLU
ACI4400NNU
ACI4410HH
ACI4420H
ACI4420HH
ACI4420HHR
ACI4420ML
ACI4420N