



PCN - 10 158

Issue Date: December 20 2010

Product Name:	55917-501LF and 87520-0010BLF			
	HPL511 – USB			
Product Manager:	James Wang			
Subject:	Process Change Notification			
Distribution:	Only for customer: IBM and its OEM			
Type of Change:	Manufacturing Location Change			
Change Description:	To move molds to in-house from supplier for USB plastic part.			
Reason for Change:	To continually improve the performance of L/T			
Affected Parts:	55917-501LF and 87520-0010BLF			
Effective Date of Change:	March	31	2011	The sample is available on Mar. 31'2011
Last Time Buy Date:	N/A	N/A	N/A	
Last Disty Return Date:	N/A	N/A	N/A	
Datasheet Attached?	No			
Qual/Test Data Attached?	No			
Samples Availability Date:	March	31	2011	The sample is available on Mar. 31'2011
Available Alternatives?	N/A			
Questions?	Contact your local FCI Representative, or			
	James Wang / Product manager			
	Phone number: 86 513 80167254 / e-mail address: James.wang@fci.com			

PCN	Item Number	Change	Effective Date	Last Shipment Date	Last Disty return date	Replacement Part	Alternate Part	Comments
PCN10158	55917-501LF	MANUFACTURING LOCATION CHANGE	31-Mar-11					
PCN10158	87520-0010BLF	MANUFACTURING LOCATION CHANGE	31-Mar-11					