



PCN - 11 021

Issue Date: March 10 2011

Product Name:	Edge Card			
	PCI EXPRESS EDGE CARD			
Product Manager:	Kevin Cheng			
Subject:	Process Change Notification			
Distribution:	Global			
Type of Change:	Manufacturing Location Change			
Change Description:	Production site change for specific PCIe part number.			
Reason for Change:	For improvement of production activity and process. FCI has decided to change manufacturing site of specific PCIe product. No function or performance of product will be impacted by this change.			
Affected Parts:	see the attached list			
Effective Date of Change:	June	10	2011	
Last Time Buy Date:	N/A	N/A	N/A	
Last Disty Return Date:	N/A	N/A	N/A	
Datasheet Attached?	N/A			
Qual/Test Data Attached?	N/A			
Samples Availability Date:	March	01	2011	
Available Alternatives?	N/A			
Questions?	Contact your local FCI Representative, or			
	Kevin Cheng / Product Marketing Manger			
	+886-3-4549135/ kevin.Cheng@fci.com			

PCN	Item Number	Change	Effective Date	Last Shipment Date	Last Disty return date	Replacement Part	Alternate Part	Comments
PCN11021	10018783-00002MLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-00103TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-00111TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-00112TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-00113TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-00200MLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-00200TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-00203TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-10000MLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-10000TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-10002MLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-10002TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-10003MLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-10003TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-10010MLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-10010TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-10012TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-10013TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-10022TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-10023TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-10030TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-10033ZLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-10100MLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-10100TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-10102TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-10103TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-10110TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-10112TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-10113TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-10120TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-10122TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-10123TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-10200MLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-10200TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-10202MLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-10202TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-10203TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-10210TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-10212TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10018783-10213TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					

[illegible]

[illegible]

PCN11021	10054652-10220TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10057596-10010TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10057596-10020TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10057596-10110TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10057596-10120TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10063960-10010TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10063960-10110TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10063960-10120TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10063960-10210TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10063960-10220TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10066356-10010TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10066356-10020TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10066356-10110TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10066356-10120TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10066356-10210TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10066356-10220TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10069690-10000TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10069690-10001TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10069690-10002TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10069690-10003TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10069690-10012TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10069690-10013TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10069690-10100TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10069690-10102TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10069690-10103TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10069690-10110TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10069690-10111TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10069690-10112TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10069690-10113TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10069690-10202TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10069690-10212TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10073481-11110TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10083987-11113TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10106033-10013TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10108777-00002MLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10108777-10002MLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10108777-10030TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10108777-10201MLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10108777-11101TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10108777-11102TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10108777-11103TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					
PCN11021	10108777-11111TLF	MANUFACTURING LOCATION CHANGE	10-Jun-11					