

PRODUCT ADVISORY NOTICE

KEEPING YOU INFORMED OF PRODUCT CHANGES

To: All Customers, Sales Representatives and Distributors

Date: February 12, 2016

Subject: Alternate Gold Plating Supplier added to approved source list

This Product Advisory Notice is to alert you that an additional Gold Plating Supplier has been added to the approved list of suppliers for gold plating on commons and terminals. This additional supplier will be used to handle the increased volumes of demand for these types of components. The change will affect all Grayhill 50, 51 56 and 58 Series Rotary switches and modified versions of those series. Our records show your company has purchased one or more of the affected part numbers in the past. Please forward this notification to the appropriate person(s) in your organization.

Description of Change

Grayhill is adding an additional approved source of supply for Gold Plating

Reason for Change

This change increases the capacity for terminals and commons to be plated for 50, 51, 56, and 58 Series Rotary Switches and modified versions of those series.

Effective Date

The material change will start to be implemented by February 22, 2016

Part Numbers Affected

All parts beginning with 50, 51, 56 and 58

Test Data Available

Samples from the new supplier have passed our qualification testing. A summary of the tests performed and the full test reports can be found online on the following pages.

Action Required


Please forward this notification and the test report to the appropriate person(s) in your organization. If the change is acceptable, no action is necessary. If you would like to receive additional information or have questions, contact your Grayhill, Inc. sales associate.



PRODUCT ADVISORY NOTICE

KEEPING YOU INFORMED OF PRODUCT CHANGES

Silver plating specification: 7.62 – 10.16 μm



PRODUCT ADVISORY NOTICE

KEEPING YOU INFORMED OF PRODUCT CHANGES

Gold plating specification: 762 – 1,016 nm

