

PRODUCT ADVISORY NOTICE

KEEPING YOU INFORMED OF PRODUCT CHANGES

To: All Customers, Sales Representatives and Distributors

Date: December 13, 2017

Subject: 62HS Series Behind Panel Reduction

This Product Advisory Notice is to alert you that there is an upcoming design change to our 62HS series of optical encoder. Your company has purchased one or more of the affected part numbers in the past. Please forward this notification to the appropriate person(s) in you organization.

Description of Change

Grayhill is implementing a process improvement on the 62HS encoders. The encoder is being shortened by 0.015" to provide a larger process window for orbital riveting of the 62HS encoders. Grayhill has thoroughly tested this revision and the change has no negative impact on the performance of the encoder.

Reason for Change

Process improvement

Effective Date

The change will be effective on order shipping after December 13, 2017.

Part Numbers Affected

62HS22-H0-020C	62HS22-H9-035C	62HS30-H9-020C
62HS22-H0-040C	62HS22-H9-040C	62HS30-H9-030C
62HS22-H0-040S	62HS22-H9-040S	62HS30-H9-040C
62HS22-H0-050S	62HS22-H9-050C	62HS30-H9-050S
62HS22-H0-060S	62HS22-H9-050S	62HS30-H9-060C
62HS22-H0-140S	62HS22-H9-080C	62HS45-H0-P
62HS22-H0-150S	62HS22-H9-100S	62HS45-H0-040C
62HS22-H9-P	62HS22-H9-140S	62HS45-H9-P
62HS22-H9-020C	62HS30-H0-040C	62HS45-H9-020C
62HS22-H9-020S	62HS30-H9-P	62HS45-H9-040C

Action Required

If you have questions, please contact your Grayhill, Inc. Sales Associate for further information at 708.354.1040.

