

# PRODUCT ADVISORY NOTICE

---

## KEEPING YOU INFORMED OF PRODUCT CHANGES

---

**To:** All Customers, Sales Representatives and Distributors

**Date:** May 30, 2012

**Subject:** 78C Series Obsolescence

This Product Advisory Notice is to alert you that Grayhill is discontinuing sales and production of the 78C right angle DIP switch series as of 09/01/2012... ***Please forward this notification to the appropriate person(s) in your organization.***

### **Description of Change**

Grayhill is discontinuing sales and production of the 78C right angle DIP switch series and will be offering the 78B right angle switches as drop-in alternatives to the 78C. The replacement part number for any 78C part number is as follows: 78**C**XXRAT is replaced by 78**B**XXRAT, 78**C**XXSRAT is replaced by 78**B**XXSRAT. (note: Although The 78B and 78C are described as interchangeable, slight dimensional differences may occur between the styles. Samples of the 78BXXRAT are available by contacting Grayhill sales. )

### **Reason for Change**

The 78B switches use the ball and spring contact system that has proven to be a reliable and effective DIP switch product for over 40 years for Grayhill.

### **Effective Date**

September 1, 2012

### **Part Numbers Affected**

- 78C02RAT
- 78C04RAT
- 78C04SRAT
- 78C05RAT
- 78C05SRAT
- 78C06SRAT
- 78C08RAT
- 78C08SRAT
- 78C10RAT
- 78C10SRAT
- 78C12RAT
- 78CAP-06

### **Action Required**

Any orders for 78C product must be completed by 09/01/2012. Orders are non-cancelable non-returnable. Please contact your Grayhill, Inc. sales associate for further information.

