

Product Change Notification

[Home](#)

The information below reflects a change that is being implemented.

Notice Date: 05/09/2005

Product Category: Battery Management; Linear Devices; Mixed Signal Devices; Power Management; Thermal Management; 93xxx

Notification Subject: Change #557 : QUALIFICATION OF 6L SOT-23 PACKAGE AT HANA

Notification Body:

Microchip Part#s Affected

93AA46A
93AA46B
93AA56A
93AA56B
93AA66A
93AA66B
93AA76A
93AA76B
93AA86A
93AA86B
93C46A
93C46B
93C56A
93C56B
93C66A
93C66B
93C76A
93C76B
93C86A
93C86B
93LC46A
93LC46B
93LC56A
93LC56B
93LC66A
93LC66B
93LC76A
93LC76B
93LC86A
93LC86B
MCP1251
MCP4022
MCP4023
MCP603
MCP6043
MCP6143
MCP6273
MCP6283
MCP6293
MCP73826
PIC10F200

PIC10F202
PIC10F204
PIC10F206
TC1035
TC1038
TC1039
TC1072
TC1073
TC1219
TC1220
TC1221
TC1222
TC1240
TC1240A
TC1240A
TC2014
TC2015
TC2054
TC2055
TC2185
TC2186
TC3826
TC670

Description of Change:
NEW ASSEMBLY SITE

Effects on Data Sheet:
NONE

Reason for Change:
INCREASED CAPACITY

Estimated Change Implementation Date(s):
JUNE, 2005

Markings to Distinguish Revised From Unrevised Devices: (e.g.: Date Code, Device Marking, Ship Container Marking)
SHIP CONTAINER MARKING, DEVICE MARKING

Close

i2 Technologies US, Inc.

HTML Pages converted to PDF Document

This document contain component information from the manufacturer's website which are not available in a revision controlled document from the manufacturer. To facilitate the addition of these parts into the Electronics Database, we are converting the HTML pages related to that part, from the manufacturer's website into Adobe PDF format. The contents of this document is based on the information provided on the manufacturer's website, therefore the information may have been changed by the manufacturer since this was created.

