





Product Change Notification - CYER-16AOEB180

Date: 20 Jan 2012

Product Category: 8-bit Microcontrollers; RF and Security; Analog (Linear & Mixed Signal) AND Interface; Touch Sensing Technologies; 16-bit Microcontrollers and Digital Signal Controllers

Device Family:  

Notification subject: CCB 1090 final notification: Qualification of 18L PDIP at ALPH (MMT).

Notification text:

PCN Status:
Final notification

Microchip Parts Affected:
See attachments of affected catalog part numbers (CPN) labeled as...
PCN_CYER-16AOEB180_Affected_CPN.xls
PCN_CYER-16AOEB180_Affected_CPN.pdf

Description of Change:
Qualification of 18L PDIP at ALPH (MMT).

Impacts to Data Sheet:
None

Reason for Change:
To improve manufacturability

Change Implementation Status:
Complete

Estimated First Ship Date:
January 27, 2012 (date code: 1205)

NOTE: Please be advised that during the transition period customers may receive pre and post change parts, due to existing inventory of the pre changed parts.

Markings to Distinguish Revised from Unrevised Devices:
Traceability code

Revision History:
September 22, 2011: Issued initial notification.
January 20, 2012: Issued final notification. Revised the estimated first ship date from 12/23/2011 to 1/27/2012.
Attached the qualification report.

Attachment(s): [PCN_CYER-16AOEB180_Affected_CPN.pdf](#)
[PCN_CYER-16AOEB180_Affected_CPN.xls](#)
[PCN_CYER-16AOEB180_Qual_Report.pdf](#)
[PCN_CYER-16AOEB180_Affected_CPN.pdf](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at <http://www.microchip.com/PCN> sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to [microchipDIRECT](#) and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."

Parts Affected

PIC16CE625
PIC16CE624
PIC16CE623
PIC16C56
PIC16C71
PIC16HV540
PIC16C54
PIC16F83
HCS512
PIC16F84
PIC16C54A
PIC16C620
PIC16C621
PIC16C622
PIC16C554
PIC16C558
PIC16C710
PIC16C711
PIC16C715
PIC16CR54C
MCP2510
PIC16CR58B
PIC16F627
PIC16F628
MCP2150
MCP2155
PIC16F84A
PIC16C54C
PIC16C620A
PIC16C622A
HS12-100D0/12DS2F
HS12-100D0/12DS15
MCP2140
PIC16C621A
PIC16C56A
PIC16C58B
PIC16C712
PIC16C716
PIC16C717
PIC16F819
PIC16F648A
PIC16F88
PIC16F87
PIC16F627A

PIC16F628A
MCP2140A
MCP23008
MCP23S08
PIC16F818
PIC18F1320
PIC18F1220
MCP2515
PIC16F54
PIC16F716
PIC18F1230
PIC18F1330
MCP23009
MCP23S09
dsPIC30F3012
dsPIC30F2011
PIC16F1827
PIC16F1826
PIC16F1847
dsPIC33FJ16GP101
PIC24HJ12GP201
dsPIC33FJ12GP201