

Change #604

- Qual. of 6700HA Mold Compound for 44L/64L TQFP Packages at MTHAI Assembly

Microchip Part#s Affected

DSPIC30F3011
DSPIC30F3014
DSPIC30F4011
DSPIC30F4013
DSPIC30F5011
DSPIC30F5015
PIC16C63A, PIC16FR63A, PIC16LC63A, PIC16LFR63A
PIC16C64A, PIC16LC64A
PIC16C65A, PIC16FR65A, PIC16LC65A
PIC16C65B, PIC16LC65B
PIC16C662, PIC16LC662
PIC16C67, PIC16FR67, PIC16LC67, PIC16LFR67
PIC16C74A, PIC16FR74A, PIC16LC74A, PIC16LFR74A
PIC16C74B, PIC16LC74B
PIC16C765
PIC16C77, PIC16FR77, PIC16LC77, PIC16LFR77
PIC16C774, PIC16LC774
PIC16C923, PIC16LC923
PIC16C924, PIC16LC924
PIC16C925, PIC16LC925
PIC16C926, PIC16LC926
PIC16CR65
PIC16CR66
PIC16CR67
PIC16CR76
PIC16CR77
PIC16F59
PIC16F74, PIC16LF74
PIC16F747, PIC16LF747
PIC16F77, PIC16LF77
PIC16F777, PIC16LF777
PIC16F871, PIC16LF871
PIC16F874, PIC16LF874
PIC16F874A, PIC16LF874A
PIC16F877, PIC16LF877
PIC16F877A, PIC16LF877A
PIC16F917
PIC16F946
PIC17C42A, PIC17FR42A, PIC17LC42A, PIC17LFR42A
PIC17C43, PIC17FR43, PIC17LC43, PIC17LFR43
PIC17C44, PIC17FR44, PIC17LC44, PIC17LFR44
PIC17C752, PIC17LC752
PIC17C756A, PIC17LC756A
PIC18C442, PIC18LC442
PIC18C452, PIC18LC452
PIC18C601, PIC18LC601
PIC18C658, PIC18LC658
PIC18F4220, PIC18LF4220
PIC18F4221, PIC18LF4221
PIC18F4320, PIC18LF4320
PIC18F4321, PIC18LF4321
PIC18F4331, PIC18LF4331
PIC18F4410, PIC18LF4410

PIC18F4415, PIC18LF4415
PIC18F442, PIC18F4439, PIC18LF442, PIC18LF4439
PIC18F4420, PIC18LF4420, PIC18LF4423
PIC18F4425, PIC18LF4425
PIC18F4431, PIC18LF4431
PIC18F4455, PIC18LF4455
PIC18F448, PIC18LF448
PIC18F4480, PIC18LF4480
PIC18F4481, PIC18LF4481
PIC18F4510, PIC18LF4510
PIC18F4515, PIC18LF4515
PIC18F452, PIC18F4539, PIC18LF452, PIC18LF4539
PIC18F4520, PIC18LF4520, PIC18LF4523
PIC18F4525, PIC18LF4525
PIC18F4550, PIC18LF4550
PIC18F458, PIC18LF458
PIC18F4580, PIC18LF4580
PIC18F4581, PIC18LF4581
PIC18F4585, PIC18LF4585
PIC18F4586, PIC18LF4586
PIC18F4610, PIC18LF4610
PIC18F4620, PIC18LF4620
PIC18F4680, PIC18LF4680
PIC18F4681, PIC18LF4681
PIC18F6310, PIC18LF6310
PIC18F6390, PIC18LF6390
PIC18F6410, PIC18LF6410
PIC18F6490, PIC18LF6490
PIC18F6520, PIC18LF6520
PIC18F6525, PIC18LF6525
PIC18F6527, PIC18LF6527
PIC18F6585, PIC18LF6585
PIC18F65J10
PIC18F65J15
PIC18F6620, PIC18LF6620
PIC18F6621, PIC18LF6621
PIC18F6622, PIC18LF6622
PIC18F6627, PIC18LF6627
PIC18F6680, PIC18LF6680
PIC18F66J10
PIC18F66J15
PIC18F6720, PIC18LF6720
PIC18F6722, PIC18LF6722
PIC18F67J10

Description of Change:
NEW MOLD COMPOUND

Impacts to Data Sheet:
NONE

Reason for Change:
IMPROVED MANUFACTURABILITY

Estimated Change Implementation Date(s):
DECEMBER, 2005

Markings to Distinguish Revised From Unrevised Devices: (e.g.: Date Code,
Device Marking, Ship Container Marking)
COO, DATE CODE

