

Change #634

- QUALIFICATION OF 8L TSSOP PACKAGE WITH HALOGEN-FREE MATERIALS AT UNISEM

Devices:

24AA00
24AA01
24AA014
24AA02
24AA024
24AA025
24AA04
24AA08
24AA128
24AA16
24AA256
24AA32A
24AA32AX
24AA52
24AA64
24C00
24C01C
24C02C
24C04B
24FC128
24FC256
24LC00
24LC014
24LC01B
24LC024
24LC025
24LC02B
24LC04B
24LC08B
24LC128
24LC16B
24LC256
24LC32A
24LC32AX
24LC64
24LCS52
24LCS52A
24LCS62
25AA010A
25AA010AX
25AA020A
25AA020AX
25AA040A
25AA040AX
25AA040X
25AA080A
25AA080B
25AA160A
25AA160B
25AA256
25AA256X

25C040X
25C080A
25C080B
25C160A
25C160B
25LC010A
25LC010AX
25LC020A
25LC020AX
25LC040A
25LC040AX
25LC040X
25LC080A
25LC080B
25LC160A
25LC160B
25LC256
25LC256X
25LCS52A
93AA46A
93AA46B
93AA46C
93AA56A
93AA56B
93AA56C
93AA66A
93AA66B
93AA66C
93AA76C
93AA86C
93C46A
93C46B
93C46C
93C56A
93C56B
93C56C
93C66A
93C66B
93C66C
93C76C
93C86C
93LC46A
93LC46B
93LC46C
93LC56A
93LC56B
93LC56C
93LC66A
93LC66B
93LC66C
93LC76C
93LC86C
HCS101
HCS201
HCS362
MCP3001
MCP3002
MCP3201
MCP3202

MCP3301
MCP601
MCP602
MCP6021
MCP6022
MCP6023
MCP603
MCP6041
MCP6042
MCP6043
MCP606
MCP607
MCP608
MCP9805
MCP98242
PIC12F508
PIC12F509
PS700
PS701
RFTXD0412

Description of Change:
PACKAGE QUALIFICATION HALOGEN-FREE MATERIALS

Impacts to Data Sheet:
NONE

Reason for Change:
INCREASED CAPACITY

Estimated Change Implementation Date(s):
MARCH, 2006

Markings to Distinguish Revised From Unrevised Devices: (e.g.: Date Code,
Device Marking, Ship Container Marking)
COO, TRACEABILITY CODE