





Product Change Notification - CYER-05FGVQ203

Date: 11 Apr 2012
Product Category: Analog (Thermal, Power Management & Safety)
Device Family:  
Notification subject: CCB 1147.02 Initial Notice: Qualification of 3L SOT-89 package with selective Ag plating on the lead-frame at LPI assembly site.
Notification text:

PCN Status:
Initial notification

Microchip Parts Affected:
See attachments of affected catalog part numbers (CPN) labeled as...
PCN_CYER-05FGVQ203_Affected_CPN.xls
PCN_CYER-05FGVQ203_Affected_CPN.pdf

Description of Change:
Qualification of 3L SOT-89 package with selective Ag plating on the lead-frame at LPI assembly site.

Pre Change:
Ag plating on entire lead-frame.

Post Change:
Ag plating on selected areas of lead-frame (die not in direct contact with Ag plating).

Impacts to Data Sheet:
None

Reason for Change:
To improve manufacturability

Change Implementation Status:
In Progress

Estimated First Ship Date:
June 30, 2012 (date code: 1226)

NOTE: Please be advised that during the transition period customers may receive pre and post change parts, due to existing inventory of the pre changed parts.

Markings to Distinguish Revised from Unrevised Devices:
Traceability code

Revision History:
April 11, 2012: Issued initial notification.

The change described in this PCN does not alter Microchip's current regulatory compliance regarding the material content of the applicable products.

Attachment(s):

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at <http://www.microchip.com/PCN> sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to [microchipDIRECT](#) and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."

Parts Affected

MCP111
MCP1700
MCP1702
MCP1703A
MCP1703
MCP1754S