

Product Change Notification - CYER-08NFNO242

Date: 20 Jun 2012**Product Category:** Memory**Device Family:** **Notification subject:** Silicon Die Revision Addition Final Notice: Addition of silicon die revision A0.**Notification text:**

PCN Status:
Final notification

Microchip Parts Affected:
See attachments of affected catalog part numbers (CPN) labeled as...
PCN_CYER-08NFNO242_Affected_CPN.xls
PCN_CYER-08NFNO242_Affected_CPN.pdf

Description of Change:
Addition of silicon die revision A0.

Pre change:
Line 4 of the package top marking: YYWWNNN-K or YYWWNNN-L

Post change:
Line 4 of the package top marking: YYWWNNN-K or YYWWNNN-L or YYWWNNN-A (addition of silicon die revision A0)

NOTE: YYWWNNN identifies the trace code where YY=year, WW=work week, and NNN=lot number.

Impacts to Data Sheet:
None

Reason for Change:
To improve cycle time and on time delivery performance

Change Implementation Status:
In Progress

Estimated First Ship Date:
August 1, 2012 (date code: 1231)

NOTE: Please be advised that after the estimated first ship date customers may receive pre and post change parts.

Markings to Distinguish Revised from Unrevised Devices:
Traceability code and top marking will include rev A.

Revision History:
June 20, 2012: Issued final notification.

The change described in this PCN does not alter Microchip's current regulatory compliance regarding the material content of the applicable products.

Attachment(s):

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at <http://www.microchip.com/PCN> sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to [microchipDIRECT](#) and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."

Parts Affected

SST39LF040

SST39VF040