




## Product Change Notification - CYER-07DQRU206

---

**Date:** 02 Jun 2011  
**Product Category:** 16-bit Microcontrollers and Digital Signal Controllers; 8-bit Microcontrollers; All 16-bit Microcontrollers; 32-bit PIC Microcontrollers  
**Device Family:**   
**Notification subject:** CCB 1029.05: Qualification of 64L QFN (9x9) packages with EFTEC-64T leadframe at NSEB (UTL)  
**Notification text:**

**PCN Status:**  
Final notification

**Microchip Parts Affected:**  
See attachments of affected catalog part numbers (CPN) labeled as...  
PCN\_CYER-07DQRU206\_Affected\_CPN.xls  
PCN\_CYER-07DQRU206\_Affected\_CPN.pdf

**Description of Change:**  
Qualification of 64L QFN (9x9) packages with EFTEC-64T leadframe at NSEB (UTL).

**Pre Change:**  
C194

**Post Change:**  
EFTEC-64T

**Impacts to Data Sheet:**  
None

**Reason for Change:**  
Improve manufacturability

**Change Implementation Status:**  
Not initiated

**Estimated First Ship Date:**  
June 30, 2011 (Date code 1127)

**NOTE:** Please be advised that during the transition period customers may receive pre and post change parts, due to existing inventory of the pre changed parts.

**Markings to Distinguish Revised from Unrevised Devices:**  
Traceability code

**Revision History:**  
February 22, 2011: Initial notice issued.  
June 2, 2011: Final notice issued and qualification report attached.

**Attachment(s):** [PCN\\_CYER-07DQRU206\\_Qual Report.pdf](#)  
[PCN\\_CYER-07DQRU206\\_Affected\\_CPN.pdf](#)  
[PCN\\_CYER-07DQRU206\\_Affected\\_CPN.xls](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

### Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at <http://www.microchip.com/PCN> sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to [microchipDIRECT](#) and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."

Parts Affected

dsPIC33FJ128GP206A  
dsPIC33FJ128GP306A  
dsPIC33FJ128GP706A  
dsPIC33FJ128MC506A  
dsPIC33FJ128MC706A  
dsPIC33FJ256GP506A  
dsPIC33FJ32GS406  
dsPIC33FJ32GS606  
dsPIC33FJ64GP206A  
dsPIC33FJ64GP306A  
dsPIC33FJ64GP706A  
dsPIC33FJ64GS406  
dsPIC33FJ64GS606  
dsPIC33FJ64MC506A  
dsPIC33FJ64MC706A  
PIC16F1946  
PIC16F1947  
PIC16F1526  
PIC16F1527  
PIC18F65K22  
PIC18F65K80  
PIC18F66K22  
PIC18F66K80  
PIC18F67K22  
PIC24FJ128DA106  
PIC24FJ128GA106  
PIC24FJ128GB106  
PIC24FJ128GB206  
PIC24FJ192GA106  
PIC24FJ192GB106  
PIC24FJ256DA106  
PIC24FJ256DA206  
PIC24FJ256GA106  
PIC24FJ256GB106  
PIC24FJ256GB206  
PIC24FJ64GA106  
PIC24FJ64GB106  
PIC24HJ128GP206A  
PIC24HJ128GP306A  
PIC24HJ128GP506A  
PIC24HJ256GP206A  
PIC24HJ64GP206A  
PIC24HJ64GP506A  
PIC32MX320F032H

PIC32MX320F064H  
PIC32MX320F128H  
PIC32MX340F128H  
PIC32MX340F256H  
PIC32MX340F512H  
PIC32MX420F032H  
PIC32MX440F128H  
PIC32MX440F256H  
PIC32MX440F512H  
PIC32MX534F064H  
PIC32MX564F064H  
PIC32MX564F128H  
PIC32MX575F256H  
PIC32MX575F512H  
PIC32MX664F064H  
PIC32MX664F128H  
PIC32MX675F256H  
PIC32MX675F512H  
PIC32MX695F512H  
PIC32MX764F128H  
PIC32MX775F256H  
PIC32MX775F512H  
PIC32MX795F512H