


**Product Change Notification - CYER-11SNTE468**

---

**Date:** 27 Jul 2011  
**Product Category:** Analog (Thermal, Power Management & Safety)  
**Device Family:**   
**Notification subject:** CCB 1070: Qualification of 3L SOT-89 with full Ag plating on the paddle at HANA assembly site.  
**Notification text:**

**PCN Status:**  
Initial notification

**Microchip Parts Affected:**  
See attachments of affected catalog part numbers (CPN) labeled as...  
PCN\_CYER-11SNTE468\_Affected\_CPN.xls  
PCN\_CYER-11SNTE468\_Affected\_CPN.pdf

**Description of Change:**  
Qualification of 3L SOT-89 with full Ag plating on the paddle at HANA assembly site.

**Pre Change:**  
Ag ring plating on paddle

**Post Change:**  
Full Ag plating on paddle

**Impacts to Data Sheet:**  
None

**Reason for Change:**  
To improve on time delivery performance

**Change Implementation Status:**  
In Progress

**Estimated First Ship Date:**  
September 30, 2011 (date code: 1140)

**NOTE:** Please be advised that during the transition period customers may receive pre and post change parts, due to existing inventory of the pre changed parts.

**Markings to Distinguish Revised from Unrevised Devices:**  
Traceability code

**Revision History:**  
July 14, 2011:  
Issued initial notification.

July 27, 2011:  
Revised initial notification to clarify that only the paddle will have Ag plating not the entire lead-frame.

**Attachment(s):** [PCN\\_CYER-11SNTE468\\_Affected\\_CPN.pdf](#)  
[PCN\\_CYER-11SNTE468\\_Affected\\_CPN.xls](#)  
[PCN\\_CYER-11SNTE468\\_Qual Plan.pdf](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

**Terms and Conditions:**

If you wish to change your product/process change notification (PCN) profile please log on to our website at <http://www.microchip.com/PCN> sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to [microchipDIRECT](#) and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."

Parts Affected

MCP111

MCP112

MCP1700

MCP1702

MCP1703