




PRODUCT

CHANGE NOTIFICATION



D6F MEMS Flow Sensor - Streamline Product Offering

In an effort to streamline our product offering, OMRON will discontinue **some** D6F models at the end of January 2025. There are no suggested replacements for the sensors. Other models within the D6F series are **not** affected. The following notice will explain the discontinuation; should you have any additional questions, however, please communicate with your local Omron Sales Professional.


LAST ORDER DATE (last time buy date)

End of January 2025

DISCONTINUED MODELS

MEMS Flow Sensor

- Model [D6F-01A1-110](#)
- Model [D6F-02A1-110](#)
- Model [D6F-05N2-000](#)
- Model [D6F-01N2-000](#)
- Model [D6F-02L2-000](#)



SUGGESTED REPLACEMENT

MEMS Flow Sensor

- No Suggested Replacement
- No Suggested Replacement
- No Suggested Replacement
- No Suggested Replacement
- No Suggested Replacement

***Note 1:** Please be advised, the D6F series of MEMS Flow Sensors is not being discontinued.*

***Note 2:** This notification applies only to the part numbers listed within this notification.*

***Note 3:** This notification does not affect or apply to the D6F-P series of MEMS Flow Sensors or the D6F-PH series of MEMS Differential Pressure Sensors.*

Thank you,
OMRON Product Management Team

SENSOR SERIES AFFECTED PARTS



Discontinued Product		Suggested Replacement	
Models		Models	Product code
D6F-01A1-110		No suggested replacement	
D6F-02A1-110		No suggested replacement	
D6F-05N2-000		No suggested replacement	
D6F-01N2-000		No suggested replacement	
D6F-02L2-000		No suggested replacement	

NOTE 1: Please be advised, the D6F series of MEMS Flow Sensors is not being discontinued.

NOTE 2: This notification applies only to the part numbers listed within this notification.

Reference: PCN# FS_046, Multiple D6F models- Discontinuation 20231205_DOP_00003