

Product discontinuation notification (PDN)

Title / short description Discontinuation of products and product versions
Affected article category Terminal blocks
Change category Discontinuation
Change number IBE190019-00
Reason for PCN/PDN Revision

Purpose/objective of the change

Discontinuation due to portfolio streamlining

Detailed description of the change

Discontinuation due to (partial) availability of alternative products

Identifying characteristics

See attached item list for discontinued items

Start of Production (SOP)	-	Last Time Delivery (LTD)	2025-01-31
Effective date (EOP)	2024-10-31	End of Service (EOSR)	-
End of Sales (EOS)	2024-10-31		

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|---|---|--|
| <input type="checkbox"/> Software / Firmware Bugfix | <input type="checkbox"/> Short-term delivery stop by supplier | <input type="checkbox"/> Short-term recall by supplier |
| <input type="checkbox"/> Force majeure | <input type="checkbox"/> Product improvement with customer benefits | |
| <input type="checkbox"/> Others | | |

Attachments

- Material_list.csv
- PDN-IBE190019-00_DE
- PDN-IBE190019-00_EN

Material list

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
3058018	AP-RSC-KS			3058017	AP RSC
2701574	GE 10/2-BA BU			3044173	UT 10-PE
5031003	ST-K 4 ASEA			3044542	UT 2,5-QUATTRO
2770066	TS-U3K 2,5			3044076	UT 2,5
3057144	UDK 3 RD			3044076	UT 2,5
3003174	UK 2,5 N/RS			3044089	UT 2,5 BU
3002018	UK 3			3047617	UT 4-FE
3002092	UK 3 BU			3044160	UT 10
3004456	UK 10-EX ALTER FUSS			1054163	UT 10 P/P
3005028	UK 10-PR			3044199	UT 16
3006179	UK 16 N-PE/N			1054163	UT 10 P/P
3059016	UK 16-PR			3044226	UT 35 BK
3048315	UK 35 BK			3044227	UT 35 RD
3048328	UK 35 RD			3047676	UT 35-FE
3048219	UK 35-FE			3047727	UT 35 IB
3008009	UK 35-IB			3047730	UT 35 IB BU
3048072	UK 35-IB BU			3047727	UT 35 IB
3048154	UK 35-IB-FE			3044128	UT 4-PE
3008054	UK 35-PE/N			3044212	UT 16-PE
5022290	SLK 4 O.SOCKEL U. FEDER			0523998	SLK 16-EX
5022261	SLK 16 OHNE SOCKEL U. FEDER			2017237	UHK 4-FS(8-2,8-0,8)
2780014	UXKK 4			2017224	UHK 4-FS/FS(12-2,8-0,8)
5022261	SLK 16 OHNE SOCKEL U. FEDER			3044173	UT 10-PE
0524997	SLK 35-EX			3044157	UT 6-PE
0270018	USK 4-FSR(4-2,8-0,8)			3003923	USLKG 10 N
0271017	USK 4-FS/FS(8-2,8-0,8)			3044212	UT 16-PE
0442011	USLKG 10			3044173	UT 10-PE
0442082	USLKG 10 N-1			3044241	UT 35-PE
0442024	USLKG 10-1			3044241	UT 35-PE
0443010	USLKG 16			3044128	UT 4-PE
0443036	USLKG 16 N-1			3044157	UT 6-PE
0448015	USLKG 16-1			3044814	UTT B 4
0443081	USLKG 2,5 N-1			3044814	UTT B 4
0444020	USLKG 35 BK				
0449014	USLKG 35-1				
0444035	USLKG 35-IB				
0441517	USLKG 5-1				
0444048	USLKG 6 N-1				

Item no.	Item Type	Hardware / Firmware		Item no.	Substitute item Type
		old	new		
2780014	UXKK 4				
0201605	ZS-6				

Produktabkündigungsmitteilung (PDN)

Titel / kurze Beschreibung	Discontinuation of products and product versions
Betroffene Artikelkategorie	Reihenklemmen
Änderungskategorie	Abkündigung
Änderungsnummer	IBE190019-00
Grund der PCN/PDN Revisionierung	

Zweck/Ziel der Änderung

Abkündigung aufgrund Portfoliobereinigung

Detailbeschreibung der Änderung

Abkündigung aufgrund (teilweise) vorhandener Alternativartikel

Identifizierende Merkmale

Abgekündigte Artikel siehe beigefügte Artikelliste

Beginn der Herstellung (SOP)	-	Letztmalige Lieferung (LTD)	2025-01-31
Inkrafttreten der Änderung (EOP)	2024-10-31	Einstellung von Service (EOSR)	-
Einstellung des Vertriebs (EOS)	2024-10-31		

Kurzfristige Änderung (< 6 Monate) oder Abkündigung (< 12 Monate), auf Grund von:

- | | | |
|---|--|--|
| <input type="checkbox"/> Software / Firmware Bugfix | <input type="checkbox"/> Kurzfristiger Lieferstopp durch den Lieferanten | <input type="checkbox"/> Kurzfristiger Rückruf durch den Lieferanten |
| <input type="checkbox"/> Höhere Gewalt | <input type="checkbox"/> Produktverbesserung mit Kundennutzen | |
| <input type="checkbox"/> Sonstiges | | |

Anlagen

- Material_list.csv
- PDN-IBE190019-00_DE
- PDN-IBE190019-00_EN

Materialliste

Art.-Nr.	Artikel Typ	Revision/Versionscharge		Art.-Nr.	Ersatzartikel Typ
		alt	neu		
3058018	AP-RSC-KS			3058017	AP RSC
2701574	GE 10/2-BA BU			3044173	UT 10-PE
5031003	ST-K 4 ASEA			3044542	UT 2,5-QUATTRO
2770066	TS-U3K 2,5			3044076	UT 2,5
3057144	UDK 3 RD			3044076	UT 2,5
3003174	UK 2,5 N/RS			3044089	UT 2,5 BU
3002018	UK 3			3047617	UT 4-FE
3002092	UK 3 BU			3044160	UT 10
3004456	UK 10-EX ALTER FUSS			1054163	UT 10 P/P
3005028	UK 10-PR			3044199	UT 16
3006179	UK 16 N-PE/N			1054163	UT 10 P/P
3059016	UK 16-PR			3044226	UT 35 BK
3048315	UK 35 BK			3044227	UT 35 RD
3048328	UK 35 RD			3047676	UT 35-FE
3048219	UK 35-FE			3047727	UT 35 IB
3008009	UK 35-IB			3047730	UT 35 IB BU
3048072	UK 35-IB BU			3047727	UT 35 IB
3048154	UK 35-IB-FE			3044128	UT 4-PE
3008054	UK 35-PE/N			3044212	UT 16-PE
5022290	SLK 4 O.SOCKEL U. FEDER			0523998	SLK 16-EX
5022261	SLK 16 OHNE SOCKEL U. FEDER			2017237	UHK 4-FS(8-2,8-0,8)
2780014	UXKK 4			2017224	UHK 4-FS/FS(12-2,8-0,8)
5022261	SLK 16 OHNE SOCKEL U. FEDER			3044173	UT 10-PE
0524997	SLK 35-EX			3044157	UT 6-PE
0270018	USK 4-FSR(4-2,8-0,8)			3003923	USLKG 10 N
0271017	USK 4-FS/FS(8-2,8-0,8)			3044212	UT 16-PE
0442011	USLKG 10			3044173	UT 10-PE
0442082	USLKG 10 N-1			3044241	UT 35-PE
0442024	USLKG 10-1			3044241	UT 35-PE
0443010	USLKG 16			3044128	UT 4-PE
0443036	USLKG 16 N-1			3044157	UT 6-PE
0448015	USLKG 16-1			3044814	UTT B 4
0443081	USLKG 2,5 N-1			3044814	UTT B 4
0444020	USLKG 35 BK				
0449014	USLKG 35-1				
0444035	USLKG 35-IB				
0441517	USLKG 5-1				
0444048	USLKG 6 N-1				

Art.-Nr.	Artikel Typ	Revision/Versionscharge		Art.-Nr.	Ersatzartikel Typ
		alt	neu		
2780014	UXKK 4				
0201605	ZS-6				

Item no.	Type	old	new	Substitute item	Replacement product designation	eCl@ss 13.0
3058018	AP-RSC-KS			3058017	AP RSC	
2701574	GE 10/2-BA BU			3044173	UT 10-PE	27141106
5031003	ST-K 4 ASEA			3044542	UT 2,5-QUATTRO	27141190
2770066	TS-U3K 2,5			3044076	UT 2,5	
3057144	UDK 3 RD			3044076	UT 2,5	27250101
3003174	UK 2,5 N/RS			3044089	UT 2,5 BU	
3002018	UK 3			3047617	UT 4-FE	27250101
3002092	UK 3 BU			3044160	UT 10	27250101
3004456	UK 10-EX ALTER FUSS			1054163	UT 10 P/P	27141190
3005028	UK 10-PR			3044199	UT 16	27250101
3006179	UK 16 N-PE/N			1054163	UT 10 P/P	27250103
3059016	UK 16-PR			3044226	UT 35 BK	27250101
3048315	UK 35 BK			3044227	UT 35 RD	27250101
3048328	UK 35 RD			3047676	UT 35-FE	27250101
3048219	UK 35-FE			3047727	UT 35 IB	27250101
3008009	UK 35-IB			3047730	UT 35 IB BU	27250101
3048072	UK 35-IB BU			3047727	UT 35 IB	27250101
3048154	UK 35-IB-FE			3044128	UT 4-PE	27250101
3008054	UK 35-PE/N			3044212	UT 16-PE	27250110
5022290	SLK 4 O.SOCKEL U. FEDER			0523998	SLK 16-EX	
5022261	SLK 16 OHNE SOCKEL U. FEDER			2017237	UHK 4-FS(8-2,8-0,8)	
2780014	UXKK 4			2017224	UHK 4-FS/FS(12-2,8-0,8)	27250102
5022261	SLK 16 OHNE SOCKEL U. FEDER			3044173	UT 10-PE	
0524997	SLK 35-EX			3044157	UT 6-PE	
0270018	USK 4-FSR(4-2,8-0,8)			3003923	USLKG 10 N	27250101
0271017	USK 4-FS/FS(8-2,8-0,8)			3044212	UT 16-PE	27250101
0442011	USLKG 10			3044173	UT 10-PE	27250103
0442082	USLKG 10 N-1			3044241	UT 35-PE	27250103
0442024	USLKG 10-1			3044241	UT 35-PE	27250103
0443010	USLKG 16			3044128	UT 4-PE	27250103
0443036	USLKG 16 N-1			3044157	UT 6-PE	27250103
0448015	USLKG 16-1			3044814	UTTB 4	27250103
0443081	USLKG 2,5 N-1			3044814	UTTB 4	27250103
0444020	USLKG 35 BK					27250103
0449014	USLKG 35-1					27250103
0444035	USLKG 35-IB					27250103
0441517	USLKG 5-1					27250103
0444048	USLKG 6 N-1					27250103
2780014	UXKK 4					27250102
0201605	ZS-6					27141190