

PRODUCT CHANGE NOTIFICATION

#PCN-DC-KLKJ-15

Business Unit	Product Line Code	Type of Change	Action	Date of issue
DC	AAB	Mechanical	Notify Distributors and Field	7/30/2015

The following Phoenix Contact products have been modified. Existing specifications will be met or exceeded. Please review and acknowledge this document and inform your personnel as needed.

Description of Change:

Upon tooling investigation it was found that we could minimize cost increases on this product line by utilizes a metal clamping sleeve used on our rail mounted terminal blocks. Because of this change there is a slight narrowing of the change at the bottom of the wire entry. See images below.

This change does not affect the wire gauge or any other technical data.

Warranty Information:

N/A

Stock Status

Can existing stock still be used? Y

Is mixture of stock acceptable? N

Transaction Dates:


Date modification goes into effect from Germany: 7/1/2015

Expected first shipment (from Phoenix Contact) of the modified product(s): 8/3/2015

Previous Product

New Product

PRODUCT CHANGE NOTIFICATION



Should you have any issues with the timeline or content of this change, please contact Phoenix Contact using the contact information below. Customers should acknowledge receipt of the PCN within 30 days of delivery of the PCN; provided, however that the failure to acknowledge receipt does not affect the product change or the effective date thereof.

Contact Info:

ANDREW BOGACZYK
(800)888-7388x3075
abogaczyk@phoenixcon.com

Thank you,



James Dunbar, Product Marketing Manager

Part#	Type Description
0707086	HDFK 4
0707866	HDFK 4 GNYE
0709026	HDFKV 4
0714011	HDFK 4/Z
3073306	UW 4
3073319	UW 4/S
3073380	UWV 4