



## Product change information

PCN no.	AAA160043	Date	22.06.2016
Article	PT 1.5/..-5.0-H + V		

### Description of the change

#### Optimization of the solder pin guide

In the course of our continuous product improvement, the solder pin guide of the PT 1.5-5.0 product series will be optimized. This adjustment applies to the horizontal as well as the vertical product versions. Further technical features remain unaffected by this change.

Previous production status	New production status
	

### General schedule of the old version

Last delivery until	
31.10.2016	

### General schedule of the new version

Expected first delivery of the changed products	
01.11.2016	

### Effects of the product change

#### Product fit

- Optimized solder pin guide
- Compatibility remains unaffected
- Old and new version can be applied in parallel

#### Product form

- Constriction of the solder pin guide

Kunde;	Name 1;	Name 2;	Name 3;	Name 4;	Straße;	PLZ;	Stadt;	Phoenix Contact Art.Nr.;	Phoenix Contact Art.Bez.;	Ihre Mate
49786					Inc.;;;Ganghoferstr. 34;	82216;	Maisach;	1935174		5/3/2005
49786					Inc.;;;Ganghoferstr. 34;	82216;	Maisach;	1935174		5/3/2005
49786					Inc.;;;Ganghoferstr. 34;	82216;	Maisach;	1935190		5/5/2005
49786					Inc.;;;Ganghoferstr. 34;	82216;	Maisach;	1935190		5/5/2005
49786					Inc.;;;Ganghoferstr. 34;	82216;	Maisach;	1935200		5/6/2005
49786					Inc.;;;Ganghoferstr. 34;	82216;	Maisach;	1935200		5/6/2005
49786					Inc.;;;Ganghoferstr. 34;	82216;	Maisach;	1935352		5/6/2005
49786					Inc.;;;Ganghoferstr. 34;	82216;	Maisach;	1935213		5/7/2005
49786					Inc.;;;Ganghoferstr. 34;	82216;	Maisach;	1935365		5/7/2005
49786					Inc.;;;Ganghoferstr. 34;	82216;	Maisach;	1935226		5/8/2005
49786					Inc.;;;Ganghoferstr. 34;	82216;	Maisach;	1935242		5/10/2005
49786					Inc.;;;Ganghoferstr. 34;	82216;	Maisach;	1935242		5/10/2005
49786					Inc.;;;Ganghoferstr. 34;	82216;	Maisach;	1935268		5/12/2005
49786					Inc.;;;Ganghoferstr. 34;	82216;	Maisach;	1935284		5/14/2005
49786					Inc.;;;Ganghoferstr. 34;	82216;	Maisach;	1935284		5/14/2005

rialnr.;Menge 2014 ST;Menge 2015 ST;Menge 2016 ST;AE 2016 ST  
0-H;;7.500 ST;;  
0-H;PHX1935174 ;;26.000 ST;16.000 ST;10.000 ST  
0-H;;6.200 ST;;  
0-H;PHX1935190 ;;2.800 ST;2.000 ST;2.000 ST  
0-H;;2.400 ST;;  
0-H;PHX1935200 ;;6.000 ST;600 ST;600 ST  
0-V;PHX1935352 ;;200 ST;;  
0-H;PHX1935213 ;;1.800 ST;2.000 ST;2.000 ST  
0-V;PHX1935365 ;;2.000 ST;2.000 ST;2.000 ST  
0-H;PHX1935226 ;;11.200 ST;3.000 ST;3.000 ST  
0-H;;7.000 ST;;  
0-H;PHX1935242 ;;16.000 ST;1.600 ST;1.600 ST  
0-H;PHX1935268 ;;10.000 ST;;  
0-H;;2.800 ST;;  
0-H;PHX1935284 ;;500 ST;2.000 ST;1.000 ST

Phoenix Contact Art.Nr.;Phoenix Contact Art.Bez.;Bemerkung

1935394	;	5/10/2005 0-V;
1935255	;	5/11/2005 0-H;
1989531	;	5/11/2005 0-H BK;
1935404	;	5/11/2005 0-V;
1935268	;	5/12/2005 0-H;
1989544	;	5/12/2005 0-H BK;
1935417	;	5/12/2005 0-V;
1935271	;	5/13/2005 0-H;
1989557	;	5/13/2005 0-H BK;
1935420	;	5/13/2005 0-V;
1935284	;	5/14/2005 0-H;
1989560	;	5/14/2005 0-H BK;
1935174	;	5/3/2005 0-H;
1991642	;	5/3/2005 0-H (1
1992544	;	5/3/2005 0-H BD:1-3;
1989450	;	5/3/2005 0-H BK;
1935323	;	5/3/2005 0-V;
1844497	;	5/3/2005 0-V RD;
1935190	;	5/5/2005 0-H;
1992573	;	5/5/2005 0-H BD:1-5;
1768156	;	5/5/2005 0-H BD:NO-5;
1990601	;	5/5/2005 0-H BDNZ:UHR
1991228	;	5/5/2005 0-H BDNZ:UHR
1989476	;	5/5/2005 0-H BK;
1712730	;	5/5/2005 0-H BK PA1
1712731	;	5/5/2005 0-H BK PA1
1701355	;	5/5/2005 0-H GY BDUHR
1730197	;	5/5/2005 0-H KMGY;
1746990	;	5/5/2005 0-H PA 1
1935349	;	5/5/2005 0-V;
1935200	;	5/6/2005 0-H;
1991354	;	5/6/2005 0-H (VPE500);
1704644	;	5/6/2005 0-H BD:1-6;

1989489	;	5/6/2005 0-H BK;
1737938	;	5/6/2005 0-H BK BD:1-6;
1737941	;	5/6/2005 0-H BK BD:7-12;
1989984	;	5/6/2005 0-H GY;
1935352	;	5/6/2005 0-V;
1935213	;	5/7/2005 0-H;
1706341	;	5/7/2005 0-H BD:1-7;
1992586	;	5/7/2005 0-H BD:4-10;
1989492	;	5/7/2005 0-H BK;
1730207	;	5/7/2005 0-H KMGY;
1935365	;	5/7/2005 0-V;
1935226	;	5/8/2005 0-H;
1988422	;	5/8/2005 0-H BD:8-1 SO;
1989502	;	5/8/2005 0-H BK;
1730210	;	5/8/2005 0-H KMGY;
1935378	;	5/8/2005 0-V;
1935239	;	5/9/2005 0-H;
1715015	;	5/9/2005 0-H BD:1-9;
1989515	;	5/9/2005 0-H BK;
1989971	;	5/9/2005 0-H GY;
1935381	;	5/9/2005 0-V;
1935242	;	5/10/2005 0-H;
1989528	;	5/10/2005 0-H BK;
1935433	;	5/14/2005 0-V;
1935297	;	5/15/2005 0-H;
1989573	;	5/15/2005 0-H BK;
1935446	;	5/15/2005 0-V;
1935307	;	5/16/2005 0-H;
1989586	;	5/16/2005 0-H BK;
1935459	;	5/16/2005 0-V;

3);

L;  
L1;

3 5;

5;  
CO SO;

3 5;