

Product change notification (PCN)

Title / short description	Second manufacturing location for FK-MCP 1,5/...-ST connectors
Affected article category	PCB terminal blocks and PCB connectors
Change category	Production location
Change number	PAA200052-00
Reason for PCN/PDN Revision	An additional manufacturing facility is being built in China to expand production capacity.

Purpose/objective of the change

Capacity expansion

Detailed description of the change

So far, the FK-MCP 1,5/...-ST connectors have been manufactured in Germany. To increase manufacturing capacity and rapidly reduce delivery times, parallel manufacturing will commence in China.

Identifying characteristics

Start of Production (SOP)	-	Last Time Delivery (LTD)	-
Effective date (EOP)	2021-11-01	End of Service (EOSR)	-
End of Sales (EOS)	-		

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|---|---|--|
| <input type="checkbox"/> Software / Firmware Bugfix | <input type="checkbox"/> Short-term delivery stop by supplier | <input type="checkbox"/> Short-term recall by supplier |
| <input type="checkbox"/> Force majeure | <input type="checkbox"/> Product improvement with customer benefits | |

Others

Reduction of delivery time due to an additional production site

Attachments

- Recommended Template for customer information_(external).docx
- Instruction for subsidiary_(internal).docx
- Material_list.csv
- PCN-PAA200052-00 Zweiter Fertigungsstandort für die FK-MCP 1,5/...-ST-Steckverbinder_DE
- PCN-PAA200052-00 Second manufacturing location for FK-MCP 1,5/...-ST connectors_EN

Material list

Item	Article Type	Hardware old	Firmware new	Item	Substitute item Type
1015782	FK-MCP 1,5/ 5-ST-3,81GY35BD1-5	0	0		
1025317	FK-MCP 1,5/13-STF-3,5 BD:1-13	0	0		
1146290	FK-MCP 1,5/ 3-STF-3,5BD+24 QMQ	0	0		
1700351	FK-MCP 1,5/12-ST-3,81BD24-13SO	0	0		
1700352	FK-MCP 1,5/12-ST-3,81 BD:1-12	0	0		
1700353	FK-MCP 1,5/12-ST-3,81 BD:13-24	0	0		
1701029	FK-MCP 1,5/ 3-ST-3,5 BD:1-3	0	0		
1701606	FK-MCP 1,5/ 3-STF-3,81 BD:1-3	0	0		
1701871	FK-MCP 1,5/ 8-STF-3,81 BD:1-8	0	0		
1701920	FK-MCP 1,5/16-STF-3,81 BD:1-16	0	0		
1701985	FK-MCP 1,5/ 6-STF-3,5 BD:1-6	0	0		
1702970	FK-MCP 1,5/ 9-STF-3,81 BD:1-9	0	0		
1702971	FK-MCP 1,5/12-STF-3,81 BD:1-12	0	0		
1709927	FK-MCP 1,5/18-STF-3,81 V002	0	0		
1709928	FK-MCP 1,5/18-STF-3,81 V001	0	0		
1851083	FK-MCP 1,5/ 6-ST-3,81	1	1		
1851119	FK-MCP 1,5/ 9-ST-3,81	1	1		
1851180	FK-MCP 1,5/16-ST-3,81	1	1		
1851164	FK-MCP 1,5/14-ST-3,81	1	1		
1851193	FK-MCP 1,5/17-ST-3,81	1	1		
1851203	FK-MCP 1,5/18-ST-3,81	1	1		
1851216	FK-MCP 1,5/19-ST-3,81	1	1		
1851229	FK-MCP 1,5/20-ST-3,81	1	1		
1967142	FK-MCP 1,5/10-ST-3,81 BK	1	1		
1800275	FK-MCP 1,5/ 5-ST-3,81 BK	1	1		
1712173	FK-MCP 1,5/ 4-ST-3,81 BU	1	1		
1800271	FK-MCP 1,5/ 3-ST-3,81 BK	1	1		
1800269	FK-MCP 1,5/ 2-ST-3,81 BK	1	1		
1800273	FK-MCP 1,5/ 4-ST-3,81 BK	1	1		
1800277	FK-MCP 1,5/ 6-ST-3,81 BK	1	1		
1800279	FK-MCP 1,5/ 7-ST-3,81 BK	1	1		
1800284	FK-MCP 1,5/ 9-ST-3,81 BK	1	1		
1800288	FK-MCP 1,5/12-ST-3,81 BK	1	1		
1800297	FK-MCP 1,5/16-ST-3,81 BK	0	0		
1851290	FK-MCP 1,5/ 8-STF-3,81	1	1		
1851339	FK-MCP 1,5/12-STF-3,81	1	1		
1851313	FK-MCP 1,5/10-STF-3,81	1	1		
1851326	FK-MCP 1,5/11-STF-3,81	1	1		

Item	Article Type	Hardware / Firmware		Item	Substitute item Type
		old	new		
1851371	FK-MCP 1,5/16-STF-3,81	1	1		
1851274	FK-MCP 1,5/ 6-STF-3,81	1	1		
1851407	FK-MCP 1,5/19-STF-3,81	1	1		
1851355	FK-MCP 1,5/14-STF-3,81	1	1		
1851245	FK-MCP 1,5/ 3-STF-3,81	1	1		
1851261	FK-MCP 1,5/ 5-STF-3,81	1	1		
1851258	FK-MCP 1,5/ 4-STF-3,81	1	1		
1851287	FK-MCP 1,5/ 7-STF-3,81	1	1		
1851410	FK-MCP 1,5/20-STF-3,81	1	1		
1851232	FK-MCP 1,5/ 2-STF-3,81	1	1		
1851300	FK-MCP 1,5/ 9-STF-3,81	1	1		
1851342	FK-MCP 1,5/13-STF-3,81	1	1		
1851368	FK-MCP 1,5/15-STF-3,81	1	1		
1800268	FK-MCP 1,5/ 2-ST-3,5 BK	0	0		
1800270	FK-MCP 1,5/ 3-ST-3,5 BK	0	0		
1800272	FK-MCP 1,5/ 4-ST-3,5 BK	0	0		
1800274	FK-MCP 1,5/ 5-ST-3,5 BK	0	0		
1724747	FK-MCP 1,5/ 8-ST-3,5 BD:1-8	0	0		
1724815	FK-MCP 1,5/ 4-ST-3,5 BD:1-4	0	0		
1800276	FK-MCP 1,5/ 6-ST-3,5 BK	0	0		
1800278	FK-MCP 1,5/ 7-ST-3,5 BK	0	0		
1800285	FK-MCP 1,5/10-ST-3,5 BK	0	0		
1734902	FK-MCP 1,5/ 4-STF-3,5 AUSO OMR	1	1		
1800286	FK-MCP 1,5/11-ST-3,5 BK	0	0		
1738351	FK-MCP 1,5/ 8-STF-3,5 AU	1	1		
1740970	FK-MCP 1,5/ 2-STF-3,5 SO OMR	0	0		
1771211	FK-MCP 1,5/ 4-ST-3,81 CN1	0	0		
1773604	FK-MCP 1,5/ 5-ST-3,5 GY7035	0	0		
1800280	FK-MCP 1,5/ 8-ST-3,5 BK	0	0		
1800281	FK-MCP 1,5/ 8-ST-3,81 BK	1	1		
1812746	FK-MCP 1,5/ 5-ST-3,5 BKBDWH-OV	0	0		
1828303	FK-MCP 1,5/18-ST-3,81CRWHLPSO2	0	0		
1831303	FK-MCP 1,5/ 3-STF-3,5 AU	0	0		
1832247	FK-MCP 1,5/15-STF-3,81 BD:1-15	0	0		
1851041	FK-MCP 1,5/ 2-ST-3,81	1	1		
1851054	FK-MCP 1,5/ 3-ST-3,81	1	1		
1851067	FK-MCP 1,5/ 4-ST-3,81	1	1		
1851070	FK-MCP 1,5/ 5-ST-3,81	1	1		
1851096	FK-MCP 1,5/ 7-ST-3,81	1	1		

Item	Article Type	Hardware / Firmware		Item	Substitute item Type
		old	new		
1851106	FK-MCP 1,5/ 8-ST-3,81	1	1		
1851122	FK-MCP 1,5/10-ST-3,81	1	1		
1851135	FK-MCP 1,5/11-ST-3,81	1	1		
1851148	FK-MCP 1,5/12-ST-3,81	1	1		
1851151	FK-MCP 1,5/13-ST-3,81	1	1		
1851177	FK-MCP 1,5/15-ST-3,81	1	1		
1851384	FK-MCP 1,5/17-STF-3,81	1	1		
1851397	FK-MCP 1,5/18-STF-3,81	1	1		
1875687	FK-MCP 1,5/10-STF-3,81 BD:1-10	1	1		
1892880	FK-MCP 1,5/ 6-STF-3,81 BD:1-6	1	1		
1898172	FK-MCP 1,5/ 6-STF-3,81 AU	2	2		
1898509	FK-MCP 1,5/ 4-STF-3,81 AU	2	2		
1898693	FK-MCP 1,5/ 6-ST-3,81 GY	1	1		
1940033	FK-MCP 1,5/15-ST-3,5	0	0		
1939934	FK-MCP 1,5/ 4-ST-3,5	0	0		
1938113	FK-MCP 1,5/ 3-ST-3,81 BD:1-3	1	1		
1939989	FK-MCP 1,5/10-ST-3,5	0	0		
1939921	FK-MCP 1,5/ 3-ST-3,5	0	0		
1940004	FK-MCP 1,5/12-ST-3,5	0	0		
1939947	FK-MCP 1,5/ 5-ST-3,5	0	0		
1939960	FK-MCP 1,5/ 7-ST-3,5	0	0		
1939950	FK-MCP 1,5/ 6-ST-3,5	0	0		
1939963	FK-MCP 1,5/ 8-ST-3,5	0	0		
1939992	FK-MCP 1,5/11-ST-3,5	0	0		
1939976	FK-MCP 1,5/ 9-ST-3,5	0	0		
1939918	FK-MCP 1,5/ 2-ST-3,5	0	0		
1940046	FK-MCP 1,5/16-ST-3,5	0	0		
1940017	FK-MCP 1,5/13-ST-3,5	0	0		
1940020	FK-MCP 1,5/14-ST-3,5	0	0		
1940237	FK-MCP 1,5/16-STF-3,5	0	0		
1940101	FK-MCP 1,5/ 3-STF-3,5	0	0		
1940059	FK-MCP 1,5/17-ST-3,5	0	0		
1940062	FK-MCP 1,5/18-ST-3,5	0	0		
1940075	FK-MCP 1,5/19-ST-3,5	0	0		
1940088	FK-MCP 1,5/20-ST-3,5	0	0		
1940198	FK-MCP 1,5/12-STF-3,5	0	0		
1940130	FK-MCP 1,5/ 6-STF-3,5	0	0		
1940143	FK-MCP 1,5/ 7-STF-3,5	0	0		
1940156	FK-MCP 1,5/ 8-STF-3,5	0	0		

Item	Article Type	Hardware / Firmware		Item	Substitute item Type
		old	new		
1940172	FK-MCP 1,5/10-STF-3,5	0	0		
1940224	FK-MCP 1,5/15-STF-3,5	0	0		
1940279	FK-MCP 1,5/20-STF-3,5	0	0		
1940211	FK-MCP 1,5/14-STF-3,5	0	0		
1940185	FK-MCP 1,5/11-STF-3,5	0	0		
1940253	FK-MCP 1,5/18-STF-3,5	0	0		
1940091	FK-MCP 1,5/ 2-STF-3,5	0	0		
1940266	FK-MCP 1,5/19-STF-3,5	0	0		
1940114	FK-MCP 1,5/ 4-STF-3,5	0	0		
1940127	FK-MCP 1,5/ 5-STF-3,5	0	0		
1940169	FK-MCP 1,5/ 9-STF-3,5	0	0		
1961928	FK-MCP 1,5/14-STF-3,81 BD:1-14	1	1		
1965759	FK-MCP 1,5/ 2-STF-3,81 BD:1-2	1	1		
1967281	FK-MCP 1,5/ 5-ST-3,5 BD:1-5	0	0		
1967728	FK-MCP 1,5/ 2-ST-3,5 BD:1-2Q	0	0		
1967731	FK-MCP 1,5/ 4-ST-3,5 BD:1-4Q	0	0		
1967744	FK-MCP 1,5/ 6-ST-3,5 BD:1-6Q	0	0		
1967757	FK-MCP 1,5/ 8-ST-3,5 BD:1-8Q	0	0		
1967760	FK-MCP 1,5/10-ST-3,5 BD:1-10Q	0	0		
1967773	FK-MCP 1,5/12-ST-3,5 BD:1-12Q	0	0		
1971824	FK-MCP 1,5/ 5-ST-3,5 BD:1-5Q	0	0		
1940208	FK-MCP 1,5/13-STF-3,5	0	0		
1940240	FK-MCP 1,5/17-STF-3,5	0	0		
1993103	FK-MCP 1,5/14-ST-3,5 BD:1-14 Q	0	0		
1994966	FK-MCP 1,5/ 4-STF-3,81 BD:1-4Q	2	2		
1995910	FK-MCP 1,5/ 2-STF-3,5 AU SO OMR	1	1		
1911648	FK-MCP 1,5/15-STF-3,81 BK	1	1		
1918308	FK-MCP 1,5/ 6-STF-3,81 BK	1	1		
1702247	FK-MCP 1,5/ 5-STF-3,81 BD:1-5	0	0		

Produktänderungsmitteilung (PCN)

Titel / kurze Beschreibung	Zweiter Fertigungsstandort für die FK-MCP 1,5/...-ST-Steckverbinder
Betroffene Artikelkategorie	Leiterplattenklemmen und -Steckverbinder
Änderungskategorie	Produktionsstandort
Änderungsnummer	PAA200052-00
Grund der PCN/PDN Revisionierung	Zur Erweiterung der Produktionskapazitäten wird in China eine zusätzliche Fertigung aufgebaut.

Zweck/Ziel der Änderung

Kapazitätserweiterung

Detailbeschreibung der Änderung

Bisher werden die FK-MCP 1,5/...-ST-Steckverbinder in Deutschland gefertigt. Zur Erhöhung der Fertigungskapazitäten und zur schnellen Reduzierung der Lieferzeiten wird in China eine Parallelfertigung gestartet

Identifizierende Merkmale

Beginn der Herstellung (SOP)	-	Letztmalige Lieferung (LTD)	-
Inkrafttreten der Änderung (EOP)	2021-11-01	Einstellung von Service (EOSR)	-
Einstellung des Vertriebs (EOS)	-		

Kurzfristige Änderung (< 6 Monate) oder Abkündigung (< 12 Monate), auf Grund von:

- | | | |
|---|--|--|
| <input type="checkbox"/> Software / Firmware Bugfix | <input type="checkbox"/> Kurzfristiger Lieferstopp durch den Lieferanten | <input type="checkbox"/> Kurzfristiger Rückruf durch den Lieferanten |
| <input type="checkbox"/> Höhere Gewalt | <input type="checkbox"/> Produktverbesserung mit Kundennutzen | |
| <input checked="" type="checkbox"/> Sonstiges | | |

Reduzierung der Lieferzeit durch einen zusätzlichen Produktionsstandort

Anlagen

- Recommended Template for customer information_(external).docx
- Instruction for subsidiary_(internal).docx
- Material_list.csv
- PCN-PAA200052-00 Zweiter Fertigungsstandort für die FK-MCP 1,5/...-ST-Steckverbinder_DE
- PCN-PAA200052-00 Second manufacturing location for FK-MCP 1,5/...-ST connectors_EN

Materialliste

Art.-Nr.	Artikel Typ	Revision/Versionscharge		Art.-Nr.	Ersatzartikel Typ
		alt	neu		
1015782	FK-MCP 1,5/ 5-ST-3,81GY35BD1-5	0	0		
1025317	FK-MCP 1,5/13-STF-3,5 BD:1-13	0	0		
1146290	FK-MCP 1,5/ 3-STF-3,5BD+24 QMQ	0	0		
1700351	FK-MCP 1,5/12-ST-3,81BD24-13SO	0	0		
1700352	FK-MCP 1,5/12-ST-3,81 BD:1-12	0	0		
1700353	FK-MCP 1,5/12-ST-3,81 BD:13-24	0	0		
1701029	FK-MCP 1,5/ 3-ST-3,5 BD:1-3	0	0		
1701606	FK-MCP 1,5/ 3-STF-3,81 BD:1-3	0	0		
1701871	FK-MCP 1,5/ 8-STF-3,81 BD:1-8	0	0		
1701920	FK-MCP 1,5/16-STF-3,81 BD:1-16	0	0		
1701985	FK-MCP 1,5/ 6-STF-3,5 BD:1-6	0	0		
1702970	FK-MCP 1,5/ 9-STF-3,81 BD:1-9	0	0		
1702971	FK-MCP 1,5/12-STF-3,81 BD:1-12	0	0		
1709927	FK-MCP 1,5/18-STF-3,81 V002	0	0		
1709928	FK-MCP 1,5/18-STF-3,81 V001	0	0		
1851083	FK-MCP 1,5/ 6-ST-3,81	1	1		
1851119	FK-MCP 1,5/ 9-ST-3,81	1	1		
1851180	FK-MCP 1,5/16-ST-3,81	1	1		
1851164	FK-MCP 1,5/14-ST-3,81	1	1		
1851193	FK-MCP 1,5/17-ST-3,81	1	1		
1851203	FK-MCP 1,5/18-ST-3,81	1	1		
1851216	FK-MCP 1,5/19-ST-3,81	1	1		
1851229	FK-MCP 1,5/20-ST-3,81	1	1		
1967142	FK-MCP 1,5/10-ST-3,81 BK	1	1		
1800275	FK-MCP 1,5/ 5-ST-3,81 BK	1	1		
1712173	FK-MCP 1,5/ 4-ST-3,81 BU	1	1		
1800271	FK-MCP 1,5/ 3-ST-3,81 BK	1	1		
1800269	FK-MCP 1,5/ 2-ST-3,81 BK	1	1		
1800273	FK-MCP 1,5/ 4-ST-3,81 BK	1	1		
1800277	FK-MCP 1,5/ 6-ST-3,81 BK	1	1		
1800279	FK-MCP 1,5/ 7-ST-3,81 BK	1	1		
1800284	FK-MCP 1,5/ 9-ST-3,81 BK	1	1		
1800288	FK-MCP 1,5/12-ST-3,81 BK	1	1		
1800297	FK-MCP 1,5/16-ST-3,81 BK	0	0		
1851290	FK-MCP 1,5/ 8-STF-3,81	1	1		
1851339	FK-MCP 1,5/12-STF-3,81	1	1		
1851313	FK-MCP 1,5/10-STF-3,81	1	1		
1851326	FK-MCP 1,5/11-STF-3,81	1	1		

Art.-Nr.	Artikel Typ	Revision/Versionscharge		Art.-Nr.	Ersatzartikel Typ
		alt	neu		
1851371	FK-MCP 1,5/16-STF-3,81	1	1		
1851274	FK-MCP 1,5/ 6-STF-3,81	1	1		
1851407	FK-MCP 1,5/19-STF-3,81	1	1		
1851355	FK-MCP 1,5/14-STF-3,81	1	1		
1851245	FK-MCP 1,5/ 3-STF-3,81	1	1		
1851261	FK-MCP 1,5/ 5-STF-3,81	1	1		
1851258	FK-MCP 1,5/ 4-STF-3,81	1	1		
1851287	FK-MCP 1,5/ 7-STF-3,81	1	1		
1851410	FK-MCP 1,5/20-STF-3,81	1	1		
1851232	FK-MCP 1,5/ 2-STF-3,81	1	1		
1851300	FK-MCP 1,5/ 9-STF-3,81	1	1		
1851342	FK-MCP 1,5/13-STF-3,81	1	1		
1851368	FK-MCP 1,5/15-STF-3,81	1	1		
1800268	FK-MCP 1,5/ 2-ST-3,5 BK	0	0		
1800270	FK-MCP 1,5/ 3-ST-3,5 BK	0	0		
1800272	FK-MCP 1,5/ 4-ST-3,5 BK	0	0		
1800274	FK-MCP 1,5/ 5-ST-3,5 BK	0	0		
1724747	FK-MCP 1,5/ 8-ST-3,5 BD:1-8	0	0		
1724815	FK-MCP 1,5/ 4-ST-3,5 BD:1-4	0	0		
1800276	FK-MCP 1,5/ 6-ST-3,5 BK	0	0		
1800278	FK-MCP 1,5/ 7-ST-3,5 BK	0	0		
1800285	FK-MCP 1,5/10-ST-3,5 BK	0	0		
1734902	FK-MCP 1,5/ 4-STF-3,5 AUSO OMR	1	1		
1800286	FK-MCP 1,5/11-ST-3,5 BK	0	0		
1738351	FK-MCP 1,5/ 8-STF-3,5 AU	1	1		
1740970	FK-MCP 1,5/ 2-STF-3,5 SO OMR	0	0		
1771211	FK-MCP 1,5/ 4-ST-3,81 CN1	0	0		
1773604	FK-MCP 1,5/ 5-ST-3,5 GY7035	0	0		
1800280	FK-MCP 1,5/ 8-ST-3,5 BK	0	0		
1800281	FK-MCP 1,5/ 8-ST-3,81 BK	1	1		
1812746	FK-MCP 1,5/ 5-ST-3,5 BKBDWH-OV	0	0		
1828303	FK-MCP 1,5/18-ST-3,81CRWHLPSO2	0	0		
1831303	FK-MCP 1,5/ 3-STF-3,5 AU	0	0		
1832247	FK-MCP 1,5/15-STF-3,81 BD:1-15	0	0		
1851041	FK-MCP 1,5/ 2-ST-3,81	1	1		
1851054	FK-MCP 1,5/ 3-ST-3,81	1	1		
1851067	FK-MCP 1,5/ 4-ST-3,81	1	1		
1851070	FK-MCP 1,5/ 5-ST-3,81	1	1		
1851096	FK-MCP 1,5/ 7-ST-3,81	1	1		

Art.-Nr.	Artikel Typ	Revision/Versionscharge		Art.-Nr.	Ersatzartikel Typ
		alt	neu		
1851106	FK-MCP 1,5/ 8-ST-3,81	1	1		
1851122	FK-MCP 1,5/10-ST-3,81	1	1		
1851135	FK-MCP 1,5/11-ST-3,81	1	1		
1851148	FK-MCP 1,5/12-ST-3,81	1	1		
1851151	FK-MCP 1,5/13-ST-3,81	1	1		
1851177	FK-MCP 1,5/15-ST-3,81	1	1		
1851384	FK-MCP 1,5/17-STF-3,81	1	1		
1851397	FK-MCP 1,5/18-STF-3,81	1	1		
1875687	FK-MCP 1,5/10-STF-3,81 BD:1-10	1	1		
1892880	FK-MCP 1,5/ 6-STF-3,81 BD:1-6	1	1		
1898172	FK-MCP 1,5/ 6-STF-3,81 AU	2	2		
1898509	FK-MCP 1,5/ 4-STF-3,81 AU	2	2		
1898693	FK-MCP 1,5/ 6-ST-3,81 GY	1	1		
1940033	FK-MCP 1,5/15-ST-3,5	0	0		
1939934	FK-MCP 1,5/ 4-ST-3,5	0	0		
1938113	FK-MCP 1,5/ 3-ST-3,81 BD:1-3	1	1		
1939989	FK-MCP 1,5/10-ST-3,5	0	0		
1939921	FK-MCP 1,5/ 3-ST-3,5	0	0		
1940004	FK-MCP 1,5/12-ST-3,5	0	0		
1939947	FK-MCP 1,5/ 5-ST-3,5	0	0		
1939960	FK-MCP 1,5/ 7-ST-3,5	0	0		
1939950	FK-MCP 1,5/ 6-ST-3,5	0	0		
1939963	FK-MCP 1,5/ 8-ST-3,5	0	0		
1939992	FK-MCP 1,5/11-ST-3,5	0	0		
1939976	FK-MCP 1,5/ 9-ST-3,5	0	0		
1939918	FK-MCP 1,5/ 2-ST-3,5	0	0		
1940046	FK-MCP 1,5/16-ST-3,5	0	0		
1940017	FK-MCP 1,5/13-ST-3,5	0	0		
1940020	FK-MCP 1,5/14-ST-3,5	0	0		
1940237	FK-MCP 1,5/16-STF-3,5	0	0		
1940101	FK-MCP 1,5/ 3-STF-3,5	0	0		
1940059	FK-MCP 1,5/17-ST-3,5	0	0		
1940062	FK-MCP 1,5/18-ST-3,5	0	0		
1940075	FK-MCP 1,5/19-ST-3,5	0	0		
1940088	FK-MCP 1,5/20-ST-3,5	0	0		
1940198	FK-MCP 1,5/12-STF-3,5	0	0		
1940130	FK-MCP 1,5/ 6-STF-3,5	0	0		
1940143	FK-MCP 1,5/ 7-STF-3,5	0	0		
1940156	FK-MCP 1,5/ 8-STF-3,5	0	0		

Art.-Nr.	Artikel Typ	Revision/Versionscharge		Art.-Nr.	Ersatzartikel Typ
		alt	neu		
1940172	FK-MCP 1,5/10-STF-3,5	0	0		
1940224	FK-MCP 1,5/15-STF-3,5	0	0		
1940279	FK-MCP 1,5/20-STF-3,5	0	0		
1940211	FK-MCP 1,5/14-STF-3,5	0	0		
1940185	FK-MCP 1,5/11-STF-3,5	0	0		
1940253	FK-MCP 1,5/18-STF-3,5	0	0		
1940091	FK-MCP 1,5/ 2-STF-3,5	0	0		
1940266	FK-MCP 1,5/19-STF-3,5	0	0		
1940114	FK-MCP 1,5/ 4-STF-3,5	0	0		
1940127	FK-MCP 1,5/ 5-STF-3,5	0	0		
1940169	FK-MCP 1,5/ 9-STF-3,5	0	0		
1961928	FK-MCP 1,5/14-STF-3,81 BD:1-14	1	1		
1965759	FK-MCP 1,5/ 2-STF-3,81 BD:1-2	1	1		
1967281	FK-MCP 1,5/ 5-ST-3,5 BD:1-5	0	0		
1967728	FK-MCP 1,5/ 2-ST-3,5 BD:1-2Q	0	0		
1967731	FK-MCP 1,5/ 4-ST-3,5 BD:1-4Q	0	0		
1967744	FK-MCP 1,5/ 6-ST-3,5 BD:1-6Q	0	0		
1967757	FK-MCP 1,5/ 8-ST-3,5 BD:1-8Q	0	0		
1967760	FK-MCP 1,5/10-ST-3,5 BD:1-10Q	0	0		
1967773	FK-MCP 1,5/12-ST-3,5 BD:1-12Q	0	0		
1971824	FK-MCP 1,5/ 5-ST-3,5 BD:1-5Q	0	0		
1940208	FK-MCP 1,5/13-STF-3,5	0	0		
1940240	FK-MCP 1,5/17-STF-3,5	0	0		
1993103	FK-MCP 1,5/14-ST-3,5 BD:1-14 Q	0	0		
1994966	FK-MCP 1,5/ 4-STF-3,81 BD:1-4Q	2	2		
1995910	FK-MCP 1,5/ 2-STF-3,5 AU SO OMR	1	1		
1911648	FK-MCP 1,5/15-STF-3,81 BK	1	1		
1918308	FK-MCP 1,5/ 6-STF-3,81 BK	1	1		
1702247	FK-MCP 1,5/ 5-STF-3,81 BD:1-5	0	0		

Item	Type	old	new	Substitute item	Replacement product designation	eCl@ss 11.0
1015782	FK-MCP 1,5/ 5-ST-3,81GY35BD1-5	0	0			27460202
1025317	FK-MCP 1,5/13-STF-3,5 BD:1-13	0	0			27460202
1146290	FK-MCP 1,5/ 3-STF-3,5BD+24 QMQ	0	0			27460202
1700351	FK-MCP 1,5/12-ST-3,81BD24-13SO	0	0			27460202
1700352	FK-MCP 1,5/12-ST-3,81 BD:1-12	0	0			27460202
1700353	FK-MCP 1,5/12-ST-3,81 BD:13-24	0	0			27460202
1701029	FK-MCP 1,5/ 3-ST-3,5 BD:1-3	0	0			27460202
1701606	FK-MCP 1,5/ 3-STF-3,81 BD:1-3	0	0			27460202
1701871	FK-MCP 1,5/ 8-STF-3,81 BD:1-8	0	0			27460202
1701920	FK-MCP 1,5/16-STF-3,81 BD:1-16	0	0			27460202
1701985	FK-MCP 1,5/ 6-STF-3,5 BD:1-6	0	0			27460202
1702970	FK-MCP 1,5/ 9-STF-3,81 BD:1-9	0	0			27460202
1702971	FK-MCP 1,5/12-STF-3,81 BD:1-12	0	0			27460202
1709927	FK-MCP 1,5/18-STF-3,81 V002	0	0			27460202
1709928	FK-MCP 1,5/18-STF-3,81 V001	0	0			27460202
1851083	FK-MCP 1,5/ 6-ST-3,81	1	1			27460202
1851119	FK-MCP 1,5/ 9-ST-3,81	1	1			27460202
1851180	FK-MCP 1,5/16-ST-3,81	1	1			27460202
1851164	FK-MCP 1,5/14-ST-3,81	1	1			27460202
1851193	FK-MCP 1,5/17-ST-3,81	1	1			27460202
1851203	FK-MCP 1,5/18-ST-3,81	1	1			27460202
1851216	FK-MCP 1,5/19-ST-3,81	1	1			27460202
1851229	FK-MCP 1,5/20-ST-3,81	1	1			27460202
1967142	FK-MCP 1,5/10-ST-3,81 BK	1	1			27460202
1800275	FK-MCP 1,5/ 5-ST-3,81 BK	1	1			27460202
1712173	FK-MCP 1,5/ 4-ST-3,81 BU	1	1			27460202
1800271	FK-MCP 1,5/ 3-ST-3,81 BK	1	1			27460202
1800269	FK-MCP 1,5/ 2-ST-3,81 BK	1	1			27460202
1800273	FK-MCP 1,5/ 4-ST-3,81 BK	1	1			27460202
1800277	FK-MCP 1,5/ 6-ST-3,81 BK	1	1			27460202
1800279	FK-MCP 1,5/ 7-ST-3,81 BK	1	1			27460202
1800284	FK-MCP 1,5/ 9-ST-3,81 BK	1	1			27460202
1800288	FK-MCP 1,5/12-ST-3,81 BK	1	1			27460202
1800297	FK-MCP 1,5/16-ST-3,81 BK	0	0			27460202
1851290	FK-MCP 1,5/ 8-STF-3,81	1	1			27460202
1851339	FK-MCP 1,5/12-STF-3,81	1	1			27460202
1851313	FK-MCP 1,5/10-STF-3,81	1	1			27460202
1851326	FK-MCP 1,5/11-STF-3,81	1	1			27460202
1851371	FK-MCP 1,5/16-STF-3,81	1	1			27460202
1851274	FK-MCP 1,5/ 6-STF-3,81	1	1			27460202
1851407	FK-MCP 1,5/19-STF-3,81	1	1			27460202
1851355	FK-MCP 1,5/14-STF-3,81	1	1			27460202
1851245	FK-MCP 1,5/ 3-STF-3,81	1	1			27460202
1851261	FK-MCP 1,5/ 5-STF-3,81	1	1			27460202
1851258	FK-MCP 1,5/ 4-STF-3,81	1	1			27460202
1851287	FK-MCP 1,5/ 7-STF-3,81	1	1			27460202
1851410	FK-MCP 1,5/20-STF-3,81	1	1			27460202
1851232	FK-MCP 1,5/ 2-STF-3,81	1	1			27460202
1851300	FK-MCP 1,5/ 9-STF-3,81	1	1			27460202
1851342	FK-MCP 1,5/13-STF-3,81	1	1			27460202
1851368	FK-MCP 1,5/15-STF-3,81	1	1			27460202
1800268	FK-MCP 1,5/ 2-ST-3,5 BK	0	0			27460202
1800270	FK-MCP 1,5/ 3-ST-3,5 BK	0	0			27460202
1800272	FK-MCP 1,5/ 4-ST-3,5 BK	0	0			27460202

1800274	FK-MCP 1,5/ 5-ST-3,5 BK	0	0		27460202
1724747	FK-MCP 1,5/ 8-ST-3,5 BD:1-8	0	0		27460202
1724815	FK-MCP 1,5/ 4-ST-3,5 BD:1-4	0	0		27460202
1800276	FK-MCP 1,5/ 6-ST-3,5 BK	0	0		27460202
1800278	FK-MCP 1,5/ 7-ST-3,5 BK	0	0		27460202
1800285	FK-MCP 1,5/10-ST-3,5 BK	0	0		27460202
1734902	FK-MCP 1,5/ 4-STF-3,5 AUSO OMR	1	1		27460202
1800286	FK-MCP 1,5/11-ST-3,5 BK	0	0		27460202
1738351	FK-MCP 1,5/ 8-STF-3,5 AU	1	1		27460202
1740970	FK-MCP 1,5/ 2-STF-3,5 SO OMR	0	0		27460202
1771211	FK-MCP 1,5/ 4-ST-3,81 CN1	0	0		27460202
1773604	FK-MCP 1,5/ 5-ST-3,5 GY7035	0	0		27460202
1800280	FK-MCP 1,5/ 8-ST-3,5 BK	0	0		27460202
1800281	FK-MCP 1,5/ 8-ST-3,81 BK	1	1		27460202
1812746	FK-MCP 1,5/ 5-ST-3,5 BKBDWH-OV	0	0		27460202
1828303	FK-MCP 1,5/18-ST-3,81CRWHLPSO2	0	0		27460202
1831303	FK-MCP 1,5/ 3-STF-3,5 AU	0	0		27460202
1832247	FK-MCP 1,5/15-STF-3,81 BD:1-15	0	0		27460202
1851041	FK-MCP 1,5/ 2-ST-3,81	1	1		27460202
1851054	FK-MCP 1,5/ 3-ST-3,81	1	1		27460202
1851067	FK-MCP 1,5/ 4-ST-3,81	1	1		27460202
1851070	FK-MCP 1,5/ 5-ST-3,81	1	1		27460202
1851096	FK-MCP 1,5/ 7-ST-3,81	1	1		27460202
1851106	FK-MCP 1,5/ 8-ST-3,81	1	1		27460202
1851122	FK-MCP 1,5/10-ST-3,81	1	1		27460202
1851135	FK-MCP 1,5/11-ST-3,81	1	1		27460202
1851148	FK-MCP 1,5/12-ST-3,81	1	1		27460202
1851151	FK-MCP 1,5/13-ST-3,81	1	1		27460202
1851177	FK-MCP 1,5/15-ST-3,81	1	1		27460202
1851384	FK-MCP 1,5/17-STF-3,81	1	1		27460202
1851397	FK-MCP 1,5/18-STF-3,81	1	1		27460202
1875687	FK-MCP 1,5/10-STF-3,81 BD:1-10	1	1		27460202
1892880	FK-MCP 1,5/ 6-STF-3,81 BD:1-6	1	1		27460202
1898172	FK-MCP 1,5/ 6-STF-3,81 AU	2	2		27460202
1898509	FK-MCP 1,5/ 4-STF-3,81 AU	2	2		27460202
1898693	FK-MCP 1,5/ 6-ST-3,81 GY	1	1		27460202
1940033	FK-MCP 1,5/15-ST-3,5	0	0		27460202
1939934	FK-MCP 1,5/ 4-ST-3,5	0	0		27460202
1938113	FK-MCP 1,5/ 3-ST-3,81 BD:1-3	1	1		27460202
1939989	FK-MCP 1,5/10-ST-3,5	0	0		27460202
1939921	FK-MCP 1,5/ 3-ST-3,5	0	0		27460202
1940004	FK-MCP 1,5/12-ST-3,5	0	0		27460202
1939947	FK-MCP 1,5/ 5-ST-3,5	0	0		27460202
1939960	FK-MCP 1,5/ 7-ST-3,5	0	0		27460202
1939950	FK-MCP 1,5/ 6-ST-3,5	0	0		27460202
1939963	FK-MCP 1,5/ 8-ST-3,5	0	0		27460202
1939992	FK-MCP 1,5/11-ST-3,5	0	0		27460202
1939976	FK-MCP 1,5/ 9-ST-3,5	0	0		27460202
1939918	FK-MCP 1,5/ 2-ST-3,5	0	0		27460202
1940046	FK-MCP 1,5/16-ST-3,5	0	0		27460202
1940017	FK-MCP 1,5/13-ST-3,5	0	0		27460202
1940020	FK-MCP 1,5/14-ST-3,5	0	0		27460202
1940237	FK-MCP 1,5/16-STF-3,5	0	0		27460202
1940101	FK-MCP 1,5/ 3-STF-3,5	0	0		27460202
1940059	FK-MCP 1,5/17-ST-3,5	0	0		27460202

1940062	FK-MCP 1,5/18-ST-3,5	0	0			27460202
1940075	FK-MCP 1,5/19-ST-3,5	0	0			27460202
1940088	FK-MCP 1,5/20-ST-3,5	0	0			27460202
1940198	FK-MCP 1,5/12-STF-3,5	0	0			27460202
1940130	FK-MCP 1,5/ 6-STF-3,5	0	0			27460202
1940143	FK-MCP 1,5/ 7-STF-3,5	0	0			27460202
1940156	FK-MCP 1,5/ 8-STF-3,5	0	0			27460202
1940172	FK-MCP 1,5/10-STF-3,5	0	0			27460202
1940224	FK-MCP 1,5/15-STF-3,5	0	0			27460202
1940279	FK-MCP 1,5/20-STF-3,5	0	0			27460202
1940211	FK-MCP 1,5/14-STF-3,5	0	0			27460202
1940185	FK-MCP 1,5/11-STF-3,5	0	0			27460202
1940253	FK-MCP 1,5/18-STF-3,5	0	0			27460202
1940091	FK-MCP 1,5/ 2-STF-3,5	0	0			27460202
1940266	FK-MCP 1,5/19-STF-3,5	0	0			27460202
1940114	FK-MCP 1,5/ 4-STF-3,5	0	0			27460202
1940127	FK-MCP 1,5/ 5-STF-3,5	0	0			27460202
1940169	FK-MCP 1,5/ 9-STF-3,5	0	0			27460202
1961928	FK-MCP 1,5/14-STF-3,81 BD:1-14	1	1			27460202
1965759	FK-MCP 1,5/ 2-STF-3,81 BD:1-2	1	1			27460202
1967281	FK-MCP 1,5/ 5-ST-3,5 BD:1-5	0	0			27460202
1967728	FK-MCP 1,5/ 2-ST-3,5 BD:1-2Q	0	0			27460202
1967731	FK-MCP 1,5/ 4-ST-3,5 BD:1-4Q	0	0			27460202
1967744	FK-MCP 1,5/ 6-ST-3,5 BD:1-6Q	0	0			27460202
1967757	FK-MCP 1,5/ 8-ST-3,5 BD:1-8Q	0	0			27460202
1967760	FK-MCP 1,5/10-ST-3,5 BD:1-10Q	0	0			27460202
1967773	FK-MCP 1,5/12-ST-3,5 BD:1-12Q	0	0			27460202
1971824	FK-MCP 1,5/ 5-ST-3,5 BD:1-5Q	0	0			27460202
1940208	FK-MCP 1,5/13-STF-3,5	0	0			27460202
1940240	FK-MCP 1,5/17-STF-3,5	0	0			27460202
1993103	FK-MCP 1,5/14-ST-3,5 BD:1-14 Q	0	0			27460202
1994966	FK-MCP 1,5/ 4-STF-3,81 BD:1-4Q	2	2			27460202
1995910	FK-MCP 1,5/ 2-STF-3,5 AU SO OMR	1	1			27460202
1911648	FK-MCP 1,5/15-STF-3,81 BK	1	1			27460202
1918308	FK-MCP 1,5/ 6-STF-3,81 BK	1	1			27460202
1702247	FK-MCP 1,5/ 5-STF-3,81 BD:1-5	0	0			27460202

Warning – Internal

**This is not a standard PCN and therefore
must not be distributed to customers
without a careful check**

Relocation / Change of Article Supplier

Dear colleagues,

Based on our global supply chain strategy we want to inform you that the place of production for the attached list of articles is planned to be changed.

Article List: Please refer to the attached Excel file
Date: *at least today + 6 months (to be individualized)*

All global Phoenix Contact production locations are working according to the same quality guidelines to ensure the same Phoenix Contact quality level worldwide.

Please be informed that due to the complexity of the process minor changes to the article list cannot be excluded at this point in time. We highlighted the articles currently planned for the relocation in attached list. We will inform you about changes during the relocation process by sharing an updated final list after the relocation is completed.

Please inform only customers about the relocation if forced by a contractual agreement.

For your external communication, please find a template attached and individualize it for your customers' needs. Please also check the full article list – with all possibly affected articles – carefully and align it with the customers' purchased articles. This procedure assures that we informed about all relocated articles upfront, even though changes to the list may occur.

The following relocation scenarios may occur and articles will be marked in the list accordingly:

- 1) Parallel Production: In addition to the former production location, we set up another production location and produce the same items at both sites simultaneously.
- 2) Full Relocation: The only sourcing location is relocated to a new place. During the time frame, that the production machinery is not operating, we internally create a forecast and corresponding safety stock based on historical data – only for in-stock articles. However, we cannot foresee any customer-specific volumes (e.g. project ramp-up, design-in activities, made-to-order articles).

- 2 -

In case you are facing this kind of additional demand, please consider a gap (average 2 months) of availability for the affected articles, that you can cover by additional upfront orders. Additional orders will not be needed for demand linked to in-stock articles, as this will be covered by the pre-produced safety stock.

If your customers require additional volumes until the machine has been installed at the new location, please place your orders within the next two weeks, after receiving this message.

For all questions related to the relocation itself (timeline, technical questions etc.) please contact the person in the relocation list, who is linked to the relocation in question.

For further commercial questions please contact your regional Commercial Sales Manager.

Example Address

Department
Name
Phone: +49 5235 3-xxx
Fax: +49 5235 3-xxx
eMail: xxx@phoenixcontact.com

10 March 2021

Warning

**This is not a standard PCN and therefore
must not be distributed to customers
without a careful check**
Please delete this warning after individualizing the letter

Relocation / Change of Article Supplier

Dear Customer (to be individualized),

Based on our global supply chain strategy we want to inform you that the place of production for the attached list of articles is planned to be changed.

Article List: Please refer to the attached Excel file
Date: at least today + 6 months (to be individualized)

All global Phoenix Contact production locations are working according to the same quality guidelines to ensure the same Phoenix Contact quality level worldwide.

With respect to the ordering process, there is no need for further action on your side. We will reorganize our sourcing routes internally.

Please be informed that due to the complexity of the process minor changes to the article list cannot be excluded at this point in time. We highlighted the articles currently planned for the relocation in attached list. We will inform you about changes during the relocation process by sharing an updated final list after the relocation is completed.

For further questions please contact [*please insert PxC contact person for the customer*].

Best Regards

xxx

PHOENIX CONTACT GmbH & Co. KG

Personally liable partner:
Phoenix Contact Verwaltungs GmbH
Amtsgericht Lemgo HRB 5273
Kom. Ges. Amtsgericht Lemgo HRA 3746Group Executive Board:
Frank Stührenberg (CEO)
Dirk Görliitzer, Torsten Janwlecke
Ulrich Leidecker
Frank Possel-Dölken, Axel WachholzDeutsche Bank AG
(BLZ 360 700 50) 226 2665 00
BIC: DEUTDE33XXX
IBAN:
DE93 3607 0050 0226 2665 00Commerzbank AG
(BLZ 476 400 51) 226 0396 00
BIC: COBADE33XXX
IBAN:
DE31 4764 0051 0226 0396 00