

Product change notification (PCN)

Title / short description	Parallel production of the FBS...-6 plug-in bridge in China
Affected article category	Installation and mounting material
Change category	Production location
Change number	PBE200089-00
Reason for PCN/PDN Revision	

Purpose/objective of the change

Capacity expansion to safeguard supply capability.

Detailed description of the change

Phoenix Contact operates a continuous improvement process throughout its product creation and manufacturing chain. To safeguard global supply capability, production of the above-listed items will be expanded.

This production expansion has absolutely no impact on the dimensions, technical data, color, approvals, functionality, or ordering data.

This change will affect our Asia-Pacific subsidiaries (China, Japan, Australia, South Korea, Singapore, New Zealand, Taiwan, Indonesia, Malaysia, and Thailand).

Identifying characteristics

All modified items can be identified by the incremented production batch and specified country of origin.

Start of Production (SOP)	2022-04-01	Last Time Delivery (LTD)	-
Effective date (EOP)	2022-04-01	End of Service (EOSR)	-
End of Sales (EOS)	-		

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|---|---|--|
| <input type="checkbox"/> Software / Firmware Bugfix | <input type="checkbox"/> Short-term delivery stop by supplier | <input type="checkbox"/> Short-term recall by supplier |
| <input type="checkbox"/> Force majeure | <input type="checkbox"/> Product improvement with customer benefits | |
| <input type="checkbox"/> Others | | |

Attachments

- Material_list.csv
- PCN-PBE200089-00 Parallelproduktion der Steckbrücke FBS...-6 in China_DE
- PCN-PBE200089-00 Parallel production of the FBS...-6 plug-in bridge in China_EN

Material list

Item	Article Type	Hardware old	Firmware new	Item	Substitute item Type
3030242	FBS 3-6	04	05		
3036945	FBS 3-6 BU	04	05		
3030255	FBS 4-6	04	05		
3036958	FBS 4-6 BU	04	05		
3030349	FBS 5-6	04	05		
3036961	FBS 5-6 BU	04	05		
3030271	FBS 10-6	04	05		
3032198	FBS 10-6 BU	04	05		

Produktänderungsmitteilung (PCN)

Titel / kurze Beschreibung Parallelproduktion der Steckbrücke FBS...-6 in China
Betroffene Artikelkategorie Installations- und Montagematerial
Änderungskategorie Produktionsstandort
Änderungsnummer PBE200089-00
Grund der PCN/PDN Revisionierung

Zweck/Ziel der Änderung

Kapazitätserweiterung zur Sicherstellung der Lieferfähigkeit.

Detailbeschreibung der Änderung

Phoenix Contact praktiziert in seiner gesamten Produktentstehungs- sowie Fertigungskette einen kontinuierlichen Verbesserungsprozess. Zur Sicherstellung der globalen Lieferfähigkeit wird für die oben genannten Artikel eine Produktionserweiterung durchgeführt. Die Produktionserweiterung hat keinerlei Auswirkungen auf Abmessungen, techn. Daten, Farbe, Approbationen, Funktionsweise oder Bestelldaten. Diese Änderung wird die Asien-Pazifik-Tochtergesellschaften (China, Japan, Australia, South Korea, Singapore, New Zealand, Taiwan, Indonesia, Malaysia und Thailand) betreffen.

Identifizierende Merkmale

Alle geänderten Artikel sind durch die erhöhte Versionscharge und Angabe des Ursprungslandes identifizierbar.

Beginn der Herstellung (SOP)	2022-04-01	Letztmalige Lieferung (LTD)	-
Inkrafttreten der Änderung (EOP)	2022-04-01	Einstellung von Service (EOSR)	-
Einstellung des Vertriebs (EOS)	-		

Kurzfristige Änderung (< 6 Monate) oder Abkündigung (< 12 Monate), auf Grund von:

- | | | |
|---|--|--|
| <input type="checkbox"/> Software / Firmware Bugfix | <input type="checkbox"/> Kurzfristiger Lieferstopp durch den Lieferanten | <input type="checkbox"/> Kurzfristiger Rückruf durch den Lieferanten |
| <input type="checkbox"/> Höhere Gewalt | <input type="checkbox"/> Produktverbesserung mit Kundennutzen | |
| <input type="checkbox"/> Sonstiges | | |

Anlagen

- Material_list.csv
- PCN-PBE200089-00 Parallelproduktion der Steckbrücke FBS...-6 in China_DE
- PCN-PBE200089-00 Parallel production of the FBS...-6 plug-in bridge in China_EN

Materialliste

Art.-Nr.	Artikel Typ	Revision/Versionscharge		Art.-Nr.	Ersatzartikel Typ
		alt	neu		
3030242	FBS 3-6	04	05		
3036945	FBS 3-6 BU	04	05		
3030255	FBS 4-6	04	05		
3036958	FBS 4-6 BU	04	05		
3030349	FBS 5-6	04	05		
3036961	FBS 5-6 BU	04	05		
3030271	FBS 10-6	04	05		
3032198	FBS 10-6 BU	04	05		

Item	Type	old	new	Substitute item	Replacement product designation	eCl@ss 11.0
3030242	FBS 3-6	04	05			27141140
3036945	FBS 3-6 BU	04	05			27141140
3030255	FBS 4-6	04	05			27141140
3036958	FBS 4-6 BU	04	05			27141140
3030349	FBS 5-6	04	05			27141140
3036961	FBS 5-6 BU	04	05			27141140
3030271	FBS 10-6	04	05			27141140
3032198	FBS 10-6 BU	04	05			27141140