

## PRODUCT CHANGE NOTIFICATION

PCN-DC-CMV4-14

Business Unit	Product Line Code	Type of Change	Action	Date of issue
DC	ABQ	Electrical	Notify Distributors and Field	2/21/2014

*The following Phoenix Contact products have been modified. Existing specifications will be met or exceeded. Please review and acknowledge this document and inform your personnel as needed.*

### Description of Change:

There has been a product change for the M12 products with wire. The change is in the basic material concerning the jacket of the wire, which will be improved with an additive. It is the same material, TPE, only the hydrolysis stability will be improved. The dimensions, structure, and the visual features will not be changed.

### Warranty Information:

N/A

### Stock Status

Can existing stock still be used? Y


Is mixture of stock acceptable? Y

### Transaction Dates:

Date modification goes into effect from Germany: 10/25/2013

Expected first shipment (from Phoenix Contact) of the modified product(s): 3/31/2014

## PRODUCT CHANGE NOTIFICATION



*Should you have any issues with the timeline or content of this change, please contact Phoenix Contact using the contact information below. Customers should acknowledge receipt of the PCN within 30 days of delivery of the PCN; provided, however that the failure to acknowledge receipt does not affect the product change or the effective date thereof.*

**Contact Info:**

CHUCK DAWSON  
Product Specialist  
(800)888-7388x3043  
cdawson@phoenixcon.com

Thank you,



---

Lyndsey Walling, Product Marketing Manager

## PRODUCT CHANGE NOTIFICATION

Part#	Type Description
1401846	SACC-E-M12FS-8CON-PG9/2,0
1419726	SACC-DSI-M12MS-17CON-M16/0,5
1551558	SACC-E-MSD-4CON-M16/0,5 SCO
1567704	SACC-E-M12FS-5CON-PG9/4,0
1565874	SACC-EC-FS-4CON-M16/1,0 SCO
1523502	SACC-EC-MS-8CON-M16/0,5 SCO
1543676	SACC-DSI-FSB-5CON-PG9/ 0,5 SCO
1419739	SACC-DSI-M12FS-17CON-M16/0,5
1430459	SACC-DSI-MS-12CON-PG9/0,5 SCO
1551888	SACC-DSI-MS-5CON-M12/0,5 SCO
1540019	SACC-E-M12FS-5CON-M16/2,5
1419687	SACC-DSI-M12MS-8CON-M16/0,5
1554720	SACC-DSI-M12FS-8CON-PG9/0,5 VA
1401030	SACC-E-FS-12CON-M16/1,0 SCO
1419713	SACC-DSI-M12FS-12CON-M16/0,5
1520000	SACC-E-FSB-5CON-M16/0,5 SCO
1419616	SACC-DSI-M12FSD-4CON-M16/0,5
1520068	SACC-EC-MS-5CON-M16/0,5 SCO
1523447	SACC-EC-FS-4CON-M16/0,5 SCO
1554694	SACC-DSI-M12MS-8CON-PG9/0,5 VA
1693775	SACC-EC-M12MS-4CON-PG9/0,5
1523492	SACC-E-MS-8CON-M16/0,5 SCO
1556618	SACC-DSI-MS-4CON-PG9/0,5 SCO
1556265	SACC-E-MS-12CON-M16/0,5 SCO
1554717	SACC-DSI-M12FS-5CON-PG9/0,5 VA
1430446	SACC-DSI-FS-12CON-PG9/0,5 SCO
1554681	SACC-DSI-M12MS-5CON-PG9/0,5 VA
1419700	SACC-DSI-M12MS-12CON-M16/0,5
1671108	SACC-EC-M12FS-5CON-PG9/0,5
1542716	SACC-DSI-MS-8CON-PG 9/0,5 SCO
1402137	SACC-DSI-MS-5P-M12/0,6 PVCS0,5
1513774	SACC-E-M12MS-8CON-PG9/0,5
1520039	SACC-E-FS-5CON-M16/0,5 SCO
1440973	SACC-SQ-M12MS-5CON-25F/0,5
1519998	SACC-EC-FSB-5CON-M16/0,5 SCO
1556252	SACC-E-FS-12CON-M16/0,5 SCO
1520026	SACC-EC-MSB-5CON-M16/0,5 SCO
1401110	SACC-E-FS-5CON-M16/1,0 SCO
1520042	SACC-EC-FS-5CON-M16/0,5 SCO
1419690	SACC-DSI-M12FS-8CON-M16/0,5
1441561	SACC-SQ-M12MS-8CON-25F/0,5
1671111	SACC-E-M12MS-5CON-PG9/0,5
1419658	SACC-DSI-M12FS-5CON-M16/0,5
1671124	SACC-EC-M12MS-5CON-PG9/0,5
1693791	SACC-EC-M12FS-4CON-PG9/0,5
1520055	SACC-E-MS-5CON-M16/0,5 SCO
1523476	SACC-E-FS-8CON-M16/0,5 SCO

## PRODUCT CHANGE NOTIFICATION

Part#	Type Description
1693788	SACC-E-M12FS-4CON-PG9/0,5
1551875	SACC-DSI-MS-4CON-M12/0,5 SCO
1556621	SACC-DSI-FS-4CON-PG9/0,5 SCO
1513758	SACC-E-M12FS-8CON-PG9/0,5
1671098	SACC-E-M12FS-5CON-PG9/0,5
1542703	SACC-DSI-MS-5CON-PG 9/0,5 SCO
1554568	SACC-E-M12MS-5CON-PG 9/0,5 VA
1405331	SACC-DSI-FS-5CON-PG9/0,5 SCORD
1542732	SACC-DSI-FS-8CON-PG 9/0,5 SCO
1542729	SACC-DSI-FS-5CON-PG 9/0,5 SCO
1551529	SACC-DSI-FSD-4CON-PG9/0,5 SCO
1551914	SACC-DSI-MS-8CON-M12/0,5 SCO
1523434	SACC-E-FS-4CON-M16/0,5 SCO
1535202	SACC-E-FSD-4CON-M16/0,5 SCO
1693762	SACC-E-M12MS-4CON-PG9/0,5
1523450	SACC-E-MS-4CON-M16/0,5 SCO
1401052	SACC-E-MS-4CON-M16/0,5 SCO PO