

Product Change Notification

PCN Date:	April 12, 2021				
Supplier Name:	Pulse Electronics				
Pulse PCN No.	PCN-100000280 Rev. A				
Description of Change	Add the alternative manufacturing location BH (factory code B1) in Sichuan Province. This location is also an ISO9001 certified factory. No impact to product form, fit and function. Product process and BOM remain the same.				
Reason for Change	 Extend the manufacturing capacity to support customers. Business contingency requirement 				
Traceability guidelines	1.For the part with remark "The back-end process already moved to Pulse own factory (UPO)", Pulse already issued PCN for move back-end process including pin correction, testing, marking, co-planarity inspection and packaging from contract manufacturer into Pulse own factory (UPO). The parts are ship from UPO with -C suffix of date code, for example 2115-C. 2.For the part without remark, they are ship from BH with -B1 suffix of date code, for example 2115-B1.				
Qualification Data attached? File name(s)	1000hour reliability test is pass. Refer to below report. H5008NL Qualificatio n Test Report 1000hrs				
Customer Part	Pulse Part	PCN Effectively	Remark		
Number	Number H1102NL	Date	The back-end process already moved to		
	Number	Date July 12,2021	The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to		
	Number H1102NL	Date	The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to		
	Number H1102NL H1102NLT	Date July 12,2021 July 12,2021	The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to		
	Number H1102NL H1102NLT H2019FNL	Date July 12,2021 July 12,2021 July 12,2021	The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO).		
	Number H1102NL H1102NLT H2019FNL H2019FNLT	July 12,2021 July 12,2021 July 12,2021 July 12,2021	The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to		
	Number H1102NL H1102NLT H2019FNL H2019FNLT HX1188FNL	July 12,2021 July 12,2021 July 12,2021 July 12,2021 July 12,2021	The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO).		
	Number H1102NL H1102NLT H2019FNL H2019FNLT HX1188FNL HX1188FNLT	July 12,2021	The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO).		
	Number H1102NL H1102NLT H2019FNL H2019FNLT HX1188FNL HX1188FNLT HX5008FNL	July 12,2021	The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO).		
	Number H1102NL H1102NLT H2019FNL H2019FNLT HX1188FNL HX1188FNLT HX5008FNL HX5008FNLT	July 12,2021	The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO).		
	Number H1102NL H1102NLT H2019FNL H2019FNLT HX1188FNL HX1188FNLT HX5008FNL HX5008FNL HX5008NL	July 12,2021	The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO).		
	Number H1102NL H1102NLT H2019FNL H2019FNLT HX1188FNL HX1188FNLT HX5008FNL HX5008FNLT HX5008NLT HX5008NLT	July 12,2021	The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO).		
	Number H1102NL H1102NLT H2019FNL H2019FNLT HX1188FNL HX1188FNLT HX5008FNL HX5008FNLT HX5008NLT HX5008NLT HX5008NLT	July 12,2021	The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO).		
	Number H1102NL H1102NLT H2019FNL H2019FNLT HX1188FNL HX1188FNLT HX5008FNL HX5008FNLT HX5008NL HX5008NLT HX5020NL HX5020NLT	July 12,2021 July 12,2021	The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO). The back-end process already moved to Pulse own factory (UPO).		

1	H1190FNLT	July 12,2021	/
/	H1259NL	July 12,2021 July 12,2021	/
1	H1259NLT	July 12,2021 July 12,2021	/
/	H1270FNL	July 12,2021 July 12,2021	/
/	H1270FNLT	July 12,2021	/
/	H5004ENL	July 12,2021 July 12,2021	/
/	H5004ENLT	July 12,2021	/
1	H5008NL	July 12,2021 July 12,2021	/
1	H5008NLT	July 12,2021 July 12,2021	/
1	H5014NL	July 12,2021	/
1	H5014NLT	July 12,2021 July 12,2021	/
1	H5020NL	July 12,2021	/
1	H5020NLT	July 12,2021	/
/	H5120NL	July 12,2021	/
1	H5120NLT	July 12,2021 July 12,2021	/
/	H6062NL	July 12,2021	/
1	H6062NLT	July 12,2021 July 12,2021	/
/	H6080NL	July 12,2021	/
1	H6080NLT	July 12,2021 July 12,2021	/
1	H6101NL	July 12,2021	,
1	H6101NLT	July 12,2021	/
1	HC1001NL	July 12,2021	/
1	HC1001NLT	July 12,2021 July 12,2021	,
/	HC1002NL	July 12,2021 July 12,2021	/
1	HC1002NLT	July 12,2021	,
1	HC5001ANL	July 12,2021	/
1	HC5001ANLT	July 12,2021	,
1	HC5001NL	July 12,2021	/
/	HC5001NLT	July 12,2021	/
1	HC5002NL	July 12,2021	/
1	HC5002NLT	July 12,2021 July 12,2021	/
1	HC5003NL	July 12,2021 July 12,2021	/
/	HC5003NLT	July 12,2021	/
1	HC5005ANL	July 12,2021	/
1	HC5005ANLT	July 12,2021 July 12,2021	/
/	HX1224CNL	July 12,2021	/
1	HX1224CNLT	July 12,2021	/
1	HX1259FNL	July 12,2021	/
1	HX1259FNLT	July 12,2021	/
/	HX1259NL	July 12,2021	/
1	HX1259NLT	July 12,2021	/
1	HX5004ENL	July 12,2021 July 12,2021	/
/	HX5004ENLT	July 12,2021	/
/	HX5181NL	July 12,2021 July 12,2021	/
1	HX5181NLT	July 12,2021	/
1	HX6080NL	July 12,2021	,
1	HX6080NLT	July 12,2021	,
1	HXC1001NL	July 12,2021	,
1	HXC1001NLT	July 12,2021	,
1	T1108QNL	July 12,2021	,
,	11100 X14E	July 12,2021	ı

1	T1108QNLT	July 12,2021	/
1	T8008QNL	July 12,2021	/
1	T8008QNLT	July 12,2021	/
/	TX1267QNL	July 12,2021	/
1	TX1267QNLT	July 12,2021	/
/	TX1502QNL	July 12,2021	/
1	TX1502QNLT	July 12,2021	/
1	TX1544NL	July 12,2021	/
1	TX1544NLT	July 12,2021	/

Customer: Generic Originator: Levene Xu