




Product Change Notification

| | | | | |
|--|--|-----------------------------|--------------------------------------|---------------------------|
| PCN Date: | April 25 th , 2012 | | | |
| Supplier Name: | Pulse | | | |
| Pulse PCN No. | 12-011 – Revision A | | | |
| Description of Change | <p>Update of Pulse manufacturing strategy – Add alternate location for open frame discrete products family.</p> <p>Below listed products are selected as first discrete assemblies to be assembled, tested and shipped from new manufacturing location. New manufacturing location is ISO registered and uses same vendors, same raw material, same manufacturing processes as Pulse operations.</p> | | | |
| Reason for Change | <p>To create manufacturing flexibility that will allow Pulse to better manage upsides in market demands.</p> <p>Since 2011, sub-contractor CLY has built and shipped thousands of molded magnetic modules for Pulse connector customers with excellent quality performances and DPPM results.</p> | | | |
| Summary of Changes between the new and old part | Present | | Present | |
| | Pulse MPO1, Suining, Sichuan province China | | CLY, Ji'An, JianXi province China | |
| Traceability guidelines | <p>Product marking, CLY is identified by the letters “CLY”</p> <p>Example: 1225-CLY</p> | | | |
| Qualification Data attached? File name(s) | Completed on product family basis – Available upon request | | | |
| Customer Part Number | Pulse Part Number | PCN Effectivity Date | Sample Availability | Qualification Data |
| |  Pulse_NetworkOp Header_Phase1_0 | 07/25/2012 | Two weeks from request | Available upon request |
| | | 07/25/2012 | Two weeks from request | |

Customer: GENERIC / DISTRIBUTOR

Originator: Manu Debrand

Phone: 858-674-8043

E-mail: <mailto:mdebrand@pulseelectronics.com>

| Part Number |
|--------------------|
| HX2019NL |
| E2023NLT |
| H2019NL |
| H2019NLT |
| H5084NL |
| H5084NLT |
| HX2019NLT |
| HX6096NLT |
| 23Z104SMNL |
| E2023NL |
| E2467NLT |
| H1121NL |
| HX6015NL |
| HX6015NLT |
| H2053ANL |
| 23Z104SMNLT |
| E2457NL |
| E2457NLT |
| E2467NL |
| H1259NL |
| H1302NLT |
| H5015NLT |
| HX1294NL |
| HX1294NLT |
| H2019NLS |
| H5135NLT |
| H2053ANLT |
| H6096NL |
| H6096NLT |
| E2458NL |
| E2458NLT |
| E2466NL |
| E2466NLS |
| E2466NLT |
| H1121NLT |
| H1302NL |
| H2055NL |
| H5077NL |
| H5077NLT |
| H5149NL |
| HX1198NLS |
| HX1393NL |
| HX1393NLT |
| HX2326NL |
| HX6015NLS |
| HX6050NLT |

| |
|-------------|
| ST4202TNL |
| TX1516QNL |
| TX3025QNL |
| TX3025QNLST |
| H2019BNL |
| H2019BNLT |
| H2019NLST |
| H5007ENL |
| H5007ENLT |
| H5135NL |
| HX6096NL |
| E2081NL |
| E2081NLT |
| E2466NLST |
| EX2024NL |
| EX2024NLT |
| H1100NL |
| H1100NLT |
| H1121NLS |
| H1121NLST |
| H1300NL |
| H1300NLT |
| H2055NLT |
| H2260NL |
| H2260NLT |
| H5007CNL |
| H5007CNLT |
| H5009NL |
| H5009NLT |
| H5015NL |
| H5067NL |
| H5067NLT |
| H5149ANL |
| H5149ANLT |
| H5149NLT |
| H6034NL |
| H6034NLT |
| H6502NL |
| H6502NLT |
| H6503NL |
| H6503NLT |
| HX1198NLST |
| HX2260NL |
| HX2260NLT |
| HX2326NLT |
| HX5062NL |
| HX5062NLT |

| |
|----------|
| HX6050NL |
|----------|

| |
|-----------|
| TX1516QNL |
|-----------|