Rear Cover



The protective covers may not be worked with hot air E.g. KEA with rear cover



E.g. Rear cover for GSF1



Description

- 1 Function
- Insulation cover rear-side
- Material: PVC black, UL 94V-0

References

Mating cover to

Weblinks

pdf datasheet, html-datasheet, General Product Information, Approvals, CE declaration of conformity, RoHS, CHINA-RoHS, REACH, Distributor-Stock-Check, Accessories, Detailed request for product

The terminals of the Schurter appliance couplers can be protected against unintentional contact by the use of an insulation cover on the rear side. They are made of black PVC and can be easily mounted from the rear to the corresponding appliance couplers.

All Variants

| Suitable for | Order Number |
|---|--------------|
| GSF1 | 0098.0078 |
| C20F, C22F, DC11, DC12, KEA, KEB1, 1092, 4707, 4721, 4723, 4793, 4798, 5130, 5200, 5220, 5707, 6200, 6202, 6205, 6220, 6600-3, 6600-4, 6600-5, 6600-9, 6602-4 | 0859.0047 |
| FGS, KFS, KFX, 5003, 5110, 5120, 5123, 6067, 6100-3, 6100-4, 6100-9, 6102-3, 6102-5, 6102-9 | 0859.0048 |
| DC12, KEC, KFA, KFB1, KFC | 0859.0072 |
| FKG, FKH, FKHD, FKI, FKID, KD, 5145, 6135, 6145, 6762, 6765 | 0859.0074 |
| KEB2, KFB2, 0723, 4719, 4797, 4797-5 | 0859.0075 |
| DD12, EC11, KE, KM, KMF | 0859.0076 |
| CD | 0859.0077 |
| 8843.FL, 8843.FLR | 0859.0086 |
| CE, EC12, KE | 0859.0108 |
| CG, DF11, DF12, EF11, EF12, KG | 0859.0109 |
| 1061, 6010, 6015, 6061, 6062, 6063, 6065, 6066, 6067, 6100-3, 6100-4, 6102-3, 6102-5, 6110-3, 6110-4, 6120-3, 6120-5 | 4311.9401 |
| 1061, 6010, 6015, 6061, 6062, 6063, 6065, 6066, 6067, 6100-3, 6100-4, 6102-3, 6102-5, 6110-3, 6110-4, 6120-3, 6120-5 | 4311.9402 |
| DC11, KEA, KEB1, 1060, 1062, 1064, 1065, 1066, 1074, 1092, 4707, 6200, 6202, 6205, 6220 | 4311.9403 |

Most Popular.

Availability for all products can be searched real-time:http://www.schurter.com/en/Stock-Check/Stock-Check-SCHURTER

100 Pcs Packaging unit