

**1 Products affected**

| Product hierarchy no. * |     |     |            | Part no.       | SBU            | Type / Description | Customer part no. |
|-------------------------|-----|-----|------------|----------------|----------------|--------------------|-------------------|
| SBU                     | PG  | PUG | Type       |                |                |                    |                   |
| 02                      | 007 | 037 | 0000002235 | See list below | Cord connector | 4735               |                   |
| 02                      | 007 | 037 | 0000002236 | See list below | Cord connector | 4736               |                   |

\*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

| List of part numbers affected |           |  |  |
|-------------------------------|-----------|--|--|
| 4735.0000                     | 4736.0000 |  |  |

**2 Type of change**

- Modified label

**3 Detailed description of change**

Old cULus listed no. 31T1, new cULus listed no. 7B90

| Old label                                                                                             | New label                                                                                              |
|-------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------|
| <p>Label for P/N 4735.0000, QTY 100, Lot 1, Date 1943. The cULus certification is marked as 31T1.</p> | <p>Label for P/N 4735.0000, QTY 100, Lot 1, Date 1943. The cULus certification is updated to 7B90.</p> |
| <p>Label for P/N 4736.0000, QTY 100, Lot 1, Date 1943. The cULus certification is marked as 31T1.</p> | <p>Label for P/N 4736.0000, QTY 100, Lot 1, Date 1943. The cULus certification is updated to 7B90.</p> |

**4 Reason of change**

cULus no. update according to the UL standard update

**5 Release date**

The change will be rolled-out starting ww 43/2019 (Date code 1943 or higher on label) and lasts approx. 6 months depending on the variant.

**6 Impact of change and recommended action**

|               |     |                     |
|---------------|-----|---------------------|
| Form          | No  | -                   |
| Fit           | No  | -                   |
| Function      | No  | -                   |
| Manufacturing | No  | -                   |
| Label         | Yes | Yes change on label |
| Packaging     | No  | -                   |

| Product Change Notification |               |              |             |                 | 4735-4736 change of label |        |             |
|-----------------------------|---------------|--------------|-------------|-----------------|---------------------------|--------|-------------|
| owner                       | creation date | release date | released by | change order no | rev                       | page   | D10-040-476 |
| sariogar                    | 21.10.2019    | 21.10.2019   | blumhe      | 2018601         | A                         | 1 of 2 |             |

**7 Reference Documents / Attachments**

| Kind of document                | Remarks |
|---------------------------------|---------|
| <a href="#">Data sheet 4735</a> |         |
| <a href="#">Data sheet 4736</a> |         |

|                             |               |              |             |                 |                           |        |             |
|-----------------------------|---------------|--------------|-------------|-----------------|---------------------------|--------|-------------|
| Product Change Notification |               |              |             |                 | 4735-4736 change of label |        |             |
| owner                       | creation date | release date | released by | change order no | rev                       | page   | D10-040-476 |
| sariogar                    | 21.10.2019    | 21.10.2019   | blumhe      | 2018601         | A                         | 2 of 2 |             |