

1 Products affected

| Product hierarchy no. * | | | | Part no. | SBU | Type / Description |
|-------------------------|-----|-----|------------|----------|--------------------------------|--------------------|
| SBU | PG | PUG | Type | | | |
| 02 | 005 | 016 | 0000001106 | See list | Power Entry Modules w/o Filter | 6220 |
| 02 | 005 | 016 | 0000001114 | See list | Power Entry Modules w/o Filter | KG |
| 02 | 005 | 016 | 0000001143 | See list | Power Entry Modules w/o Filter | GSF2 |
| 02 | 005 | 017 | 0000001165 | See list | Power Entry Modules w/o Filter | EC11 |

*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

2 Type of change



- Modified label
- Improved identification product configuration code on the label

3 Detailed description of change

All product types listed in section 1 receive a new label layout.

To better visualize the changes, we have used colors and numbers to cluster information into the following sections (The colors and white numbers are not part of the new label layout):

| | |
|---|---|
| Product identification section: To improve readability, we clustered all the information concerning product identification in this group. To increase clarity, we introduce our product configuration code into this area. | 1 |
| Product conformity section: Identical information was slightly rearranged. | 2 |
| Product logistics section: Label names changed. Information was slightly rearranged. | 3 |
| Product approval section: Identical information was slightly rearranged. | 4 |
| Interruption ratings section: Identical information was slightly rearranged. | 5 |
| Origin information section: Label for Factory Code was added. Information was slightly rearranged. | 6 |

| Old label | New label |
|---|--|
|  <p>The old label layout includes: 1. P/N KM00.1205.11, 2. SCHURTER AG CH-6002 Luzern, 3. QTY 50, 4. ST CoO: CZ, 5. KM POWER ENTRY MODUL 10A 70° KM-00-0133-0303-100, 6. Lot 3216547, Date 2121.</p> |  <p>The new label layout includes: 1. P/N KM00.1205.11, 2. SCHURTER AG CH-6002 Luzern, 3. Qty 50, 4. FC ST, 5. Part Description Configuration Code KM Power Entry Module 10A C14 KM-00-0133-0303-100, 6. CoO CZ.</p> |

4 Reason of change

SCHURTER improves and modernizes the label printing process to increase standardization and harmonize processes throughout all SCHURTER factory locations.

5 Release date

Packaging labels will be changed earliest in week 27/2021 (Date code 2127 or higher on the label).

| Product Change Notification | | | | | PCN Global Labeling | | |
|-----------------------------|---------------|--------------|-------------|-----------------|---------------------|--------|-------------|
| owner | creation date | release date | released by | change order no | rev | page | D10-058-189 |
| huberth | 02.06.2021 | 02.06.2021 | muehlema | 2022100 | C | 1 of 2 | |

6 Impact of change and recommended action

| | | |
|---------------|-----|--|
| Form | No | |
| Fit | No | |
| Function | No | |
| Manufacturing | No | |
| Label | Yes | No actions required since bar code & 2D-code are not affected by the change. |
| Packaging | No | |

7 Reference Documents / Attachments

| Kind of document | Remarks |
|---------------------------|--|
| List of affected articles | List contains a comparison of text/ content between old and new labels in reference to chapter 3. "Product identification section" |

| | | | | | | | |
|-----------------------------|---------------|--------------|-------------|-----------------|---------------------|--------|-------------|
| Product Change Notification | | | | | PCN Global Labeling | | |
| owner | creation date | release date | released by | change order no | rev | page | D10-058-189 |
| huberth | 02.06.2021 | 02.06.2021 | muehlema | 2022100 | C | 2 of 2 | |

