PRODUCT CHANGE NOTIFICATION



1 Products affected

| Product hierarchy no. * | | | | Part no. | SBU | Type / Description | Customer part no. |
|-------------------------|-----|-----|-----------|--------------|------------------------------|--------------------|-------------------|
| SBU | PG | PGU | Type | | | | |
| 02 | 007 | 042 | 000002285 | 4785.0000 | Connector Rewireable, Angled | 4785 | |
| 02 | 007 | 042 | 000002285 | 4785.0100 | Connector Rewireable, Angled | 4785 | |
| 02 | 007 | 042 | 000002285 | 4785.0100.08 | Connector Rewireable, Angled | 4785 | 83012520 |

^{*}SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

2 Type of change

Modification of approval marks

3 Detailed description of change

old version



new version



4 Reason of change

New CCC Approval and change the VDE approval to ENEC10

5 Release date

The change will be rolled-out starting ww 12/2014 and lasts approx. 9 months depending on the variant.

6 Impact of change and recommended action

Form: Change of approval

Fit: N/A
Function: N/A
Production Site: N/A
Product Label: N/A

7 Reference Documents / Attachments

| Kind of document | Document number | Remarks | | |
|------------------|-----------------|---------|--|--|
| 4785 Data Sheet | | | | |
| | | | | |

| | 0118.2198 | | | | | |
|---------------|------------|--------------|-------------|------------------|----------|--------|
| creation date | created by | release date | released by | notification no. | revision | page |
| 2014-01-09 | hollenpe | 2014-09-01 | hollenpe | 25611 | _ | 1 of 1 |