

PRODUCT CHANGE NOTIFICATION



OPTEK Technology

1645 Wallace Drive
Carrollton, TX 75006 USA

Phone: 972-323-2200
Facsimile: 972-323-2396
Email: sensors @optekinc.com
Website: www.optekinc.com

Notification Date: November 18, 2013.

Product Change Notification Number: 1018

Affected Part Numbers: See attachment I for the list of affected part numbers.

Description of Change: The C210-027-001 header is now being fabricated at new locations in Arizona and Massachusetts.

Change Identification: Product produced on or after date code 1347 will use headers from either new location.

Reason for Change: The original manufacturing location of this header was destroyed in a fire in December 2012. The two new fabrication locations are being qualified to ensure a future continuous supply of product.

Expected Impact: The new C210-027-001 header manufacturing locations will not impact the form, fit, function, quality, or reliability of the affected product.

Implementation of Change: November 18, 2013.

Cessation of Present Process: There is no inventory of the C210-027-001 headers from the previous fabrication location.

Assessment: The qualification report and samples from the Massachusetts manufacturing location are expected to be available after November 18, 2013. The qualification reports and samples from the Arizona fabrication location are expected to be available after November 25, 2013.

Product Change Notification Authorization:

A handwritten signature in blue ink, appearing to read 'Mike King'.

Mike King
Global Director of Engineering
Optoelectronics Business Unit



PRODUCT CHANGE NOTIFICATION

Notification Date: November 18, 2013

Product Change Notification Number: 1018

Affected Part Numbers: See attachment I for the list of affected part numbers.

Customer Product Change Notification Acknowledgement:

Recipient Signature: _____

Printed Name: _____

Company: _____

Position: _____

Date: _____

Customer Product Change Acceptance:

Acceptance Signature: _____

Printed Name: _____

Company: _____

Position: _____

Date: _____

Please return this product change notification with signature to:

Jeff Beatty
1645 Wallace Drive
Carrollton, TX 75006
Phone: +1.972.323.2464
Fax: +1.972.389.2355
Email: jeff.beatty@ttelelectronics.com

For any requests or exceptions, please contact your local TTElectronics sales representative.

Form 500-1047-001 Rev. -



A subsidiary of TT electronics plc

**Attachment I
PCN1018 Affected Part Numbers**

| Standard Part Numbers | Custom Part Numbers |
|------------------------------|----------------------------|
| OP123 | KT3582-2 |
| OP124 | OMT1024 |
| OP223 | OMT1026 |
| OP223TX | OMT1062 |
| OP224 | OMT1078 |
| OP224K | OP1531 |
| OP224S | OP2068 |
| OP224TX | OP2112 |
| OP224TXV | OP2851 |
| OP300SL | OP4211 |
| OP301SL | OP4294 |
| OP302SL | OP4323 |
| OP303SL | OP4362 |
| OP304SL | OP4873TXV |
| OP305SL | OP4935 |
| OP600A | OP6585 |
| OP600B | OP6599 |
| OP600C | OP6641 |
| OP603TX | OP6725 |
| OP604TX | OP6725A |
| OP604TXV | OP6726A |
| OP641SL | OP6728 |
| OP642SL | OP6731 |
| OP643SL | OP6731A |
| OP644SL | OP6755 |
| OP900SL | OP6773S |
| OPB700ALZ | OP6777 |
| OPB700TX | OP6779TXV |
| OPB700TXV | OP6781 |
| OPB700Z | OP6785 |
| OPB701ALZ | OPB10991-1 |
| OPB701Z | OPB11068 |
| OPB821TX | OPB11181 |
| OPB821TXV | OPB11421 |
| OPB847TX | OPB12277 |
| OPB870T51TX | OPB12277-01 |
| OPB871N55TX | OPB12326 |
| OPB871T51TXV | OPB12498 |
| OPB871T55TX | OPB12498 |
| OPV222 | OPB12498 |
| OPV322 | OPB12514 |



A subsidiary of TT electronics plc

Attachment I
PCN1018 Affected Part Numbers

| | Custom Part Numbers (Con't) |
|--|------------------------------------|
| | OPB12791 |
| | OPB12805 |
| | OPB3906A |
| | OPB7001 |
| | OPB8096 |
| | OPB9809 |
| | OPB9809Z |
| | OPS1319 |



A subsidiary of TT electronics plc

OPTOELECTRONICS

FIBER OPTICS

MAGNETIC SENSORS