



28-Jan-2022

**PCN #:** PCN-22-127818

**Subject :** 8 and 14 position AMPSEAL plug assembly

**Description of Change :** The Industrial and Commercial Transportation business unit of TE Connectivity is making a material change to the perimeter seal used on the AMPSEAL Sealed Plug Assembly for the part number(s) listed below. These PNs are TE proprietary designs, therefore considered catalog/general market product. PPAP request must be submitted within 14 days of PCN submission via [ict-ppap-request@te.com](mailto:ict-ppap-request@te.com) or ePPAP system. Submission will not occur without request. If PPAP requested, disposition response is required within 14 days of submit date or it will be considered approved. Product drawing(s) is affected.

Dear Customer, we hereby inform you of this change. The change is necessary to avoid supply chain disruption. The change does not impact performance. **IMPORTANT:** The current and previous revisions of these parts can be used interchangeably in the field. The change(s) are being phased in gradually and previous revision can remain stocked until use. Shipments of both configurations may be mixed

**Reason :**

**Key Dates :**

**Contact By Date:**31-Mar-2022

**Implementation Date:**31-Mar-2022

<b>Product Affected</b>	<b>Alias Part Number</b>	<b>Substitute Part Number</b>	<b>AliasSub Part Number</b>
776286-2			
776273-5			
776273-1			
776273-4			
776273-2			
776286-1			

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.