



Product Change Notification

Current Date: 18-Mar-2015

TE Connectivity

Product Change Notification: P-15-011242

PCN Date: 17-MAR-15

Customer: TTI Inc(0000139702)

Location: WORLDWIDE

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
AMPLIMITE PCB Mount Receptacle Assemblies, Sizes 1-4

Description of Changes
Change assembly insert material. was: GLCP-30F PER MIL-M-24519 now: POLYPHENYLENE SULFIDE GST-40F PER MIL-M-24519. The Size 5 Receptacle Assembly insert already molded in POLYPHENYLENE SULFIDE GST-40F PER MIL-M-24519.

Reason for Changes:								
Product improvement.Consolidation of insert materials improves efficiencies.								
Estimated Dates:								
<table border="1"><tr><td>Last Order Date (Obsolete Parts Only):</td><td>First Date To Ship (Changed Parts Only):</td></tr><tr><td></td><td>30-JUN-2015</td></tr><tr><td>Last Ship Date (Obsolete Parts Only):</td><td>Last Date for Mixed Shipments: (Changed Parts Only):</td></tr><tr><td></td><td>30-DEC-2016</td></tr></table>	Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):		30-JUN-2015	Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):		30-DEC-2016
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):							
	30-JUN-2015							
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):							
	30-DEC-2016							

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1218408-1	NO						
1218408-2	NO						
1218408-4	NO						
1218434-2	NO						
1218434-4	NO						
1757828-1	NO						
1757828-2	NO						
1757828-3	NO						
1757828-4	NO						
1757830-1	NO						
1757830-2	NO						
1757830-3	NO						
1757830-4	NO						
1757836-1	NO						
1757836-2	NO						
1757836-3	NO						
443975-1	NO						
443975-2	NO						
443975-3	NO						
443975-4	NO						
443976-1	NO						
443976-2	NO						
443976-3	NO						
443976-4	NO						

Customer: TTI Inc(1281288)

Location: Fort Worth

Agreement Number: TTI002

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1218408-1	NO						
1218408-2	NO						
1218408-4	NO						
1218434-2	NO						
1218434-4	NO						
1757828-1	NO						
1757828-2	NO						
1757828-3	NO						
1757828-4	NO						
1757830-1	NO						
1757830-2	NO						
1757830-3	NO						
1757830-4	NO						
1757836-1	NO						
1757836-2	NO						
1757836-3	NO						
443975-1	NO						
443975-2	NO						
443975-3	NO						
443975-4	NO						
443976-1	NO						
443976-2	NO						
443976-3	NO						
443976-4	NO						

Customer: TTI Inc.(1305175)

Location: Maisach-Gernlinden

Agreement Number: TTI001

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1218408-2	NO						
1757828-4	NO						
1757830-1	NO		TYC1757830-1				
1757830-2	NO		TYC1757830-2				
1757830-4	NO		TYC1757830-4				
443976-1	NO		TYC443976-1				
443976-2	NO		TYC443976-2				