



02-Sep-2016

PCN #:E-16-012472

**Subject:**OBSOLETE HAND TOOL Action for order processing Action for purchasing No Action for field service

**Description of Change:** The following part numbers are being discontinued (obsolete status). If there are suggested TE Connectivity substitute part numbers or alternate part numbers, they are shown below with any significant differences described. Please verify all substitute or alternate part numbers provided are suitable for your specific application. Drawings are available via [TE.com](http://TE.com).

**Reason:** Discontinuance.

**Impact of Change:**form - fit - function

**Key Dates:**

**Last Order Date:**06-Sep-2016

**Last Ship/EOL Date:**13-Sep-2016

**Product Affected**

654174-1

(Alias Part Numbers:

"CL5479-000"

"SIML-0-0654174-1")

**Recommended Replacement**

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.