



15-Jun-2018

PCN #:E-18-007392

Subject:LC Tight Jacket Connector -- Protective Cap Change

Description of Change: Change protective cap on all LC Tight Jacket kits, Gen. 1 only

Reason: Product Improvement. Polymer availability for molding current santoprene cap. New cap will result in improved cap retention

Impact of Change:form - fit - function

Key Dates:

Contact By Date:22-Jun-2018

Implementation Date:22-Jun-2018

Product Affected

1918228-1

6828130-2

6828095-1

6828130-1

(Alias Part Numbers:

"CON11582")

6828129-1

6828094-1

6828129-2

1918153-1

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.