



09-Jul-2018

PCN #:E-18-010126

Subject:RAYCHEM parts D-436-60, DR25-1-2-0-SP, DR25-3-16-0-SP, ROUNDIT2000-13MMBK, S1255-02.

Description of Change: RAYCHEM parts Discontinuance

Reason: Discontinuance. These parts are neither in stock nor certainly in SAP. So we got confirmation from Raychem that we can make them obsolete.

Impact of Change:form - fit - function

Key Dates:

Last Order Date:31-Jul-2018

Last Ship/EOL Date:15-Aug-2018

Product Affected

S1255-02

DR25-3-16-0-SP

(Alias Part Numbers:

"DR25-3/16-0-SP")

D-436-60

ROUNDIT2000-13MMBK

(Alias Part Numbers:

"ROUNDIT-2000-13MM-BK")

DR25-1-2-0-SP

(Alias Part Numbers:

"DR25-1/2-0-SP")

Recommended Replacement

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.