



21-Jun-2019

PCN #:E-19-009746

Subject:Superseding of existing HT-200 Tubing part numbers.
Manufacturing location change, Sales Unit of Measure change.

Description of Change: The following part numbers are being obsoleted (obsolete status). If there are suggested TE Connectivity substitute part numbers or alternate part numbers, they are shown below with any significant difference described. Please verify that all substitute or alternate part numbers provided below are suitable for your specific application.

Reason: Discontinuance. Dear Customer, You are receiving this notice because TE Connectivity has record of you purchasing a part or multiple parts on the list below. TE Connectivity is continuing to move production of HT-200 tubing to Trutnov CZ. This on-going transfer is being made in phases until all appropriate equipment has moved. Different parts will move in different phases, consequently all new part numbers may not be immediately available at the end of the notification period. We will start to ship HT-200 products from the Czech Republic after September 10th 2019. After this date TE reserves the right to provide qualified products from any of the manufacturing locations during this transfer until the final closure date of Menlo Park location by the end of 2019. As not all part numbers will transfer at the same time customers may still receive Products from the Menlo Park location after this transfer date due to inventory.

Key Dates:

Last Order Date:30-Sep-2019

Last Ship/EOL Date:31-Dec-2019

Product Affected

EM3030-000

(Alias Part Numbers:

"HT-200-2-X-SP")

Recommended Replacement

NB17174001

Product Affected	Recommended Replacement
EM3029-000 (Alias Part Numbers: "HT-200-1-1/2-X-SP")	NB17144001
EM3028-000 (Alias Part Numbers: "HT-200-1-1/4-X-SP")	NB17154001
CV4363-000 (Alias Part Numbers: "HT-200-1-X-SP")	NB17164001
CV4362-000 (Alias Part Numbers: "HT-200-3/4-X-SP")	NB17184001
CV4361-000 (Alias Part Numbers: "HT-200-1/2-X-SP")	NB15124001
CV4360-000 (Alias Part Numbers: "HT-200-3/8-X-SP")	NB15184001
CV4359-000 (Alias Part Numbers: "HT-200-1/4-X-SP")	NB15134001
CV4358-000 (Alias Part Numbers: "HT-200-3/16-X-SP")	NB15154001
CV4357-000 (Alias Part Numbers: "HT-200-1/8-X-SP")	NB15144001
CV4356-000 (Alias Part Numbers: "HT-200-3/32-X-SP")	NB15164001

Product Affected
CV4355-000
(Alias Part Numbers:
"HT-200-1/16-X-SP")

Recommended Replacement
NB15114001

CV4354-000
(Alias Part Numbers:
"HT-200-3/64-X-SP")

NB15174001

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.