



Product Change Notification

Current Date: 01-Nov-2020

TE Connectivity

Product Change Notification: P-20-019933

PCN Date: 30-OCT-20

Customer: TTI Inc(0000139702)

Location: WORLDWIDE

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

SINGLE WIRE SEAL

Description of Changes

Manufacturing location change. Following Part Numbers will be transferred from Supplier Elmet (Austria) to TE San Salvo (Italy). The involved mold is 21-0067882 that produce the PN 281934-4.

Reason for Changes:

Dear Customer, we hereby inform you about a transfer of tool. The transfer follows a strict procedure, which fully maintains quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location operates under a certified quality management system in accordance with standard automotive requirements. A TE-internal release test based on the relevant part specifications will be executed before delivery. Upon request, a PPAP Level 2 will be available if it concerns a transfer of a tool which produces a finished TE-product. A PPAP Level 1 will be available if it concerns a component of a TE-product, where the production location of the finished TE-product remains unchanged. If you require such a PPAP, please notify the responsible TE Sales Contact within 14 calendar days after receipt of this PCN.

Estimated Dates:

Last Order Date (Obsolete Parts Only): First Date To Ship (Changed Parts Only):

26-MAR-2021

Last Ship Date (Obsolete Parts Only): Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
281934-4	NO			"CM8392-000", "AMP-0-0281934-4", "820P-36529", "4004200208", "80.244.00", "43116-000"			

Customer: TTI Inc (3164508)

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
281934-4	NO			"CM8392-000", "AMP-0-0281934-4", "820P-36529", "4004200208", "80.244.00", "43116-000"			

Customer: TTI Electronics Asia Pte Ltd. (2771300)

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
281934-4	NO			"CM8392-000", "AMP-0-0281934-4", "820P-36529", "4004200208", "80.244.00", "43116-000"			
281934-4	NO			"CM8392-000", "AMP-0-0281934-4", "820P-36529", "4004200208", "80.244.00", "43116-000"			

Customer: TTI Inc (168830)

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
281934-4	NO			"CM8392-000", "AMP-0-0281934-4", "820P-36529", "4004200208", "80.244.00", "43116-000"			

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
281934-4	NO		TYC281934-4	"CM8392-000", "AMP-0-0281934-4", "820P-36529", "4004200208", "80.244.00", "43116-000"			

Customer: TTI Electronics Asia Pte Ltd. (2771300)

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
281934-4	NO			"CM8392-000", "AMP-0-0281934-4", "820P-36529", "4004200208", "80.244.00", "43116-000"			
281934-4	NO			"CM8392-000", "AMP-0-0281934-4", "820P-36529", "4004200208", "80.244.00", "43116-000"			

Customer: TTI Electronics Asia Pte Ltd. (1407161)

Location: Hong Kong

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
281934-4	NO			"CM8392-000", "AMP-0-0281934-4", "820P-36529", "4004200208", "80.244.00", "43116-000"			

Customer: TTI (556264)

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
281934-4	NO			"CM8392-000", "AMP-0-0281934-4", "820P-36529", "4004200208", "80.244.00", "43116-000"			