



19-Jan-2022

PCN #: P-22-022031

Subject : Spec 44 and FLDW Wires

Description of Change : TE Connectivity was informed by one of its material supplier on a consolidation in their manufacturing plant for PVDF based Color Concentrates (CC). TE Wire and Cable plants in Tijuana and Redwood City use PVDF CCs as colorant for outer insulation layer in spec 44 and FLDW primary wires. TE has evaluated the PVDF CCs from the supplier's new manufacturing location and no change to Form, Fit and Function of finished parts has been observed.

Reason : Part status change. TE was notified by its material supplier that except for Black PVDF CC, no change has been made in material formulation and recipe for PVDF CCs produced from their new manufacturing site. Due to health and safety policy of vendor's new manufacturing site with respect to handling raw carbon black pigments, this CC has undergone a change of one raw material component. TE evaluated these changes on the key characteristics of the CCs and the finished goods and no impact on the properties and performance of finished parts has been observed. Test reports on the wire characteristics can be provided upon request. In addition to the evaluation conducted by TE, FAIs will be performed on the first manufactured primary wire lot per each gauge for validation.

Key Dates :

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
875991-000	"4-1200449-2", "EPD21139B"		
CM3166-000	"44B1121-14-0/2-9CS356"		
160335-000	"8-1191157-7", "44AM1121-16-04/5-9"		
EM7090-000	"400R4121-14-0/2-0"		
747555K001	"7-1195831-9"		
810503K001	"5-1196298-2"		

188763-000	"9-1191369-3", "EPD51237A-X-0"		
710683K001	"1-1195568-6"		
522705-000	"44AM1161-22-MSL6-9CS2275", "2-1194107-3"		
377177K001	"5-1192824-3"		
756043-000	"44A1221-16-0/9-9-1KF/1", "3-1195892-8"		
CW0103-000	"EPD-RWC-20307-L028"		
021781-000	"9-1190168-6", "44AM1131-16-0/0/0-9"		
944373-000	"2-1197310-0", "WXA-0085-16-0"		
CW7486-000	"81044/12-18-0CS3209"		
282780-000	"1192126-5", "44A0111-24-09"		
EK4599-000	"FLDWC6004-18-0"		
001152-000	"1-1199146-8", "EPD64686A-US"		
2820303009	"1192096-8", "44A0111-22-0"		
EG8788-000	"400R0111-12-0"		
688453-000	"6-1195407-1", "EPD52978A"		
CA8214-000	"EPD98957B-US"		
665517-001	"7-1195243-0", "FB-44-4624-0201CS1578"		

259658-000	"6-1191899-2", "345/63B-26-90-0"		
919647-000	"6-1197136-5", "EPD-RWC-10074"		
382121-006	"1192857-9", "44A1131-24-0/2/9-9-MX"		
CN5904-000			
936211-000	"44A7985-X-9CS1663", "3-1197253-9"		
573277K001	"9-1194550-9"		
A27812K001	"7-1200403-1"		
CU8702-000	"EPD-DND-21443-L279"		
473439-000	"1193547-4", "EPD-ROC-10040"		
CF1591-000			
EF5949-000			
EH2576-000	"44A9677-20-ELC4-9CS3433"		
437583K003	"9-1193288-8"		
405629-000	"1-1193061-3", "EPD52960A"		
CF1668-000	"FLDWC0311-14-0CS2736"		
CX1597-000	"EPD-DND-22560"		
F80785-000	"EPD62598A-MTI", "6-1200500-7"		
484899-000	"44AM1121-20-0/2-9CS356", "5-1193629-6"		
415151-000	"1193129-3", "EPD-ROK-10019"		

331469-000	"3-1192504-6", "EPD-ROK-10314"		
045792K001	"4-1198990-5"		
3C0542-000	"5-1193002-0", "EPD5841-20-0"		
306045-001	"3-1192317-9", "44AM1121-20-0/9-9"		
CB7448-000	"44A4231-20-0/2/9-9"		
059325K001	"1-1190450-7"		
265908-000	"1191963-9", "81044/9-14-0"		
094903K001	"3-1190695-8"		
669901K001	"5-1197823-4"		
EH2535-000	"EPD-RWC-23832"		
281703-000			
778585-000	"345/37B-22-60-0CS1913", "9-1196059-5"		
EH8076-000	"44A9605-20-0"		
983269-000	"8-1197596-1", "EPD20028C-18-0CS2231"		
631705-000	"44AM1121-20-0/6-9", "6-1197825-2"		
CX1587-000	"EPD-DND-21459"		
341901-000	"8-1192577-6", "EPD33489A-US"		
857582K001	"6-1197956-6"		
294531K001	"4-1192231-1"		

286870-000	"1-1198927-9", "EPD-RWC-16522"		
D60328-000	"5-1201391-3", "EPD-ROK-10326-L027"		
D04838-000	"9-1200552-4", "FLDWC1331-20-ELC3-9CS3050"		
D97471-000	"81044/12-20-0CS3005", "2-1200714-4"		
CU5269-000	"EPD66213A-L099"		
CS7470-000	"EPD-DND-21443-L099"		
A03913-000	"2-1200450-7", "EPD-ROK-10326-L063"		
301019-000	"1201275-6", "44AM1111-20-0-9"		
551129-000	"345M09J-22-6-0CS2041", "8-1194356-2"		
511349-000	"4-1194019-2", "EPD51031A-22-0"		
EQ07443001	"44A1121-14-0/9-9CK0202/2"		
EG8824-000	"400R1121-12-0/9-9"		
889663-002	"3-1196921-8", "EPD23572B-US"		
782197-000	"5-1196075-5", "44AM4121-24-0/9-9CS262"		
CJ1642-000			
CY8606-000			

267968-000	"3-1198990-2", "EPD-ROK-10491"		
A86940-000	"5-1201041-0", "EPD-RWC-18211"		
036753K001	"8-1190283-7"		
017891-000	"6-1190139-7", "EPD52164A-18-0"		
CX8477-000	"EPD114769 A-US"		
CN6738-000			
CP6420-000	"EPD-RWC-21576"		
510839-000	"44AM1121-26-0/9-9CS984", "1-1194015-3"		
F46141-000	"4-1201367-1", "FLDWC0311-24-0CS2979"		
CX0036-000	"EPD-DND-21547-L016"		
360615K001	"1-1192705-0"		
CU3944-000			
CS7486-000	"EPD-DND-21451-L099"		
BM9598-000	"44A1171-20-F856-9"		
680589-000	"1-1195353-7", "EPD-RWC-15759"		
382590-000			
797355K001	"8-1196169-1"		
CF9907-000	"EPD-RWC-20536-L106"		
371991K001	"4-1192786-1"		
572409-000	"6-1194543-9", "EPD51026A-26-0"		

CR4774-000			
A57811K001	"3-1201147-4"		
009023K001	"9-1190069-6"		
512653-000	"4-1194028-5", "81044/9-24-0"		
306137-001	"2-1192318-6", "44AM1121-22-0/2-9"		
CS2807-000	"EPD-RWC-21804"		
631831K001	"3-1194999-9"		
771521-000	"1-1196010-9", "EPD-RWC-15513"		
638645-000	"44AM1121-22-0/2-9CS356", "2-1195048-2"		
EH8636-000	"400R0311-12-0"		
383234-000	"6-1192872-2", "44A1121-16-0/2-9"		
382525-000	"8-1192864-2", "44A0124-24-0/9-US"		
851555K001	"2-1196639-1"		
779703K001	"5-1196067-2"		
C00385-000	"44AM1131-20-0/4/8-2", "6-1200570-4"		
246475-000	"1191808-5", "44AM1131-22-0/1/9-9CS1702"		
D24587-000	"4-1201423-3", "EPD-RWC-18510"		
CU6390-000	"EPD-DND-22841"		
CU6479-000			

CS1914-000	"EPD66778B-US-L012"		
333750-000	"7-1192521-9", "EPD23071B"		
368745-000	"4-1192763-6", "EPD-ROK-10313"		
269893-000	"1-1191992-1", "EPD-RWC-14598"		
CF8629-000	"EPD-RWC-20454-L188"		
CA1805-000	"FB-44-4624-0209CS3186"		
608403-000	"1-1194812-8", "EPD-RWC-15432"		
475388-000	"6-1199104-5", "EPD-RWC-16564CS2966"		
358875K001	"8-1192692-8"		
279644-000	"2-1197957-7", "EPD-RWC-16327"		
382765-000	"6-1192867-0", "44A1121-18-0/9-0-MX"		
173409-000	"1-1191261-5", "345M15B-22-38-0CS2041"		
900081-000	"5-1196996-9", "FB-44-7026A-0232CS896"		
756875-000	"2-1195898-0", "EPD52212A"		
394385-000	"7-1192958-3", "44A0121-22-0/2CS356"		
284854-000	"5-1192153-4", "44A0111-18-09-MX"		

CU0182-000	"EPD-RWC-10937-L016"		
200397-000	"1-1191452-6", "EPD-RWC-14595"		
3823123016	"3-1192861-1", "44A0121-24-0/9"		
CX8556-000	"EPD-RWC-23210"		
449607K001	"2-1193377-9"		
736933K001	"1195754-5"		
360199K001	"3-1192702-9"		
301187-000	"7-1192281-1", "44AM1111-24-0-9"		
EG8804-000	"400R1111-10-0-9"		
D42281-000	"1-1201229-8", "CXA-0197-22-0/9-9"		
145927-000	"7-1191054-8", "EPD47168A"		
EG8850-000	"400R1131-20-0/6/9-9"		
A94835K001	"7-1201818-2"		
916713K001	"1197116-6"		
CS6946-000	"EPD-DND-21535-L099"		
667861-000	"7-1195259-2"		
125955-000	"6-1190915-0", "81044/12-26-05"		
CF3510-000			
390425-000	"2-1192931-2", "44AM1141-18-0/2/5/9-9"		

284491-000	"2-1192150-9", "44A0111-20-03-MX"		
E42006K001	"9-1200697-6"		
110495-000	"1-1190807-3", "EPD-RWC-10947"		
768919-000	"6-1195991-7", "EPD48804B-24-0"		
123533-001	"6-1190898-2", "FB-44-7026A-0213CS896"		
674611K001	"1-1195306-2"		
526608-000	"2-1194138-6", "44AM4121-22-0/9-9CS262"		
179129-000	"2-1191302-7", "81044/12-22-0CS294"		
A14982-000	"5-1201264-6", "44A1121-18-0/2-0-L016"		
CY6749-000	"EPD-DND-21491"		
952483K001	"8-1197375-0"		
CU4944-000			
CS6999-000	"EPD-DND-21508-L099"		
487335-000	"5-1193646-5", "EPD52956A"		
EG8806-000	"400R1111-12-0-9"		
A76985-000	"2-1200577-6", "EPD-RWC-17038"		
EG8856-000	"400R1131-26-0/6/9-9"		

651503K001	"7-1195143-9"		
219319K001	"3-1191618-2"		
980341-000	"44A0111-26-0CS2896-N", "4-1197575-6"		
353793K001	"9-1192656-0"		
E43679K001	"4-1201140-7"		
EH2503-000	"44A9090-16-0/2/9-9CS3433"		
CB6207-000			
469091K001	"6-1193515-6"		
493863-000	"44A9666-16-0/9", "7-1193693-1"		
F69670W001	"8-1201755-6"		
201249-000	"9-1191458-5", "44A0141-12-0/1/7/8CS356"		
CJ1639-000			
383862-000	"3-1192879-0", "44A0121-14-0/9"		
314353K001	"4-1192379-6"		
CY8600-000			
141121K001	"9-1191022-8"		
CR6173-000	"44A0131-12-0/2/9-MX"		
306338-001	"3-1192320-6", "44AM1131-22-0/2/9-9"		
542901K001	"6-1194258-0"		
145672K001	"6-1198867-9"		

170045-000	"6-1197847-4", "EPD30222D-US"		
321219K001	"3-1192434-8"		
CS1906-000	"EPD100949 A-US-L012"		
CX8995-000			
485584-000	"345/46B-22-48-0CS1913", "8-1193633-2"		
CY7495-000			
847643-000	"81044/12-14-0-1KF/1", "1196611-2"		
CN5903-000			
EG3461-000	"EPD-RWC-21561-L335"		
734863-000	"3-1195739-1", "EPD45267A"		
226611-000	"6-1191668-4", "EPD64092A"		
CV7302-000			
602253-000	"44A9664-12-0/2/9-0", "5-1194767-6"		
643637K001	"2-1195085-1"		
382554-002	"2-1192865-6", "44A1141-24-0/2/5/9-9"		
306317-000	"1-1192320-2", "44AM1131-20-0/2/9-9"		
232486-000	"8-1191707-2", "EPD20021C"		
443591K001	"1193334-3"		
C59836-000	"5-1201885-1", "44A0114-24-0-L095-US"		

CA2669-000	"EPD42817A-US"		
495691-000	"44A7668-20-8", "3-1193707-9"		
EF7914-000			
520978K001	"3-1199499-2"		
421804-000	"1193177-2", "44B1121-16-0/9-92"		
CY0038-000			
845723K001	"1-1196597-9"		
306253-000	"2-1192319-8", "44AM1121-24-0/9-9"		
313306-000	"3-1200195-7", "81044/12-24-0CS3005"		
115113-000	"9-1190838-7", "EPD52598A-26-0"		
A93907K001	"1201056-2", "EPD-ROK-10512-COC-KIT-1"		
955822-000	"44AM1121-22-0/9-91", "3-1197400-0"		
383141-002	"7-1192871-7", "44A4121-18-0/9-9-US"		
606475K001	"1194798-5"		
009527-000	"9-1190073-5", "44AM1131-12-0/2/9-9"		
653701-000	"7-1197887-7", "WXA-0085-10-0"		
524238-000	"4-1199501-9", "EPD-NAV-85410"		
CX2183-000	"FLDWC0311-12-0CS2736"		

306631-000	"9-1192322-8", "44AM1141-24-0/2/6/9-9"		
502413K001	"7-1193773-1"		
282097-000	"9-1192103-0", "44A0211-24-0"		
CR3725-000	"EPD-RWC-21561"		
CR3658-000	"EPD-RWC-22218"		
460719K001	"7-1193455-0"		
CR3649-000			
358097K001	"2-1192687-6"		
E96035K001	"4-1200803-0"		
966855K001	"2-1197476-1"		
384221-000	"5-1192882-4", "44A0121-22-0/1"		
384890-000	"8-1192887-7", "44A1141-24-0/2/6/9-9"		
021267K001	"4-1190165-8"		
478343K001	"9-1193581-7"		
584047-000	"345M12B-26-12-0CS2041", "4-1194625-7"		
CX8433-000	"44A4141-16-0/2/4/5-"		
383379-000	"5-1192874-2", "44A1131-20-0/2/9-91"		
CY1328-000			
061625K001	"2-1190466-0"		
083761K001	"1190619-7"		
E72128K001	"1200403-6"		

919599-000	"345M06B-22-14-0", "2-1197136-8"		
389783-000			
637976-000	"3-1200290-5", "FLDWC0311-20-0CS2979"		
CX8467-000			
496797K001	"6-1193714-7"		
C66874-000	"1201179-4", "EPD-RWC-18569-L099"		
737050-000	"44AM1121-22-0/9-97", "5-1199113-9"		
CJ5174-000			
CM4936-000			
CN6850-000			
CB4569-000	"EPD37260A-US-L099"		
CX1256-000	"ATFC0411-18-09"		
EG8846-000	"400R1131-16-0/6/9-9"		
EM3777-000	"44AM1131-16-0/2/9-9-L227"		
582235-000	"5-1194612-5", "EPD61790A"		
CN5670-000			
086887-000	"2-1190641-2", "44AM1841-10-0/2/5/9-9"		
282230-000	"2-1192109-4", "81044/12-14-0"		
CU8796-000	"EPD-DND-21490-L177"		
483638-000	"44B1121-24-0/9-98", "6-1193619-7"		

579863-000	"6-1194595-9", "EPD32869C"		
645557-000	"4-1195098-0"		
211983-000	"3-1191535-3", "345M09J-22-38-0CS2041"		
383346-000	"2-1192874-0", "44A1121-22-0/9-97"		
A942803001	"7-1201388-6", "44A1121-18-0/9-9CK0001"		
503015-000	"2-1193786-7", "EPD-RWC-14223"		
000321-000	"6-1190002-6", "345/52B-18-21-0CS1913"		
510249K001	"7-1194010-4"		
436839K001	"6-1193283-3"		
107475K002	"2-1190785-5"		
462455-000	"5-1193468-1", "CMC-0560-X-0"		
347493-000	"1192615-2", "EPD37109B-US"		
D33399K001	"1201448-9"		
306011-000	"9-1192316-9", "44AM1121-14-0/9-9"		
CR9948-000	"EPD84639A-US"		
668743-000	"8-1195265-1", "EPD-RWC-14030"		
CM1061-000	"EPD86690A-US"		
876777-000	"44AM4121-26-0/9-9", "7-1196819-8"		

066557-000	"9-1190501-9", "44A0121-24-0/2CS356"		
589453-000	"9-1194663-2", "EPD-RWC-14225"		
CU9566-000			
282662-000	"1192122-9", "44A0114-20-0"		
564393-000	"44AM1141-22-0/2/4/94-0", "2-1194458-9"		
833031-000	"44A9677-20-ELC4-9CS2746", "9-1196503-7"		
CN1265-000			
818647K001	"9-1196379-3"		
CS8052-000	"EPD-DND-22560-L016"		
589611K001	"1194665-4"		
A65327K001	"8-1199953-2"		
CR9275-000	"81044/12-22-0-BARREL"		
382372-004	"3-1192862-0", "44A4121-16-0/9-9-MX"		
364523K001	"7-1192733-3"		
736583K001	"6-1195751-4"		
162545-000	"4-1191173-4", "44A7715-22-0CS2230"		
496637-000	"44AM1121-16-05/62-9", "5-1193713-6"		
383491-000	"6-1192875-1", "44A1121-22-0/9-93"		
923652-000	"5-1197165-6", "EPD8471B-US"		

316837-000	"6-1192400-7", "EPD-RWC-15754"		
CS7774-000	"EPD-DND-22560-L099"		
651289-000	"3-1195142-7", "EPD52964A"		
356581K001	"2-1192676-9"		
556179K001	"3-1194387-8"		
846082-000	"4-1198263-9", "EPD92660A-US"		
045167-000	"1190347-2", "EPD51157A"		
247092-000	"5-1199505-7", "EPD-RWC-17079"		
136811K001	"7-1190991-3"		
774005-000	"44AM1121-24-0/9-9CS262", "5-1196027-3"		
969347-000	"2-1197494-8", "WXA-0085-14-0"		
CS1829-000			
CU8800-000	"EPD-DND-23026-L281"		
E33792-000	"5-1201345-6", "EPD-RWC-10937-L110"		
475279-000	"1193560-7", "FB-44-7026A-0225CS896"		
262031-000	"5-1191927-3", "44A0711-16-0"		
F57013-000	"EPD95429A-US", "1200589-8"		

732021-000	"5-1195718-3", "FB-44-7026A-0215CS896"		
844345-000	"44A9676-20-0/2/9-9CS2746", "4-1196587-2"		
CU0952-000	"EPD-DND-21440-L016"		
093335-000	"7-1190684-2", "44T1121-20-0/9-04"		
641895-000	"1-1195073-1", "EPD69160A-20-0"		
458702-000	"44B1121-24-0/9-92", "1-1193441-9"		
169754-000	"7-1199952-9", "EPD4695A-US"		
ER1220-000			
662203K001	"9-1195219-3"		
843081K001	"7-1196576-2"		
259135K001	"8-1191895-5"		
CZ1117-000			
826170-000	"44A9605-16-0CS2979", "6-1199983-3"		
CP6417-000			
837487-000	"44A9550-20-0-US", "5-1196536-9"		
CA2939-000			
EH1805-000	"81044/12-20-0CS3209"		
ER0597-000	"EPD-RWC-21427-L414"		
EG8786-000	"400R0111-10-0"		
825887-000	"1196451-8", "EPD52946A"		

CP8075-000			
817861K001	"1-1196373-7"		
EJ1070-000	"EPD43502D-US-L012"		
400911-000	"4-1193027-1", "EPD52798A-10-0"		
232555-000	"3-1191708-1", "FB-44-7026A-0221CS896"		
744151-000	"345M18B-18-42-0CS2041", "3-1195805-9"		
A39894-000	"4-1201667-6", "81044/12-20-0-L136"		
277405K001	"3-1192054-0"		
383865-000	"4-1192879-1", "44A0121-20-0/2"		
EH2693-000	"44A4321-22-0/9-9CS3433"		
CZ2709-000			
374962-000	"3-1201789-5", "44A1321-24-0/9-9-US"		
C82313-000	"3-1201922-3", "EPD-RWC-19452-L016"		
704839-000	"345/37B-22-30-0", "5-1195528-2"		
382714-000	"1192867-8", "44A1122-22-0/9-9-US"		
416739K001	"5-1193140-7"		
E97673-000	"9-1201653-9", "EPD-ROK-10544"		
F04014K001	"1200501-8"		

A21790-000	"7-1200541-5", "EPD-RWC-17701"		
666426-001	"345/98B-26-48-0CS1913", "8-1195249-5"		
790651K001	"1-1196124-6"		
CS7760-000			
CX8764-000	"EPD-DND-23320"		
D80930K001	"8-1200589-1"		
CA2184-000			
325471K001	"9-1192462-4"		
010063K001	"5-1190078-8"		
919175K001	"1197133-5"		
876717K001	"4-1196819-2"		
382451-003	"6-1192863-1", "44A4121-20-0/9-9-US"		
393867-000	"8-1192954-4", "44B1811-10-0-9"		
CP2425-000			
CM9790-000			
D06718K001	"9-1200523-5"		
704943-000	"44A9663-16-0-0", "2-1195529-7"		
384958-000	"6-1192888-2", "44A7600-26-0/9"		
888429K001	"5-1196911-5"		
CB7025-000	"44A3131-16-0/2/3"		
260049-000	"6-1191902-7", "EPD51069A-22-0"		

614731-000	"44AM1121-24-0/2-94", "3-1194859-1"		
306266-001	"4-1192319-8", "44AM1121-26-0/9-9"		
416733-000	"4-1193140-9", "EPD23068B"		
CX8762-000			
CJ5877-000			
CN6737-000			
172649-000	"6-1191255-8", "EPD51035A-22-0"		
594367-000	"44A1181-20-A707-9", "1194699-8"		
774085K001	"1196028-9"		
771339-000	"44AM4121-22-0/9-95", "9-1196008-9"		
137105-000	"9-1190993-0", "44A0111-22-0CS289"		
348563-000	"9-1192622-9", "EPD-RWC-11709"		
CF2166-000			
E872683001	"4-1201229-9", "44A0121-22-0/9CK0001"		
547231K001	"4-1194308-1"		
306490-000	"1192322-1", "44AM1121-22-0/9-90"		
383485-000	"4-1192875-7", "44A1121-20-0/9-92"		
EG8346-000			
F30521-000	"8-1201274-0", "ATFC0713-22-0"		

CN2382-000	"44A0311-16-0-1KF/1"		
407015K001	"7-1193070-9"		
046691K001	"6-1190358-9"		
805420K001	"9-1198861-6"		
A46997K001	"2-1201132-2"		
176575K001	"8-1191283-0"		
467481K001	"1193504-4"		
529879-000	"1-1194161-8", "EPD-RWC-14229"		
940089K001	"6-1197279-3"		
A62800-000	"6-1200524-2", "EPD62609A-MTI"		
D81774-000	"8-1201757-2", "FLDWC0311-20-0CS3149"		
300078F003	"9-1192272-7"		
CS3830-000	"EPD-DND-21535-L263"		
D08897K001	"9-1201426-6"		
404841K001	"4-1193055-8"		
005335-000	"7-1190040-2", "EPD51038A-18-0"		
717673-000	"44A0111-24-0CS289", "8-1195613-9"		
306217-000	"1192319-7", "EPD-RWC-14213"		
EG5965-000	"EPD62288A-US"		
CR1999-000	"44B1121-20-0/9-9"		

748116-001	"44A0114-24-0CS448", "9-1195835-3"		
678663-000	"1195335-7", "44A1231-16-0/2/9-9"		
635959K001	"5-1195028-6"		
416799-000	"1193141-7", "EPD51048A-18-0"		
594157K001	"6-1194697-3"		
EM5739-000	"44AM4141-12-0/2/5/9-9"		
CU7739-000	"EPD-DND-22844-L276"		
007603-000	"9-1190058-2", "44AM1121-18-0/9-9CS356"		
EG2807-000	"44A0111-22-0-E626"		
EG8820-000	"400R1111-26-0-9"		
382308-004	"7-1192860-3", "44A1131-16-0/2/9-9-MX"		
271983-000	"1-1192015-5", "44A1121-20-0/9-9CS406"		
058553K001	"3-1190444-4"		
598779-000	"345M18B-18-30-0CS2041", "3-1194734-5"		
D63978-000	"5-1201560-8", "FLDWC0311-18-0CS3134"		
CF9568-000	"EPD24187D-US"		
449781K001	"5-1193378-1"		
CU4073-000	"EPD100167 A-US"		

C344183001	"2-1201336-4", "44A0111-14-0CK0001"		
849887-000	"44A9681-22-0/9-9CS2748", "8-1196626-8"		
EG6951-000	"FLDWC0311-14-0-L039"		
358485K001	"1192690-6"		
154567-000	"3-1191116-9", "EPD-MPP-10046"		
772290-000	"5-1196015-7", "EPD23074A"		
A66991-000	"9-1200697-0", "EPD92952B-US"		
CU6841-000	"EPD-DND-21541-L016"		
956373-000	"44AM1121-26-0/2-93CS765", "1-1197404-7"		
265095-000	"6-1191953-2", "44A0811-12-0-US"		
CB7176-000			
E95721-000	"1200163-7", "EPD-RWC-16775"		
D21520K001	"7-1201041-0"		
CU4070-000			
E78744-000	"3-1202129-2", "EPD37262A-US"		
398841K001	"7-1192990-2"		
384387-000			
037259K001	"9-1190287-4"		
C63265-000	"1201886-6", "44A0114-26-0-L095"		

306409-000	"1-1192321-1", "44AM1141-20-0/2/5/9-9"		
258225-000	"4-1191889-9", "44A7690-22-0CS2231"		
269251K001	"2-1191987-1"		
777731-000	"44A0111-20-0CS448", "1-1196054-5"		
425663K001	"1193204-8"		
EH8648-000	"400R0311-24-0"		
105721K001	"6-1190772-0"		
196841-000	"1-1191427-7", "44AM1121-20-0/9-9CS262"		
593164-000			
C66149K001	"8-1201379-1"		
376323-000	"6-1202086-9", "44A1141-18-0/2/4/6-9-US"		
E43326-000	"3-1201411-7", "FLDWC0311-14-0CS2979"		
CZ7352-000	"345M09B-22-28-0CS2041"		
473787-000	"44AM1131-22-0/2/8-9CS356", "5-1193549-6"		
944051-000	"9-1197307-6"		
3822433012	"8-1192858-1", "44A1121-24-0/9-9"		
974583K001	"6-1197531-1"		
384991-000	"1192889-1", "44A1141-16-0/2/6/9-9-MX"		

CV7303-000	"EPD-RWC-23716"		
282095-000	"7-1192103-3", "44A0211-22-0-MX"		
EG8347-000			
619543-000	"44AM1111-16-09-9", "3-1194894-2"		
EG8836-000	"400R1121-24-0/9-9"		
CP2438-000			
497657K001	"1193721-3"		
917825-000	"44A0114-26-09", "6-1197123-2"		
100759K001	"8-1190737-1"		
286921K002	"1-1192173-3"		
487807K001	"1-1193650-0"		
CA7737-000			
CU2243-000			
282949-000			
383384-000	"5-1192874-9", "44A1131-22-0/2/9-92"		
572169K001	"8-1194541-8"		
CU8793-000			
CF0991-000	"ATFC0411-18-0"		
E25700K001	"1-1199868-1"		
530457-000	"44AM1151-16-F913-9", "5-1194166-1"		
CN8273-000			
306000-000	"8-1192316-9", "44AM1121-12-0/9-9"		
376588-000			

378962-000	"3-1192835-9", "44A1131-20-0/2/9-3"		
636163-000	"9-1195029-9", "EPD52207A-CS2834"		
CB7181-000			
743853-000	"2-1195803-0", "EPD-RWC-11424"		
361112K001	"1-1200999-6"		
EH8640-000	"400R0311-16-0"		
CY1455-000	"EPD-DND-21461"		
761815-000	"8-1195932-8", "EPD52966A"		
283859-000	"7-1192143-8", "44A0111-20-09-US"		
CN6849-000			
762819-000	"1195940-1", "EPD-RWC-14218"		
EG6829-000	"EPD62288A-US-L077"		
393539K001	"5-1192952-1"		
EP7725-000	"CEC-RWC-25683-L009"		
124519-000	"3-1190905-2", "FB-44-3824-0001"		
287267-000	"8-1192176-2", "44A0111-12-04"		
649713-000	"1-1195128-8", "FLDWC0311-20-0"		
185849K001	"7-1191349-2"		

775503-000	"44A1222-16-0/9-9", "5-1196038-7"		
EG4281-000	"EPD91514A-US-L012"		
CW5804-000			
CA4481-000	"FB-44-4624-0201CS3186", "2-1899114-4"		
838039-000	"4-1196540-9", "FB-44-7026A-0208CS896"		
EK9401-000			
CB7182-000	"EPD-RWC-19939"		
723615K001	"9-1195656-3"		
526689K001	"8-1194138-5"		
EG8792-000	"400R0111-16-0"		
CU1804-000			
282093-000	"4-1192103-9", "44A0211-20-0-MX"		
477029K001	"7-1193572-7"		
D54108-000	"9-1200481-7", "FLDWC0311-16-0CS2979"		
606171-000	"44A9615-26-0/9CS910", "6-1194795-8"		
803523-000	"345M18B-18-72-0CS2041", "9-1196211-2"		
030610K001	"2-1197971-2"		
374902-000	"4-1192808-4"		
182003K001	"5-1191322-5"		

CX2625-000	"EPD-RWC-21527CS3092"		
968287-001	"3-1197486-5", "EPD5841-20-0CS1898"		
945331-000	"3-1197316-6", "EPD-ROC-10047"		
455645-000	"1-1193420-4", "EPD40799A"		
CS7776-000	"EPD-DND-21536-L099"		
CJ6172-000	"EPD52946A-CS2979", "4-1899297-3"		
CB8373-000			
312865-000	"8-1192366-1", "EPD52973A"		
907168K001	"7-1199500-8"		
461189K001	"1-1193459-8"		
631171-000	"6-1194994-3", "EPD-RWC-15752"		
285187-000	"6-1192156-2", "81044/12-12-0"		
630893-000	"6-1194992-8", "EPD-RWC-10946"		
D36727-000	"1201138-7", "EPD100539 A-ISR-L099"		
CU8712-000	"EPD-DND-21489-L281"		
441491-000	"6-1193319-9", "EPD50965A"		
CA8118-000			
D63862-000	"EPD8780B-US"		

791423K001	"7-1196129-6"		
EM9813-000	"400R1141-18-0/2/4/9-0"		
543641K001	"7-1194264-6"		
383302-000	"5-1192873-8", "44A1121-20-0/9-90"		
265117-000	"4-1191954-3", "44A0811-18-0-MX"		
013021K001	"1-1190102-6"		
CS1898-000			
861311K001	"2-1196710-1"		
282439-000	"7-1192116-8", "44A0211-14-0"		
103235K001	"2-1190755-6"		
CW5807-000	"EPD108228 A-US"		
502363-000	"345M06B-22-14-0CS2041", "9-1193771-2"		
A09640K001			
799049-000	"1196178-1", "FLDWC0311-18-0"		
497661-000	"44AM1111-16-04-9", "1193721-5"		
556432K001	"1-1198255-6"		
215193-000	"3-1191554-1", "CSC-0189-20-0CS2439"		
661383-000	"44AM1121-24-0/2-9CS356", "8-1195213-0"		
293169-000	"2-1192222-3", "44AM1121-20-0/4-9CS356"		

031791-000	"5-1190246-6", "44AM4121-24-0/9-0"		
CR2144-000	"44A1121-26-0/9-0-US"		
850191-000	"1196629-2", "EPD47443A-US"		
CB5749-000	"44A1171-22-0/2/4/5/6/8/9-9"		
859843K001	"8-1196699-8"		
563927-000	"1-1194455-5", "EPD44227A"		
284038-000	"7-1192145-6", "44A0111-16-09"		
CY1334-000			
CU2615-000	"EPD-DND-21443-L016"		
232257K001	"2-1191706-0"		
EG5593-000	"44A1221-16-0/2-9CS3030"		
092121F001	"2-1190675-7"		
A39338K001	"4-1201652-5"		
D93014K001	"6-1199862-5"		
707893K001	"9-1195548-0"		
792090-000	"2-1196134-0", "44A0111-10-0-MX"		
197719K001	"1191433-4"		
215441-000	"9-1191555-8", "44AM1121-20-0/9-9F970"		
882541K001	"6-1196869-2"		
CN3400-000			

170841K001	"2-1191243-6"		
501955-000	"44A1121-24-0/09-0", "2-1193752-5"		
CU6275-000	"EPD-DND-21491-L016"		
CA2666-000			
711080-000	"9-1199176-0", "FLDWC0311-12-0CS2722"		
C27459-000	"4-1201390-1", "44AM1121-18-0/6-6"		
053255-000	"7-1190406-1", "EPD-ROK-10324"		
A24414-000	"3-1202118-0", "44A1121-18-0/2-0-L050"		
CF5444-000			
084557-000	"6-1190624-2", "FLDWC0311-16-0"		
D70969K001	"1-1200944-5"		
690777K001	"8-1195423-9"		
CS4978-000	"44A1821-18-0/9-6-1KF/1"		
365935-000	"8-1192743-0", "EPD52247A-X-0"		
847759-000	"44A0211-22-0-1KF/1", "8-1196611-4"		
557064-000	"44A0331-20-0/2/9CS2747", "6-1200248-2"		
CS6952-000	"EPD-DND-21459-L099"		
CN5900-000			
CZ0152-000	"EPD-DND-21490"		

329957K001	"7-1192493-6"		
992065K001	"8-1197673-2"		
382468-000	"8-1192863-7", "44A1141-22-0/2/5/9-9-MX"		
EH9625-000	"EPD-RWC-24409-L172"		
825653-000	"3-1196449-5", "EPD-ROK-10332"		
CX8421-000			
CN6736-000			
CV7400-000			
EG8814-000	"400R1111-20-0-9"		
D522093001	"2-1201229-1", "44A0121-20-0/9CK0001"		
584675K001	"9-1194629-6"		
940287K001	"1-1197281-7"		
CU1225-000	"EPD-DND-21441-L016"		
929925-001	"2-1197209-2"		
400298-000	"6-1199499-4", "EPD-NAV-85411"		
0110183001	"3-1198931-2", "44A1121-22-0/9-9CK0001"		
927579K001	"1-1197193-4"		
EG9472-000	"EPD97611A-US"		
329081-000	"2-1192488-8", "EPD-RWC-14795CS2836"		
589024-000	"44B1121-24-0/9-97", "9-1194660-0"		

CA9991-000			
627745-000	"44AM1131-20-0/2/9-9CS356", "6-1194970-0"		
774837-000	"6-1196033-7", "FB-44-7026A-0203CS896"		
799405-000	"5-1196180-3", "EPD-RWC-15755"		
193281-000	"2-1191402-2", "44A9087-16-0/2/9/90"		
EL5755-000			
285720-000	"9-1192160-8", "44A0111-16-06"		
F95364-000	"2-1201884-4", "44A0112-12-0-L095"		
CS2153-000	"44A4131-20-F862-8"		
926203K001	"4-1197183-6"		
986573K001	"8-1197870-3"		
431665K001	"5-1193246-9"		
CY8601-000	"EPD-DND-23390"		
538811K001	"5-1194228-5"		
297515K001	"3-1192253-0"		
831121-000	"8-1196489-3", "EPD51025A-22-0"		
CU6637-000			
CX5539-000	"EPD-RWC-20307-L295"		
405201-000	"1-1193058-0", "EPD-RWC-10945"		

383342-000	"1192874-3", "44A1121-22- 0/9-91"		
984777K001	"5-1197607- 8"		
948603K001	"5-1197339- 2"		
CW5806-000			
EM5049-000	"44A0111-18- 0-E626"		
372677-000	"2-1192791- 7", "EPD51039A- 18-0"		
768428-001	"1-1195988- 9", "FB-44- 7026A- 0237CS896"		
373451-000	"2-1192797- 8", "EPD48810B- 24-0"		
CU0899-000	"EPD-DND- 21536-L016"		
CN5816-000			
517051-000	"9-1194059- 2", "EPD52666A "		
115547K001	"1190842-8"		
CF9567-000			
283805-000	"8-1192142- 4", "44A0111-22- 09-US"		
CP0664-000	"FB-RWC- 20698CS2198 "		
833721-000	"ATFC0311- 20-0", "1642385-9"		
382312-009	"1-1192861- 9", "44A0121- 24-0/9-MX"		
382243-015	"6-1192858- 9", "44A1121- 24-0/9-9-MX"		
3823063009	"6-1192860- 1", "44A1121- 16-0/9-9"		

CA7752-000			
D87301-000	"EPD-RWC-19899"		
992846K001	"9-1198925-2"		
795849K001	"1-1196161-4"		
412820-000	"9-1200140-7", "EPD-PFM-10059CS2974"		
A24367-000	"5-1200552-2", "FLDWC1321-16-0/9-9CS3050"		
CF3334-000	"EPD-RWC-17594", "1899210-8"		
CS7773-000			
ER1058-000	"EPD-RWC-17612CS3523"		
705993K001	"5-1195536-2"		
C71351-000	"9-1201884-7", "44A0114-22-0-L095-US"		
300713K001	"6-1192277-4"		
382562-000	"3-1192865-4", "44A0131-20-0/2/9-MX"		
112795K001	"9-1190822-6"		
386996-000	"5-1192902-9", "44A1121-24-0/2-3-US"		
CN2631-000			
EJ1842-000	"44A9676-18-0/2/9-9CS3433"		
A72375-000	"8-1201429-7", "81044/12-16-0CS3005"		

085797-000	"2-1190633-6", "44B1121-24-0/9-90"		
CX8472-000			
441169K001	"4-1193317-1"		
082747-000	"4-1190612-9", "345M09J-22-14-0CS2041"		
549077-000	"44AM4121-26-0/6-9", "1194321-3"		
071841K001	"2-1190539-4"		
049131-000	"8-1190376-3", "44AM1131-20-0/1/9-9CS1702"		
A10949-000	"4-1201250-0", "ATFB6000-22-0"		
759504-000	"1200082-6", "81044/12-22-0CS3005"		
888777K001	"4-1196914-1"		
745434-000	"44A0111-26-0CS2896", "5-1199422-8"		
384174-000	"1-1197969-0", "44A1141-18-0/2/5/9-9-US"		
CL6051-000			
382778-000	"7-1200383-2", "44A1141-16-0/2/5/9-9-US"		
CU5129-000	"EPD-DND-22683-L016"		
F45850-000	"EPD48804B-US-CS2979", "8-1200205-0"		
382687-000	"6-1192866-9", "44A1221-16-0/9-9"		

EG4559-000	"EPD-DND-21445-L016"		
438999-000	"1193299-9", "44A0121-20-0/9CS356"		
383486-000	"5-1192875-0", "44A1121-20-0/9-94"		
315922K001	"1-1199947-3"		
EG8790-000	"400R0111-14-0"		
CR7938-000	"EPD-RWC-22367"		
513665-001	"8-1194035-1", "EPD5845-20-0CS1898"		
C24053-000	"9-1201422-7", "FLDWC0311-22-0CS2979-1KF"		
766667-000	"44A0111-12-0CS448", "1-1195975-6"		
CP3494-000			
838654K001	"1-1200162-0"		
EK9473-000	"EPD-RWC-24328"		
CB6786-000	"EPD52974A-CS2979", "1899181-6"		
931033-000	"345/41B-22-14-0CS1913", "9-1197216-0"		
C46893-000	"44A0141-12-0/2/5/9", "7-1200388-8"		
815239-000	"44A0111-14-02", "6-1196353-1"		
EG3892-000			
384327-000	"8-1192883-7", "44A0121-26-0/4-US"		

374315-000	"7-1200383-3", "44A1141-12-0/2/5/9-9-US"		
382384-000	"6-1192862-1", "44A0131-20-0/1/9"		
D53517-000	"3-1201047-0", "WXA-0101-18-0CS3089"		
EK8652-000	"44A1221-12-0/9-9-L386"		
145499-000	"2-1191051-6", "EPD25501A"		
CY1329-000			
CA8019-000	"EPD98901A-US"		
A86970-000	"44AM4121-16-0/09-9CS356", "5-1200705-6"		
EH2499-000	"44A9632-16-0/9-9CS3433"		
306344-000	"4-1192320-1", "44AM1131-22-0/5/9-9"		
354418-000	"4-1201422-2", "44A0341-20-0/2/6/9-US"		
887483K001	"8-1196904-4"		
202373K001	"2-1191467-3"		
913507-000	"44AM4144-26-ELC4-0CS2238", "2-1197093-8"		
382373-000	"3-1192862-3", "44A1221-18-0/9-9"		
523505-000	"44AM1121-22-0/5-9CS356", "8-1194112-0"		

382588-000	"7-1192865-2", "44A7429-X-0"		
CR2192-000			
CX8741-000			
612213-000	"44AM1131-16-0/1/9-9CS1702", "5-1194840-7"		
EH2546-000	"44A9675-18-0/9-9CS3433"		
EM9115-000	"400R1161-20-0/2/3/5/6/9-9"		
CY8607-000	"EPD-DND-23491"		
250094-000	"5-1201055-9", "EPD-ROK-10511"		
702946K001	"1-1198263-2"		
629647-000	"44AM1141-22-ELC4-9CS356", "7-1194983-2"		
382564-000	"3-1192865-9", "44A0121-26-0/3-US"		
940101-000	"7-1197279-5", "EPD43499D"		
F42629-000	"EPD20460B-US"		
994039-000	"44AM1131-16-0/09/92-9", "1197689-6"		
CA8212-000			
CP1215-000	"44A0112-18-0CS3184"		
549243K001	"1-1194322-5"		
F51311-000	"1201416-2", "44A0111-16-0-BRL-L117"		
CM3224-000	"81044/12-18-0CS3005", "4-1899407-0"		

EG8798-000	"400R0111-22-0"		
344075K001	"6-1192591-1"		
688995-000	"2-1195411-5"		
CU9610-000	"EPD-DND-21486-L016"		
CY2164-000			
257511K001	"3-1191884-9"		
114167K001	"4-1190832-6"		
954573-000	"44A9677-22-ELC4-9CS2746", "8-1197390-2"		
265792-000	"2-1191962-8", "81044/9-12-0"		
CL6987-000	"EPD-RWC-18211CS3251"		
383097-002	"2-1192871-8", "44A0121-22-0/2-MX"		
170621-000	"6-1191241-2", "44A1221-14-0/9-9"		
CR9946-000			
331173K001	"2-1192502-9"		
306303-000	"9-1192319-3", "44AM1131-16-0/2/9-9"		
EP7724-000			
421569-000	"5-1193175-3", "44A9665-14-0/2/5/9-0"		
711102-000	"44B1121-24-0/9-96CS2024", "4-1195571-7"		
623845-000	"1194932-7", "FB-44-1424-0002"		

757013-000	"10474-X-8CS791", "1-1195899-6"		
593786-000	"44AM1141-12-G048-9CS561", "5-1199150-0"		
909487-000	"345/92-20-4-0CS2026", "6-1197064-1"		
733407-000	"4-1195728-4", "EPD-RWC-13644"		
514977-000	"1-1194045-3", "CMC-0009-22-0"		
341791-000	"1-1192577-7", "WXA-0165-20-0"		
C63237-000	"6-1201860-2", "EPD101772 A-US"		
CX1592-000	"EPD-DND-21443"		
CU9606-000	"EPD-DND-21452-L016"		
EG8828-000	"400R1121-16-0/9-9"		
120375K001	"6-1190875-8"		
886634-000	"EPD-NAV-85111"		
274705K001	"7-1192034-8"		
361962-000	"8-1198733-2", "44A0211-16-0-1KF/1"		
629721-000	"44A1131-22-0/9/9-9", "2-1194984-6"		
376589-000			
115383-000	"8-1190840-4", "44A9647-12-0"		
628073K001	"6-1194972-9"		
EH2583-000	"44A9682-22-0/2/9-9CS3433"		

620637-000	"2-1194904-8", "EPD-RWC-15358"		
EG6691-000	"FLDWD0311-12-0CS3422"		
306252-001	"2-1192319-5", "44AM1121-24-0/2-9"		
401913-000	"3-1193034-6", "WXA-0085-18-0"		
CF1793-000			
336963K001	"1-1192544-7"		
518475K001	"6-1194069-1"		
427781K001	"6-1193218-8"		
500045K001	"1-1193738-2"		
EF7912-000			
589641-000	"2-1194665-8", "EPD51482A-18-0"		
CX8476-000			
427575K001	"1-1193217-2"		
A31681-000	"7-1201447-1", "EPD100916A-US-L099"		
EM8414-000	"44A0114-22-0"		
CY1454-000			
904921K001	"1197032-4"		
845419K001	"1-1196595-4"		
EG8810-000	"400R1111-16-0-9"		
175889K001	"8-1191278-5"		
357423K001	"9-1192681-3"		

260787K001	"8-1191907-4"		
A02792K001	"5-1200287-1"		
EG8794-000	"400R0111-18-0"		
805974-000	"2-1199501-2", "EPD-NAV-79418"		
463793K001	"9-1193477-9"		
CS1913-000			
EH2534-000			
360397-000	"6-1192703-6", "ATFC0611-21-0"		
061267K001	"8-1190463-3"		
314553-000	"7-1192380-6", "EPD40804A"		
374402-000	"2-1192804-7", "44A0141-24-0/2/6/9"		
384223-000	"6-1192882-2", "44A0121-22-0/5-MX"		
3831593001	"1-1192872-0", "44A0221-16-0/9"		
538059-000	"44AM1141-20-ELC4-9CS356", "1-1194223-0"		
383090-000	"1192871-7", "44A1131-24-0/2/6-9"		
C38469K001	"6-1201280-4"		
186315K001	"1191353-3"		
221055-000	"5-1191629-5", "EPD4626F"		
376139-000	"4-1192817-5", "44A1131-22-0/2/6-9-MX"		

004999-000	"2-1190038-5", "345M12B-26-48-0CS2041"		
818063K001	"1196376-1"		
218242-000	"3-1201226-8", "FLDWC0311-12-0CS2979"		
550851K001	"2-1194348-1"		
741599-000	"44AM1841-10-0/2/5/9-1", "6-1195787-7"		
973679K001	"2-1197525-9"		
2820933002	"5-1192103-1", "44A0211-20-0"		
383760-002	"7-1192877-6", "44A0121-24-0/2-MX"		
028127-000	"9-1190217-6", "EPD50847A-22-0"		
282092-000	"4-1192103-3", "44A0114-24-0"		
E60866K001	"8-1200594-3"		
407261K001	"2-1197900-4"		
CJ3634-000	"FLDWD0311-10-0CS2736"		
EG8842-000	"400R1131-12-0/6/9-9"		
CL5548-000	"44A1161-22-0/1/2/3/4/9-9"		
CX8618-000			
282040-015	"9-1192097-8", "44A0111-24-0-MX"		
842992-000	"7-1196575-3", "EPD23066B-US"		

844935-000	"7-1196591-6", "FB-44-7026A-0230CS896"		
046073-000	"1190354-2", "EPD43503E-US"		
475047-000	"44A9663-12-0-0", "5-1193558-3"		
875362K001	"6-1199485-6"		
580800-000	"5-1198989-9", "EPD-ROK-10492"		
CF1043-000			
E60829-000	"8-1200690-9", "EPD-RWC-10937-L091"		
884565-000	"1-1196884-2", "EPD-ROK-10045"		
EM7724-000			
306876-000	"6-1192324-3", "44AM4121-22-0/9-9"		
027819K001	"2-1190215-5"		
D50704K001	"8-1201420-8"		
729405-000	"7-1195698-6", "EPD6207-26-0/9-9CS2315"		
C36892-000	"4-1200384-3", "EPD-RWC-17036"		
E70833K001	"7-1201056-4"		
225971K001	"2-1191664-0"		
282504-000			
E13427-000	"8-1200586-8", "EPD91157L-US"		

459668-001	"10515-X-8CS1285", "9-1193447-1"		
222989K001	"9-1191642-8"		
412421K001	"4-1193110-5"		
382432-011	"3-1192863-2", "44A1121-18-0/9-9-MX"		
A94684-000	"5-1201860-9", "EPD101677 A-US"		
186426-000	"5-1198248-9", "WXA-0165-18-0"		
CR0560-000	"44A1121-22-0/8-9-MX"		
C04002-000	"8-1201447-3", "EPD100897 A-US-L099"		
D18740-000	"EPD5846"		
A55314-000	"5-1200290-5", "FLDWC0311-22-0CS2979"		
A21717-000	"1-1200691-0", "EPD-RWC-10937-L088"		
761279K001	"2-1195929-1"		
932097-000	"44A9089-16-0/9-9CS2514", "7-1197224-9"		
349458-000	"4-1192629-2", "44B1121-24-0/9-94CS2024"		
181165K001	"4-1191316-5"		
736875K001	"6-1195753-4"		
EF5948-000	"EPD-RWC-23972"		
CN8003-000			

466063-000	"1193494-6", "EPD-RWC-15757"		
690011-000	"4-1195418-7", "FLDWC0311-18-0CS2722"		
CU3941-000	"EPD21826G-L099"		
CB8620-000	"EPD-RWC-20309CS3092"		
692117-000	"6-1195433-7", "EPD-RWC-14214"		
711585-000	"7-1195574-0", "EPD86151A"		
D63549K001	"8-1201179-9"		
CB4688-000	"EPD-RWC-18278CS3085"		
CP6419-000			
CU3937-000	"EPD21832F-L099"		
D44855-000	"4-1201038-0", "EPD-RWC-10950-L103"		
666253-000	"10473-X-8CS791", "7-1195248-2"		
CS7765-000			
BM9086-000	"44A1221-16-0/9-9CS3432"		
CA8131-000	"44A0112-20-0CS3184"		
EG8834-000	"400R1121-22-0/9-9"		
793509-000	"44A0121-22-0/8CS356", "9-1196143-8"		
261170-000	"1-1191911-2", "44A0111-18-06-US"		

730639-000	"8-1195707-4", "44A1121-16-0/9-9CS406"		
CX2059-000			
442469-000	"3-1193326-3", "44A9647-16-0"		
445158-000	"10515-X-8", "5-1193345-8"		
CN5813-000			
D76778K001	"7-1200402-8"		
732363-000	"9-1195720-1", "EPD-ROC-10043"		
973699-000	"44A9605-16-0", "4-1197525-2"		
201363-000	"7-1191459-0", "EPD60303B-US"		
CB3118-000			
358907K001	"1-1192693-2"		
EM0484-000			
237287-000	"5-1191744-2", "EPD64091A"		
382306-011	"5-1192860-5", "44A1121-16-0/9-9-MX"		
223465K001	"3-1191646-3"		
383027-000	"3-1192870-5", "44A0131-24-0/2/9"		
CR3898-000			
551885K001	"2-1194362-0"		
CA3513-000			
405994-000	"5-1193063-4", "44A7425-12-0CS289"		

072567K001	"8-1190543-2"		
282236-000	"3-1192109-9"		
005879K001	"9-1190044-0"		
955995-000	"44A9663-14-0-0", "5-1197401-2"		
515031K001	"4-1194045-7"		
705449-000	"44B1121-24-0/9-97CS2024", "5-1195532-4"		
285070-000	"5-1192155-3", "81044/13-24-0"		
648571-000	"8-1195119-1", "EPD-RWC-12359"		
CA8125-000	"44A0112-16-0CS3184"		
531447-000	"5-1194173-0", "EPD-CAN-10067"		
810826K001	"2-1199501-3"		
240718-000	"5-1191768-5", "EPD4745F"		
139409K002	"1191011-3"		
086505K001	"2-1190638-3"		
853219-000	"9-1196650-1", "EPD52967A"		
923133-000	"44A9666-14-0/9", "9-1197161-7"		
611386-000	"44B1121-16-0/9-90CS2025", "4-1194834-9"		
CN6739-000			

632565K001	"7-1195004-0"		
119836K001	"4-1197957-2"		
CN6740-000			
382309-022	"8-1192860-2", "44A1131-22-0/2/9-9-MX"		
306144-001	"3-1192318-2", "44AM1121-22-0/9-9"		
CF9775-000	"44A4201-22-A048-0"		
EG9416-000			
EG3893-000			
940205-000	"44A7714-22-0CS2230", "5-1197280-5"		
653936-001	"44AM4121-20-0/1-9CS356", "9-1195159-7"		
743447-000	"345M18B-18-21-0CS2041", "5-1195800-2"		
367886-000	"5-1199499-8", "EPD-NAV-88409"		
595493K001	"1-1194709-9"		
427875K001	"3-1193219-2"		
999214-000	"44A0122-22-0/9", "8-1201014-7"		
116717K001	"4-1190850-2"		
CR9271-000	"81044/12-16-0-BARREL"		
452321K002	"4-1193396-4"		
868149-000	"5-1196758-1", "EPD-RWC-14875"		
955205K001	"3-1197395-5"		

409980-000	"4-1198115-0", "44AM1122-22-0/9-9-5CF/1"		
027877K001	"7-1190215-7"		
346817-000	"8-1192610-4", "EPD40416A-US"		
D26779-000	"44AM1121-18-0/9-9CS561", "2-1200554-8"		
674939-000	"3-1195308-7", "FB-44-7026A-0224CS896"		
258985K001	"8-1191894-1"		
465415-000	"44A7669-20-8", "6-1193489-3"		
C36664-000	"8-1201426-2", "EPD-RWC-18834-L099"		
148145K001	"7-1191070-6"		
772117-001	"4-1196014-2", "FB-44-7026A-0236CS896"		
955061K001	"1-1197394-4"		
EK9400-000	"EPD-RWC-24330"		
084047-000	"1-1190621-4", "EPD43498B-US"		
397241-000	"345M05B-20-12-0CS2041", "3-1192979-3"		
A89505-000	"4-1201420-6", "EPD-IRL-35503"		
577371K001	"9-1194579-7"		

058007K001	"4-1190440-4"		
664189-000	"3-1195234-3", "EPD-RWC-13950"		
499253K001	"4-1193732-0"		
389852-000	"4-1192926-6", "44A3131-18-0/2/9"		
529385-000	"5-1194157-7", "EPD-RWC-15745"		
A82639K001	"7-1200803-2"		
383093-000	"1-1192871-1", "44A0121-12-0/9-US"		
668847K001	"6-1195266-1"		
CU8802-000	"EPD-DND-23034-L146"		
183802K001	"8-1199199-7"		
467767-000	"1193506-6", "FLDWC0311-14-0"		
902115K001	"4-1197011-6"		
300253-000	"5-1192274-0", "44AM1131-20-0/1/9-9"		
371177K001	"5-1192780-0"		
306398-000	"8-1200875-0", "44AM1141-16-0/2/5/9-9"		
EG6687-000	"FLDWC0311-14-0CS3422"		
150441K001	"7-1191087-8"		
525444-000	"44B1121-24-0/9-92CS2024", "4-1194129-6"		
195008K001	"5-1199869-0"		

799237K001	"3-1196179- 2"		
734903K001	"5-1195739- 9"		

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.