



19-Jan-2022

PCN #: P-22-022025

Subject : Spec 44 and FLDW Wires

Description of Change : TE Connectivity was informed by one of its material supplier on a consolidation in their manufacturing plant for PVDF based Color Concentrates (CC). TE Wire and Cable plants in Tijuana and Redwood City use PVDF CCs as colorant for outer insulation layer in spec 44 and FLDW primary wires. TE has evaluated the PVDF CCs from the supplier's new manufacturing location and no change to Form, Fit and Function of finished parts has been observed.

Reason : Part status change. TE was notified by its material supplier that except for Black PVDF CC, no change has been made in material formulation and recipe for PVDF CCs produced from their new manufacturing site. Due to health and safety policy of vendor's new manufacturing site with respect to handling raw carbon black pigments, this CC has undergone a change of one raw material component. TE evaluated these changes on the key characteristics of the CCs and the finished goods and no impact on the properties and performance of finished parts has been observed. Test reports on the wire characteristics can be provided upon request. In addition to the evaluation conducted by TE, FAIs will be performed on the first manufactured primary wire lot per each gauge for validation.

Key Dates :

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
382403-000	"9-1192862-5", "44A1121-22-0/9-0"		
D13017-000	"44A0111-10-9CS2979", "7-1199808-7"		
CU6479-000			
710683K001	"1-1195568-6"		
A94684-000	"5-1201860-9", "EPD101677 A-US"		

756043-000	"44A1221-16-0/9-9-1KF/1", "3-1195892-8"		
209185-000	"1191516-5", "EPD-RWC-14919"		
922243K001	"5-1197155-0"		
635299-000	"44B9535-22-9/96-9CS1728", "4-1195023-5"		
015447K001	"3-1190121-3"		
094005-000	"2-1190689-8", "EPD-RWC-14215"		
746493-001	"5-1195823-7", "FB-44-7026A-0235CS896"		
301169-000	"5-1192281-3", "44AM1114-20-9-9"		
208086K001	"7-1200625-6"		
270561-000	"9-1192001-0", "44AM1121-26-9/91-9"		
900874-000	"44A0131-26-3/6/9", "4-1197002-3"		
559387K001	"5-1194415-6"		
EM0387-000	"EPD-RWC-22228-L016"		
442585K001	"2-1193327-0"		
382765-000	"6-1192867-0", "44A1121-18-0/9-0-MX"		
383346-000	"2-1192874-0", "44A1121-22-0/9-97"		
775503-000	"44A1222-16-0/9-9", "5-1196038-7"		

722481-000	"7-1195648-5", "EPD-ADD-10088"		
207323-000	"7-1191502-2", "EPD-RWC-16009"		
EP1359-000	"EPD-RWC-25207"		
732517-000	"44A7620-16-9/5-9", "1-1195722-7"		
195289-000	"5-1191416-0", "EPD52743A-18-0"		
285788-000	"4-1192163-4", "44A0111-26-93-US"		
666477-000	"2-1195250-3", "WXA-0085-14-9"		
D64188-000	"44/7004-16-9CS1059-L026", "1200696-9"		
CS7643-000	"EPD-RWC-22228-L099"		
066621K001	"5-1190502-0"		
840544-000	"8-1196557-6", "EPD8494C"		
CS7486-000	"EPD-DND-21451-L099"		
115113-000	"9-1190838-7", "EPD52598A-26-0"		
D72808-000	"1-1201706-4", "44A0111-12-9-2CS3144"		
053255-000	"7-1190406-1", "EPD-ROK-10324"		
C21680-000	"2-1201124-5", "EPD-IRL-18306"		

384382-000	"3-1192884-7", "44A0121-26-2/9-US"		
CZ7611-000	"EPD-RWC-22228"		
394383K001	"7-1192958-1"		
529385-000	"5-1194157-7", "EPD-RWC-15745"		
329957K001	"7-1192493-6"		
CN9341-000	"FLDWC0311-16-9CS2979"		
829069-000	"44A9416-18-9CS1981", "7-1196473-7"		
668847K001	"6-1195266-1"		
825653-000	"3-1196449-5", "EPD-ROK-10332"		
CA2184-000			
C30207-000	"8-1201342-0", "FLDWC6004-14-9CS2722"		
CS2807-000	"EPD-RWC-21804"		
168351K001	"8-1191225-5"		
840613K001	"4-1196558-8"		
160546K001	"5-1198264-4"		
495277-000	"44A0111-22-9(FS)", "1-1197968-0"		
F95835-000	"EPD-RWC-17035", "6-1200287-6"		
241755K001	"1191776-9"		
738325K001	"7-1195763-9"		
383066-000	"7-1192870-4", "44A1121-22-2/9-9-MX"		

258913-000	"3-1191894-8", "EPD-ADD-10013"		
141121K001	"9-1191022-8"		
747187K001	"1195829-3"		
387036-000	"3-1192904-3", "44A1211-22-9-9-US"		
383467-000	"2-1192875-2", "44A1141-18-9/93/95/96-9"		
026251-000	"8-1190203-1", "EPD-ADD-10086"		
A02792K001	"5-1200287-1"		
573626-000	"7-1198907-2", "FLDWC1341-20-F019-9CS2959"		
386921-000	"44A0121-22-9/98"		
940205-000	"44A7714-22-0CS2230", "5-1197280-5"		
384174-000	"1-1197969-0", "44A1141-18-0/2/5/9-9-US"		
563927-000	"1-1194455-5", "EPD44227A"		
119289-000	"9-1190867-0", "EPD51028A-26-0"		
485584-000	"345/46B-22-48-0CS1913", "8-1193633-2"		
331173K001	"2-1192502-9"		
282096-000	"7-1192103-9", "44A0211-22-9-MX"		
320693K001	"2-1192431-5"		

282763-000	"4-1192125-9", "44A0111-22-917-US"		
CL6864-000	"EPD-RWC-20849"		
818647K001	"9-1196379-3"		
514977-000	"1-1194045-3", "CMC-0009-22-0"		
182003K001	"5-1191322-5"		
225927K001	"8-1191663-9"		
383159-000			
732363-000	"9-1195720-1", "EPD-ROC-10043"		
546268-000	"5-1199501-4", "EPD-NAV-85413"		
071435-000	"4-1190536-6", "CSC-0002-18-0CS1958"		
425062-001	"9-1193199-6", "FB-44-4624-0209CS1578"		
283242-000	"8-1192133-3", "44A0111-18-906"		
520327-000	"3-1194090-4", "EPD51900A-18-0"		
681412-000	"1195358-3", "FB-44-4026-0047"		
311069-000	"5-1192354-4", "EPD-ADD-10087"		
F37121-000	"44A4121-26-3/9-9", "1-1201058-8"		
609781K001	"9-1194821-3"		
CB7448-000	"44A4231-20-0/2/9-9"		

F63216-000	"44A0124-22-9/6CS2994", "8-1199874-7"		
CX1601-000	"EPD-DND-21667"		
177030-000	"8-1197951-8", "44A1221-16-9/96-9-1KF/1"		
369647-000	"9-1192769-5", "44A2121-26-1/9-9CS006"		
EM5739-000	"44AM4141-12-0/2/5/9-9"		
EM8675-000	"EPD-RWC-24363"		
E28198-000	"1201759-1", "44A0111-12-9-1KF"		
CA8134-000	"44A0112-26-9CS3184"		
469045K001	"3-1193515-7"		
A76985-000	"2-1200577-6", "EPD-RWC-17038"		
515031K001	"4-1194045-7"		
118117K001	"7-1190859-4"		
CB6207-000			
CX1587-000	"EPD-DND-21459"		
CS7766-000	"EPD-DND-21488-L099"		
190839K001	"3-1191384-2"		
EM7714-000			
367886-000	"5-1199499-8", "EPD-NAV-88409"		
376903-000	"7-1192822-7", "44A0121-22-5/95"		
738837K001	"5-1195767-1"		

447253-000	"1-1193361-3", "44A9605-16-95"		
CL6053-000	"EPD-RBS-10075"		
E70943-000	"2-1202115-2", "EPD-RWC-19734"		
377101-000	"1192824-2", "44/2422-24-9/9-9CS1222"		
387301-000	"8-1192907-8", "44A1111-22-9-95"		
566245-001	"44A9439-24-9-9CS527", "8-1194471-4"		
382578-000	"5-1192865-4", "44A2121-22-1/9-9"		
415347-000	"2-1193130-4", "EPD52151A-CS2816"		
260049-000	"6-1191902-7", "EPD51069A-22-0"		
292133-000	"8-1192214-4", "EPD-ROC-10013"		
761815-000	"8-1195932-8", "EPD52966A"		
927579K001	"1-1197193-4"		
EK8980-000	"44A0311-12-9-E634"		
306183-000	"7-1192318-4", "44AM1121-22-2/9-3"		
549243K001	"1-1194322-5"		
151023-000	"8-1191091-7", "44A4124-24-1/9-9CS1086"		

CA1046-000			
375035-000	"6-1192809-6", "44AM1121-22-9/91-9CS1726"		
389525-000	"1192924-3", "44A0121-18-6/9-MX"		
A21717-000	"1-1200691-0", "EPD-RWC-10937-L088"		
645141-000	"44A0212-16-9", "5-1195095-4"		
547231K001	"4-1194308-1"		
CM6020-000			
232433-000	"3-1191707-2", "44A0211-12-9-1KF/1"		
114167K001	"4-1190832-6"		
283878-000	"9-1192143-6", "44A0111-10-9-MX"		
309967-000	"9-1192346-9", "44A0212-14-9"		
107475K002	"2-1190785-5"		
CU0182-000	"EPD-RWC-10937-L016"		
200397-000	"1-1191452-6", "EPD-RWC-14595"		
466063-000	"1193494-6", "EPD-RWC-15757"		
037793-001	"9-1190291-5", "44A2121-22-1/9-9CS006"		
171891-000	"3-1191250-9", "44A1221-14-9/96-9-5CF/1"		

307314-000	"9-1197927-6", "EPD92308A-US"		
CY1866-000	"EPD-RWC-22192-L077"		
CN3176-000			
477029K001	"7-1193572-7"		
833031-000	"44A9677-20-ELC4-9CS2746", "9-1196503-7"		
EH9938-000	"FLDWC1321-20-1/9-8"		
A61710-000	"5-1201196-5", "EPD91412A-US"		
441541-001	"345/37B-22-6-0CS1913", "1193320-1"		
CF4846-000	"44B1122-16-1/9-9CS3223"		
282659-000	"9-1192121-3", "44A0111-22-912-US"		
211271-000	"8-1191530-6", "EPD51361A-CS791"		
CA0945-000			
028127-000	"9-1190217-6", "EPD50847A-22-0"		
680589-000	"1-1195353-7", "EPD-RWC-15759"		
301053-000	"3-1192280-5", "44AM1111-22-9-8"		
CS6952-000	"EPD-DND-21459-L099"		
A23962-000	"8-1200403-9", "EPD96521A-US"		

538601-000	"44A9436-22-9/96CS2312", "9-1194226-5"		
407261K001	"2-1197900-4"		
CS7760-000			
384233-000	"8-1192882-8", "44A0121-22-5/9-US"		
995201K002	"1-1197698-1"		
100759K001	"8-1190737-1"		
E23424-000	"2-1200899-7", "EPD-RWC-18032"		
CA6779-000			
CS2885-000	"44A0311-12-9-F871"		
881397-000	"4-1196861-5", "EPD-CAN-10019"		
CZ4723-000			
424364K001	"1199930-5"		
290023-000	"8-1192198-3", "FB-RWC-11810"		
394497-000	"5-1192959-0", "EPD50500A"		
CS7726-000			
828445-000	"6-1196469-0", "CSC-0218-C-X-0"		
EG9287-000	"EPD-RWC-24142-L012"		
D06718K001	"9-1200523-5"		
346993K001	"1192612-5"		
EG6683-000	"FLDWC0311-16-9CS3422"		
CY1454-000			
C52500K001	"1-1200394-4"		

C13866K001	"6-1200394-9"		
CR6173-000	"44A0131-12-0/2/9-MX"		
387138-000	"8-1192905-8", "44A1311-22-9-9-US"		
204949-000	"2-1191485-4", "EPD-CAN-10021"		
357423K001	"9-1192681-3"		
260787K001	"8-1191907-4"		
579345K001	"1194592-8"		
889351-000	"1196919-9", "EPD52739A-18-0"		
511349-000	"4-1194019-2", "EPD51031A-22-0"		
383239-000	"7-1192872-0", "44A1131-26-3/6/9-9-US"		
CA2940-000			
852077-000	"8-1196642-6", "CTC-0039-22-9/5-93CS1963"		
F97157-000	"44A1221-16-9/9-9CS3030", "9-1200356-3"		
129929-000	"5-1190943-7", "EPD21144B"		
C76437-000	"5-1200403-5", "EPD96520A-US"		
589611K001	"1194665-4"		
061593K001	"1190466-4"		
054867K001	"5-1190418-9"		
455645-000	"1-1193420-4", "EPD40799A"		

CZ4626-000	"EPD-RWC-23583"		
285792-000	"6-1192163-3", "44A0111-26-92-US"		
398057K001	"1-1192985-9"		
117861-000	"9-1190857-6", "44A0211-12-94"		
C63237-000	"6-1201860-2", "EPD101772 A-US"		
EM8467-000	"UB2-26C131BG11-9"		
631171-000	"6-1194994-3", "EPD-RWC-15752"		
651289-000	"3-1195142-7", "EPD52964A"		
CY6749-000	"EPD-DND-21491"		
223465K001	"3-1191646-3"		
587463-000	"4-1194649-5", "EPD-RWC-12372CS2749"		
562235K001	"3-1194442-6"		
820349K001	"6-1196396-0"		
103235K001	"2-1190755-6"		
CA6181-000	"EPD-RWC-20021"		
469091K001	"6-1193515-6"		
658911-000	"6-1195194-2", "CMC-0441-22-6-0"		
376893-000	"7-1192822-2", "44A0121-22-4/94"		

531447-000	"5-1194173-0", "EPD-CAN-10067"		
CA3530-000			
116717K001	"4-1190850-2"		
452321K002	"4-1193396-4"		
548389K001	"3-1194316-9"		
306419-000	"2-1192321-4", "44AM1141-22-2/5/6/9-3"		
CM6022-000	"44A1231-16-9/93/96-9"		
301046-001	"2-1192280-4", "44AM1111-22-9-2"		
CX3824-000			
520978K001	"3-1199499-2"		
360615K001	"1-1192705-0"		
232555-000	"3-1191708-1", "FB-44-7026A-0221CS896"		
641932-000	"44AM1121-22-0/9-94", "4-1195073-2"		
A53192-000	"3-1201700-4", "44AM1111-18-96-9-1KF"		
188077-000	"9-1191364-5", "EPD-RWC-10424-334F"		
306266-001	"4-1192319-8", "44AM1121-26-0/9-9"		
666131-000	"44A0141-26-3/5/6/9", "9-1195247-3"		
747555K001	"7-1195831-9"		

F45837-000	"44A0111-18-950-2KF", "2-1200268-6"		
CU8718-000	"EPD-DND-21508-L177"		
393539K001	"5-1192952-1"		
801430-000	"6-1200230-5", "FB-RWC-17576"		
C04002-000	"8-1201447-3", "EPD100897 A-US-L099"		
D18740-000	"EPD5846"		
387778-000	"3-1192912-8", "44A1111-22-90-9"		
282426-000	"3-1192116-1", "44A0311-16-9-US", "44A0311-16-9-US"		
382122-000	"1-1192857-8", "44A1131-26-0/2/9-9-US"		
124519-000	"3-1190905-2", "FB-44-3824-0001"		
605359-000	"8-1194789-4", "EPD51032A-22-0"		
383602-000	"2-1201189-1", "44A1131-22-2/6/9-9-US"		
559978-001	"44A2111-22-9-9CS011", "5-1194419-6"		
CN1188-000	"44AM1121-18-9/96-9CS3209"		
606739-000	"7-1194799-6", "EPD52597A-26-0"		
344075K001	"6-1192591-1"		

438315K001	"3-1193294-1"		
888492-000	"8-1198850-7", "CMC-0125CS1791"		
350937K001	"7-1192638-2"		
665123K001	"9-1195240-6"		
756875-000	"2-1195898-0", "EPD52212A"		
E89413-000	"1201408-3", "44A0111-18-945-2KF"		
022371K001	"2-1190173-9"		
449607K001	"2-1193377-9"		
523723-000	"5-1194114-2", "44A9118-X-0CS1791"		
287602-000	"1192181-3", "44A0111-22-9-12"		
919647-000	"6-1197136-5", "EPD-RWC-10074"		
589453-000	"9-1194663-2", "EPD-RWC-14225"		
CX8022-000	"FLDWC1331-16-F023-0CS2959"		
795987-000	"44A9586-26-9-5", "8-1196161-7"		
169513K001	"9-1191233-0"		
CU6275-000	"EPD-DND-21491-L016"		
354660-000	"1-1200000-3", "44B1221-22-9/96-925"		
931033-000	"345/41B-22-14-0CS1913", "9-1197216-0"		

285791-000	"5-1192163-8", "44A0111-26-90-US"		
383141-002	"7-1192871-7", "44A4121-18-0/9-9-US"		
163651K001	"9-1191180-9"		
523039K001	"5-1194109-8"		
803021-000	"44A9416-12-9CS1981", "1196208-2"		
416739K001	"5-1193140-7"		
CZ0152-000	"EPD-DND-21490"		
839135-000	"2-1196548-2", "EPD-RWC-12888"		
CP2438-000			
CA4834-000			
306344-000	"4-1192320-1", "44AM1131-22-0/5/9-9"		
D81746-000	"6-1201691-3", "44A0111-10-9-10"		
286921K002	"1-1192173-3"		
444271-000	"8-1193338-4", "44A0111-12-9CS448"		
571493-000	"1-1194532-6", "EPD-RWC-14221"		
487807K001	"1-1193650-0"		
CX8421-000			
D78830K001	"1-1201448-8"		
282757-000	"1-1192125-6", "44A0111-22-95"		

E60829-000	"8-1200690-9", "EPD-RWC-10937-L091"		
CS8379-000	"EPD-DND-21973-L016"		
946583-000	"44A1221-18-9/96-9", "1197325-1"		
856533-000	"44A0321-20-0/9CS2747", "9-1196675-9"		
C36892-000	"4-1200384-3", "EPD-RWC-17036"		
CJ0236-000	"EPD-RWC-16888-L191"		
306193-000	"8-1192318-7", "44AM1121-22-9/96-3"		
D04838-000	"9-1200552-4", "FLDWC1331-20-ELC3-9CS3050"		
282767-002	"6-1192125-6", "44A0111-22-927"		
A31681-000	"7-1201447-1", "EPD100916 A-US-L099"		
282654-000	"5-1192121-9", "44A0111-22-904"		
E14638-000	"8-1200625-9", "EPD-RWC-17889"		
EG3617-000	"EPD-RYQ-23616-L333"		
321219K001	"3-1192434-8"		
330299-000	"9-1192495-8", "44/7004-24-9CS1059"		
463793K001	"9-1193477-9"		

390845-000	"4-1192934-2", "EPD-RWC-10426"		
030610K001	"2-1197971-2"		
BM9086-000	"44A1221-16-0/9-9CS3432"		
421569-000	"5-1193175-3", "44A9665-14-0/2/5/9-0"		
EG6690-000	"FLDWD031 1-12-9CS3422"		
E87233K001	"1-1200584-3"		
CX5299-000	"EPD-RWC-22192"		
799178-000	"44A1221-14-9/96-9", "6-1198309-7"		
592736-001	"3-1194687-9", "FB-44-40-7000"		
371303K001	"2-1192781-7"		
CJ8042-000	"44AM1121-22-9/96-9CS3209"		
534823-000	"44/7004-26-9CS1890", "8-1194197-2"		
282618-000	"3-1192120-4", "44A0111-22-938"		
583891-000	"44A1231-18-F862-9", "3-1194624-2"		
746577K001	"5-1195824-3"		
C53917-000	"3-1201692-1", "44A0111-10-9-6"		
EF4145-000	"44A9970-14-90CS2745"		
552717K001	"4-1194368-9"		

360401-000	"6-1192703-8", "44AM1111-18-966-9"		
251680-000	"9-1199377-5", "44AM1111-18-924-9-1KF"		
F65902-000	"EPD24566D-RYQ", "1-1200937-8"		
CU8292-000	"44A0212-12-95"		
EP2875-000	"44A1221-14-0/9-9-L409"		
678663-000	"1195335-7", "44A1231-16-0/2/9-9"		
479647-000	"8-1193590-3", "EPD-ROC-10049"		
CA1045-000			
551885K001	"2-1194362-0"		
387681-000	"5-1192911-6", "44A3111-22-9"		
306421-000	"2-1192321-8", "44AM1141-22-9/93/95/96-9"		
121855K001	"1190887-8"		
361637K001	"1-1192712-0"		
983269-000	"8-1197596-1", "EPD20028C-18-0CS2231"		
514869-000	"2-1194044-0", "EPD6833-22-0"		
382523-000	"7-1192864-6", "44A1131-22-3/6/9-9"		
384933-000	"3-1192888-5", "44A1221-24-9/92-9"		

502363-000	"345M06B-22-14-0CS2041", "9-1193771-2"		
383851-007	"1192879-8", "44A0121-26-0/9-US"		
124423-000	"6-1190904-9", "EPD6566-22-0"		
F67239-000	"5-1201315-3", "44A0111-12-922"		
386925-000	"44A0121-22-9/904"		
372368-000	"5-1197950-3", "44A0211-14-9-1KF/1"		
CU3022-000	"44A0212-12-90"		
539371-000	"44AM1111-18-945-9", "2-1194232-8"		
908933-000	"4-1197060-6", "FB-44-4026-0007"		
BM8770-000	"UB2-26C131BG11-9-E630"		
919079-000	"44/9093-24-9-9CS1222", "4-1197132-1"		
289692-000	"4-1192196-1", "EPD6648-22-0"		
EP0254-000	"44A0331-16-9/9/9"		
839629K001	"4-1196551-3"		
389783-000			
282297-000	"3-1192112-5", "44A0212-12-9"		
777745-000	"2-1196054-6", "FLDWC0311-20-9"		

CF5269-000	"44BC2124-24-1/9-9CS3215"		
521503-000	"7-1194098-1", "EPD-ROK-10155"		
D56733-000	"44A1221-18-6/9-0-US", "2-1200933-6"		
382394-003	"7-1192862-3", "44A1141-22-0/2/6/9-9"		
476601-000	"44A9632-16-0/9-9CS2748", "5-1193569-2"		
CR7932-000	"CTC-0039-16-9/5-9"		
CA1805-000	"FB-44-4624-0209CS3186"		
420599-000	"7-1193168-1", "44AM1111-18-924-9"		
562149K001	"6-1194441-7"		
836843-000	"9-1196531-6", "FB-44-7026A-0219CS896"		
657562-000	"5-1198907-5", "FLDWC1321-20-9/90-9CS2959"		
407497-000	"1-1193074-5", "EPD52855A-20-0"		
234455K001	"4-1191722-3"		
CL3970-000	"EPD-RWC-14668CS2497"		
056861-000	"6-1190432-0", "EPD-RWC-11674"		
EK1637-000	"44A0311-26-9-E634"		

900081-000	"5-1196996-9", "FB-44-7026A-0232CS896"		
954573-000	"44A9677-22-ELC4-9CS2746", "8-1197390-2"		
CM4211-000	"44A1221-24-9/92-9CS2812"		
153915K001	"1191112-3"		
496444-001	"1-1193712-8"		
637033-000	"44A9083-14-9CS2745", "9-1195036-3"		
EG8697-000	"EPD-RWC-24022"		
709335-000	"44A9966-10-9-US", "5-1195558-3"		
265580-000	"3-1199501-5", "EPD-NAV-79417"		
841155-000	"6-1196562-3", "EPD-ADD-10089"		
648535K001	"5-1195119-6"		
804283K001	"4-1196217-4"		
C36664-000	"8-1201426-2", "EPD-RWC-18834-L099"		
405381-000	"3-1193059-4", "44A9673-20-9CS2745"		
772117-001	"4-1196014-2", "FB-44-7026A-0236CS896"		
740463-000	"44A0841-20-MAS4CS2017", "6-1195779-8"		
CZ2122-000	"44A0111-26-9-1KF/1"		
CF5444-000			

058007K001	"4-1190440-4"		
CP3777-000	"EPD100897 A-US"		
664189-000	"3-1195234-3", "EPD-RWC-13950"		
606475K001	"1194798-5"		
374962-000	"3-1201789-5", "44A1321-24-0/9-9-US"		
CU9567-000	"EPD-RWC-22799"		
039057-000	"1-1190299-2", "WXA-0165-20-92"		
149739-001	"6-1191082-9", "44A9416-24-9CS1981"		
C32005-000	"9-1201422-9", "FLDWC0311-22-9CS2979-1KF"		
CY0660-000	"44A1231-14-MST3-9CS3030"		
543199-000	"9-1194260-0", "EPD52745A-18-0"		
619433K001	"4-1194893-9"		
387327-000	"2-1192908-6", "44A1111-22-9-94-US"		
790651K001	"1-1196124-6"		
502413K001	"7-1193773-1"		
844935-000	"7-1196591-6", "FB-44-7026A-0230CS896"		
383737-000	"4-1192877-5", "44A0121-26-3/9-US"		
035529K001	"7-1190274-0"		

CS3695-000	"EPD-CAN-10019-L262"		
301044-001	"2-1192280-0", "44AM1111-22-9-0"		
F86697-000	"44A0211-14-9CS3030", "4-1200354-9"		
495267-000	"2-1193704-7", "EPD-RWC-13999"		
318515K001	"5-1192416-1"		
553947-000	"44AM1111-22-9-9CS1702", "3-1194374-0"		
CY6514-000	"44A1231-12-MST3-9CS3030"		
477619-000	"44A9673-22-9CS2745", "1-1193577-3"		
923863K001	"9-1197166-6"		
D07587-000	"8-1200583-1", "EPD-RWC-17784"		
427781K001	"6-1193218-8"		
053935-000	"8-1190411-7", "44B9534-12-9-9CS1728"		
475279-000	"1193560-7", "FB-44-7026A-0225CS896"		
849887-000	"44A9681-22-0/9-9CS2748", "8-1196626-8"		
732021-000	"5-1195718-3", "FB-44-7026A-0215CS896"		
632565K001	"7-1195004-0"		

906315-000	"4-1197041-8", "EPD-RWC-15996"		
CX4900-000	"44A1321-12-9/9-9CS3030"		
843081K001	"7-1196576-2"		
F55665-000	"1202100-4", "EPD52415A-12-0-L016"		
769337-001	"44AM1111-22-9-6", "8-1195994-5"		
219481-000	"5-1191619-6", "44A0131-18-2/7/9"		
054643K001	"9-1190416-8"		
A35431-000	"6-1201177-1", "EPD-RWC-18504-L099"		
473439-000	"1193547-4", "EPD-ROC-10040"		
E70645-000	"8-1201691-9", "44A0111-10-9-12"		
575249K001	"4-1194565-4"		
E40872K001	"1-1200393-3"		
EH9936-000	"FLDWC1331-20-1/5/9-8"		
085187-000	"8-1190628-9", "44A9083-16-90CS2745"		
EM5438-000	"EPD-RWC-23496CS3490"		
390425-000	"2-1192931-2", "44AM1141-18-0/2/5/9-9"		
386919-000	"44A0121-22-9/95"		
364523K001	"7-1192733-3"		
CB8373-000			

CU5303-000	"44A1111-10-9-9"		
698405K001	"9-1195480-4"		
227321K001	"4-1191673-0"		
144557K001	"7-1191044-8"		
EM6446-000			
356581K001	"2-1192676-9"		
886634-000	"EPD-NAV-85111"		
CA7752-000			
D87301-000	"EPD-RWC-19899"		
CL6052-000			
285786-000	"3-1192163-5", "44A0111-26-96-US"		
384027-000	"5-1192880-0", "44A9090-14-0/2/9-9CS2746"		
629721-000	"44A1131-22-0/9/9-9", "2-1194984-6"		
384183-000	"9-1192881-9", "44A0121-26-5/9"		
C85093K001	"1-1200571-1"		
859137K001	"5-1196694-8"		
072567K001	"8-1190543-2"		
778585-000	"345/37B-22-60-0CS1913", "9-1196059-5"		
EM4421-000	"CEC-RWC-24951"		
396416-000	"1-1197951-1", "44A1221-14-9/96-9-1KF/1"		

F17005-000	"EPD4695A-US-L072", "4-1200564-4"		
649905-000	"44A1221-24-9/92-9CS984", "4-1195129-5"		
757093-000	"6-1195899-8", "EPD-RWC-15764"		
382687-000	"6-1192866-9", "44A1221-16-0/9-9"		
267968-000	"3-1198990-2", "EPD-ROK-10491"		
737861-000	"4-1195760-5", "FB-44-7026A-0216CS896"		
075781-000	"6-1190566-7", "EPD52372A-22-0"		
232486-000	"8-1191707-2", "EPD20021C"		
017891-000	"6-1190139-7", "EPD52164A-18-0"		
383040-000	"5-1192870-2", "44A0141-22-9/9/9/9"		
CP8075-000			
909702-000	"1198990-7", "EPD-ROK-10493"		
433793-000	"7-1193262-2", "FB-44-7024A-0202"		
773975-000	"2-1196027-9", "CSC-0215-18-0"		
425663K001	"1193204-8"		
387367-000	"6-1192908-7", "44A1111-22-9-93"		
EJ1070-000	"EPD43502D-US-L012"		

535595-000	"1-1194205-1", "EPD-RWC-14668CS2888"		
493623K001	"9-1193691-0"		
CF5287-000	"44A4124-24-1/9-9CS3227"		
194184-000	"9-1191408-5", "44B1221-24-9/96-925"		
555927-000	"44AM1111-22-9-9CS2399", "7-1194385-4"		
484841-000	"44/1424-26-0/9-9CS2251", "2-1193629-0"		
199073-000	"1191442-8", "44A0121-22-7/97"		
377177K001	"5-1192824-3"		
282693-000	"9-1197942-8", "44A0211-22-92-US"		
383492-000	"6-1192875-4", "44A1121-22-0/9-94"		
774837-000	"6-1196033-7", "FB-44-7026A-0203CS896"		
950343-000	"7-1197349-9", "CMC-0124-8"		
583047K001	"5-1194618-0"		
CN9508-000			
EP1302-000	"EPD-RWC-25206"		
027720-000	"8-1198916-1", "44A0311-26-9-1KF"		
932097-000	"44A9089-16-0/9-9CS2514", "7-1197224-9"		

608403-000	"1-1194812-8", "EPD-RWC-15432"		
746881K001	"9-1195826-3"		
211983-000	"3-1191535-3", "345M09J-22-38-0CS2041"		
800213-000	"5-1196187-8", "FB-44-7026A-0222CS896"		
456211-000	"1-1193424-1", "EPD-ROK-10021"		
471915K001	"7-1193535-7"		
EG6913-000	"44A0111-10-9-E627"		
CR5025-000	"EPD-DND-21972-L012"		
301093-000	"9-1192280-0", "44AM1114-22-9-9"		
665517-001	"7-1195243-0", "FB-44-4624-0201CS1578"		
322971K001	"7-1192444-1"		
EF5724-000			
022755K001	"1-1190176-8"		
431665K001	"5-1193246-9"		
951528-000	"3-1199188-1", "FLDWC0311-12-9CS2722"		
D33399K001	"1201448-9"		
443139-000	"1193331-1", "44A0821-20-92/96CS2017"		
876777-000	"44AM4121-26-0/9-9", "7-1196819-8"		
178573K001	"5-1191298-9"		

405201-000	"1-1193058-0", "EPD-RWC-10945"		
329775-000	"6-1192492-2", "44A9673-22-90CS2745"		
456143-000	"44A9586-22-9", "7-1193423-0"		
564393-000	"44AM1141-22-0/2/4/94-0", "2-1194458-9"		
519743-000	"44B9537-12-MST4-9CS1728", "1194078-8"		
376912-000	"8-1192822-1", "44A0121-22-6/96"		
301047-001	"2-1192280-6", "44AM1111-22-9-3"		
495468-000	"1-1197898-1", "EPD-RWC-14668CS2888-L006"		
349363K001	"6-1192628-0"		
903823-000	"6-1197023-7", "EPD51193A-22-0"		
CW4989-000	"EPD-RYQ-23554-L012"		
811857K001	"7-1196314-0"		
383607-000	"6-1192876-2", "44A1141-26-0/2/5/9-9"		
F10755K001	"1-1200403-4"		
382590-000			
279801K001	"6-1192070-9"		
096413K001	"2-1190707-0"		

832883K001	"7-1196502-1"		
566449-000	"44A9673-20-90CS2745", "4-1194473-5"		
386924-000	"44A0121-22-9/903"		
666426-001	"345/98B-26-48-0CS1913", "8-1195249-5"		
382254-009	"1-1192859-1", "44A1121-22-0/9-9-MX"		
842992-000	"7-1196575-3", "EPD23066B-US"		
888083-000	"2-1196909-9", "EPD52968A"		
726399-000	"44/0411-22-9CS1038", "9-1195676-1"		
985637-000	"44B1831-20-MAS3-9CS2018", "3-1197614-5"		
EP7610-000	"EPD-RWC-23464-L005"		
692357K001	"2-1195435-9"		
CZ7634-000	"EPD-RWC-22254"		
471453K001	"6-1193532-3"		
EG6695-000	"FLDWC0311-20-9CS3422"		
D50704K001	"8-1201420-8"		
589964-000	"44AM1111-18-92-9-1KF", "3-1199379-6"		
173474-000	"1-1200086-9", "44A0221-16-9/9-5CF/1"		
598449K001	"6-1194731-6"		

061625K001	"2-1190466-0"		
ER5795-000	"44AM1121-18-9/96-9CS3529"		
CP2425-000			
301082-002	"7-1192280-2", "44AM1111-26-9-3"		
282258-000	"8-1192110-7", "44A0211-18-9-MX"		
606235K001	"1-1194796-1"		
D35841-000	"6-1201712-8", "44AM1121-18-9/96-9CS2994"		
071841K001	"2-1190539-4"		
923133-000	"44A9666-14-0/9", "9-1197161-7"		
068880-000	"4-1199423-8", "44A0111-26-9CS2896"		
112907-000	"7-1190823-4", "44A9113-22-8CS1681"		
845419K001	"1-1196595-4"		
169754-000	"7-1199952-9", "EPD4695A-US"		
EG5695-000	"EPD-RWC-24097-L348"		
754529-000	"44A9416-22-915CS1981", "9-1195881-3"		
255959-000	"3-1191873-8", "44A9177-20-8CS1747"		
728053-000	"44/4424-26-0/9-9CS2251", "2-1195689-7"		

202587-001	"7-1191468-0", "FB-44-4022-0001"		
686771K001	"9-1195392-9"		
CS6946-000	"EPD-DND-21535-L099"		
159029-000	"1-1191149-5", "44A9586-26-9-6"		
386918-000	"44A0121-22-9/94"		
101117-000	"1190740-8", "44A9088-16-9-9CS2746"		
CF3510-000			
445158-000	"10515-X-8", "5-1193345-8"		
824743-000	"4-1196440-9", "EPD-RWC-10438"		
405629-000	"1-1193061-3", "EPD52960A"		
416654-000	"8-1198271-6", "44A0121-16-9/96CS2109"		
617065-000	"44A9090-16-0/2/9-9CS2746", "1-1194877-5"		
382314-002	"3-1192861-8", "44A0121-22-2/9-MX"		
123533-001	"6-1190898-2", "FB-44-7026A-0213CS896"		
415151-000	"1193129-3", "EPD-ROK-10019"		
630893-000	"6-1194992-8", "EPD-RWC-10946"		
383028-000	"4-1192870-0", "44A1132-24-0/2/9-9-US"		

598967K001	"6-1194735-3"		
EG9467-000	"44A9177CS1747"		
237287-000	"5-1191744-2", "EPD64091A"		
691865-000	"8-1195431-3", "EPD-RWC-14917"		
A24367-000	"5-1200552-2", "FLDWC1321-16-0/9-9CS3050"		
CR0857-000	"44A0321-22-9/96"		
590393-000	"5-1194670-5", "EPD51045A-26-0"		
3C0390-000	"6-1199861-7", "EPD5374-X-0"		
219319K001	"3-1191618-2"		
576191-000	"44AM1111-18-92-9", "5-1194571-6"		
058553K001	"3-1190444-4"		
956281-000	"44A1126-26-0/9-9", "4-1197403-8"		
CA2939-000			
082153K001	"6-1190608-6"		
603851-000	"44AM1141-22-9/92/93/96-9", "6-1194778-2"		
E53963-000	"1-1201700-0", "44A0111-18-95-2KF"		
287346-000	"1192178-6", "44A0111-22-9-26"		

CF4816-000	"44B9530-22-1/9-9CS3219"		
583219K001	"6-1194619-8"		
643637K001	"2-1195085-1"		
242377K001	"2-1191779-0"		
258225-000	"4-1191889-9", "44A7690-22-0CS2231"		
186315K001	"1191353-3"		
383022-000	"3-1192870-0", "44A1141-22-3/5/6/9-9-US"		
384234-000	"9-1192882-3", "44A0121-22-3/9-MX"		
674939-000	"3-1195308-7", "FB-44-7026A-0224CS896"		
919599-000	"345M06B-22-14-0", "2-1197136-8"		
412421K001	"4-1193110-5"		
CA6566-000	"44A4122-20-1/9-9CS3185"		
969953K001	"4-1197498-6"		
762819-000	"1195940-1", "EPD-RWC-14218"		
EM4250-000	"EPD-RWC-23464"		
241097K001	"2-1191771-3"		
443119K001	"8-1193330-8"		
312625K001	"9-1192364-3"		
CY4263-000			
282620-000	"4-1192120-1", "44A0111-22-946"		

613143K001	"8-1197888-8"		
185849K001	"7-1191349-2"		
CP2252-000	"EPD-DND-21667-L108"		
306490-000	"1192322-1", "44AM1121-22-0/9-90"		
CY9614-000	"EPD-RWC-14920-L012"		
637362-000	"2-1199869-3", "FB-RWC-17132"		
173409-000	"1-1191261-5", "345M15B-22-38-0CS2041"		
138655-000	"5-1191005-5", "44A1231-18-0/2/9-0"		
436839K001	"6-1193283-3"		
705582-000	"44A0111-22-9000", "4-1195533-9"		
534305-000	"44A9440-12-9/96-9CS527", "1-1194194-2"		
876921-000	"44/2421-20-9/90-9CS1506", "6-1196820-7"		
105499K001	"1-1190771-4"		
CJ9549-000	"44A0311-10-9-L050"		
283294-000	"3-1192134-2", "44A0211-12-90"		
282069-000	"1192101-1", "44A0112-16-9"		
CM1061-000	"EPD86690A-US"		
CR5118-000	"4J2N-12-F6-0"		

EJ1767-000	"44A1321-14-9/9-9C3030L014"		
170621-000	"6-1191241-2", "44A1221-14-0/9-9"		
928068-000	"44A0211-16-9-1KF/1", "1198733-5"		
CA3528-000			
171641-000	"6-1191248-3", "44B9535-12-9/96-9CS1728"		
CM5742-000	"FLDWC0311-12-9CS2736"		
277405K001	"3-1192054-0"		
002475K001	"1190019-6"		
109449-000	"2-1197970-6", "EPD70555A-US"		
A72600-000	"6-1200524-7", "EPD62610A-MTI"		
630947-000	"44A9083-16-9CS2745", "1194993-7"		
C38375-000	"1-1201691-9", "44A0111-10-9-8"		
704839-000	"345/37B-22-30-0", "5-1195528-2"		
389852-000	"4-1192926-6", "44A3131-18-0/2/9"		
530327-000	"44A9966-10-9CS2745", "3-1194165-9"		
CF9907-000	"EPD-RWC-20536-L106"		
572409-000	"6-1194543-9", "EPD51026A-26-0"		
960653-000	"1197433-9", "EPD-RWC-16063-L300"		

282691-000	"1-1192123-0", "44A0111-18-94"		
CS1899-000	"EPD66779B-US-L012"		
CP4258-000	"44A1132-16-9/93/96-9"		
387012-000	"5-1192903-6", "44A1111-18-9-9"		
F64040-000	"EPD24565D-RYQ", "1-1200937-6"		
460719K001	"7-1193455-0"		
282661-000	"1192122-4", "44A0111-22-915-US"		
404221-000	"4-1193051-3", "44A9083-14-90CS2745"		
354418-000	"4-1201422-2", "44A0341-20-0/2/6/9-US"		
CA7737-000			
CB7006-000	"EPD-RWC-19002"		
F03227-000	"44A1221-16-9/9-9-1KF/1", "8-1199656-9"		
746559-000	"345M13B-26-8-0CS2041", "4-1195824-0"		
562449-000	"44B9534-22-9-9CS1728", "1-1194444-0"		
909937K001	"1-1197068-5"		
292439-000	"9-1192216-4", "44A0111-18-955"		
525777K001	"7-1194131-0"		

F61806-000	"1200572-5", "FB-RWC-17654-L080"		
225971K001	"2-1191664-0"		
195008K001	"5-1199869-0"		
518475K001	"6-1194069-1"		
CU3010-000	"EPD-RWC-22933"		
082747-000	"4-1190612-9", "345M09J-22-14-0CS2041"		
E33792-000	"5-1201345-6", "EPD-RWC-10937-L110"		
282765-000	"5-1192125-7", "44A0111-22-925-US"		
794090-000	"1-1199162-4", "FLDWC0311-24-9"		
975665-000	"4-1197539-0", "EPD-ADD-10012"		
ER6312-000	"44A0321-16-0/9-US"		
904539-000	"44A0311-20-9CS2745BAR REL", "3-1197029-4"		
664153-000	"1195234-6", "CMC-0578-18-0CS2327"		
542901K001	"6-1194258-0"		
CY3359-000	"EPD-CAN-10019-L312"		
F87031K001	"3-1200404-0"		
123731-000	"1190900-1", "44A9089-14-0/9-9CS2746"		
CN8364-000	"44/0412-20-9CS1038"		

A94316-000	"4-1200727-0", "EPD98877A-US-CS2979"		
299387-000	"5-1192266-1", "EPD-RWC-14233"		
063357K001	"7-1190478-2"		
282580-000	"1-1192119-9", "44A0211-14-9-MX"		
356793-000	"6-1192677-7", "EPD51415A-X-0"		
382506-000	"4-1192864-1", "44A1121-22-6/9-9-MX"		
162545-000	"4-1191173-4", "44A7715-22-0CS2230"		
276667K001	"1192049-6"		
372135-000	"4-1192787-8", "EPD52253A-CS2749"		
045792K001	"4-1198990-5"		
CZ5309-000	"EPD-DND-21538"		
282762-000	"4-1192125-4", "44A0111-22-913"		
CU8712-000	"EPD-DND-21489-L281"		
EM4417-000			
692481-000	"44A9605-16-98", "1-1195436-5"		
D60995-000	"44A1221-14-9/9-9CS3030", "3-1200358-1"		
E20527-000	"44A0121-12-9/96CS2994", "5-1200400-1"		
669901K001	"5-1197823-4"		

902393-000	"EPD49715A-US"		
834737-000	"7-1196516-5", "EPD52740A-18-0"		
D96705-000	"44A0221-16-9/9CS3030", "9-1200301-6"		
282764-000	"5-1192125-3", "44A0111-22-918"		
300713K001	"6-1192277-4"		
177473K001	"1-1191290-2"		
EM8484-000	"EPD-RWC-24364"		
EG9654-000	"EPD-RWC-16063"		
E88978-000	"3-1201692-8", "44A0111-10-9-2"		
648571-000	"8-1195119-1", "EPD-RWC-12359"		
CU8800-000	"EPD-DND-23026-L281"		
283147-000	"8-1192132-0", "44A0111-22-924-US"		
036753K001	"8-1190283-7"		
443591K001	"1193334-3"		
282100-003	"1-1192104-1", "44A0311-22-9-US", "44A0311-22-9-US"		
269251K001	"2-1191987-1"		
004999-000	"2-1190038-5", "345M12B-26-48-0CS2041"		

D13057-000	"44A1161-12-0/2/3/4/5/9-9", "5-1200173-2"		
105721K001	"6-1190772-0"		
593164-000			
497721-000	"4-1193721-3", "EPD51943A-18-0"		
129471-000	"3-1190940-5", "EPD-ROC-10016"		
F32056K001	"3-1201864-7"		
387239-000	"1192907-5", "44A1112-24-9-9-MX"		
386936-000	"44A0121-22-9/917"		
459668-001	"10515-X-8CS1285", "9-1193447-1"		
526285-000	"8-1194135-4", "EPD-RWC-13842"		
984099K001	"7-1197602-9"		
188763-000	"9-1191369-3", "EPD51237A-X-0"		
CB4569-000	"EPD37260A-US-L099"		
056679-000	"4-1190431-2", "44A9636-24-9/96-9CS2337"		
D73586-000	"44AM4821-20-6/9-9CS2994", "6-1201031-4"		
382315-002	"4-1192861-4", "44A0121-22-6/9-MX"		
086211K001	"3-1190636-1"		
CP1693-000	"44A0111-10-9-3-L232"		

CS1779-000	"EPD-RWC-14918-L012"		
A21391-000	"5-1200354-7", "EPD-RWC-17601"		
383343-000	"1192874-6", "44A1121-22-0/9-92-US"		
CU8796-000	"EPD-DND-21490-L177"		
178585-000	"6-1191298-4", "EPD-ADD-10085"		
269893-000	"1-1191992-1", "EPD-RWC-14598"		
749033-000	"3-1195842-8", "EPD52370A-22-0"		
292762-000	"9-1198733-8", "44A1161-18-0/2/3/4/5/9-9"		
378774-000	"1-1200075-9", "44A1121-26-4/9-9"		
636701K001	"1195034-4"		
F54437-000	"44A0231-16-9/9/9CS3030", "1-1200301-3"		
C35057-000	"3-1200695-4", "EPD-RWC-17886"		
503015-000	"2-1193786-7", "EPD-RWC-14223"		
766273-000	"44A0811-20-9CS1465", "1-1195972-9"		
073769-000	"1190552-3", "44AM1121-22-6/9-9CS2399"		
533119-000	"6-1194185-6", "CMC-0577-18-0CS2327"		
991899K001	"2-1197672-3"		

478231-000	"44A9964-16-9CS2514", "1-1193581-6"		
736875K001	"6-1195753-4"		
395203-000	"10477-X-8CS791", "9-1192964-2"		
F70704-000	"44A0111-18-9-L038", "7-1200553-0"		
462455-000	"5-1193468-1", "CMC-0560-X-0"		
347493-000	"1192615-2", "EPD37109B-US"		
658099-000	"44AM1161-26-0/2/3/5/6/9-9", "9-1195188-8"		
046691K001	"6-1190358-9"		
C49996K001			
CB4688-000	"EPD-RWC-18278CS3085"		
EG4276-000			
360199K001	"3-1192702-9"		
D74999-000	"1-1200881-7", "EPD-RWC-18031"		
E74787-000	"6-1200297-3", "EPD-SVD-10023"		
003597-000	"2-1190027-4", "44A1221-14-0/9-9-5CF/1"		
CA3707-000	"44A9749-20-1/9-9CS3185"		
529879-000	"1-1194161-8", "EPD-RWC-14229"		
448305K001	"6-1193368-3"		
550851K001	"2-1194348-1"		

717463-000	"44A9586-22-9CS2897", "3-1195612-3"		
167977-000	"1191223-6", "44A1231-12-9/90/92-9CS984"		
371501-000	"9-1197901-8", "44A1221-12-9/96-9-5CF/1"		
CS2890-000	"44A0321-20-0/9-F871"		
523023K001	"4-1194109-6"		
401873-000	"1193034-7", "EPD51153A"		
CA2350-000	"EPD-RWC-19791"		
CS7717-000			
350981K001	"9-1192638-9"		
380951K001	"4-1192848-0"		
306377-000	"8-1192320-0", "44AM1131-26-0/2/9-9"		
CR6265-000	"EPD-RWC-17038-L012"		
C79296-000	"4-1201884-1", "44A0114-20-9-L095"		
937297-000	"3-1197261-1", "WXA-0165-20-9"		
317339-000	"3-1192404-6", "EPD52965A"		
195657-000	"3-1197846-6", "44A1851-20-0/2/4/6/9-9"		
618101K001	"1194884-1"		
726328K001	"1199952-3"		
523923K001	"9-1194115-2"		

940287K001	"1-1197281-7"		
306876-000	"6-1192324-3", "44AM4121-22-0/9-9"		
465097K001	"2-1193487-6"		
027819K001	"2-1190215-5"		
282617-000	"2-1192120-9", "44A0111-22-937"		
799237K001	"3-1196179-2"		
282759-000	"2-1192125-7", "44A0111-22-901-US"		
971125-001	"44/0412-24-9CS1220", "8-1197506-1"		
086505K001	"2-1190638-3"		
174947-000	"2-1191272-5", "44A9085-16-0/9CS2747"		
267289K001	"1197843-9"		
844345-000	"44A9676-20-0/2/9-9CS2746", "4-1196587-2"		
614034-000	"3-1194854-5", "FB-44-0722-0001"		
345591-000	"8-1192601-5", "EPD52210A-22-0"		
CR2144-000	"44A1121-26-0/9-0-US"		
953445-000	"44A4321-20-0/9-9CS2748", "9-1197382-3"		

A72881-000	"2-1200976-0", "EPD-RWC-18278CS3085-L101"		
382763-000	"7-1200873-0", "44A1131-18-0/2/9-0-US"		
CS2017-000	"44A4121-18-2/9-8"		
326809-000	"9-1192472-0", "WXA-0165-22-9"		
551129-000	"345M09J-22-6-0CS2041", "8-1194356-2"		
557719K001	"2-1194399-0"		
CP4245-000	"44A1122-16-9/96-9"		
EG6909-000	"44A0111-12-9-E627"		
733407-000	"4-1195728-4", "EPD-RWC-13644"		
CS3830-000	"EPD-DND-21535-L263"		
503403K001	"1193789-1"		
D08897K001	"9-1201426-6"		
F65978-000	"44A0221-14-9/9CS3030", "4-1200354-4"		
437583K003	"9-1193288-8"		
301048-001	"2-1192280-9", "44AM1111-22-9-4"		
C71511-000	"44A1231-14-9/93/96-9"		
451851K001	"1193393-8", "EPD-RWC-15432-COA-KIT-1"		
CF4855-000	"44B4122-16-1/9-9CS3225"		

383357-000	"2-1192874-8", "44A1121-22-9/96-9"		
383491-000	"6-1192875-1", "44A1121-22-0/9-93"		
526608-000	"2-1194138-6", "44AM4121-22-0/9-9CS262"		
386915-000	"9-1192901-2", "44A0121-22-9/91"		
442393-001	"7-1193325-9", "44A0111-26-9CS289"		
264828-001	"9-1191948-6", "44A9440-24-9/96-9CS527"		
358907K001	"1-1192693-2"		
CA7753-000	"EPD-NAV-32504"		
282623-000	"5-1192120-6", "44A0111-22-923-US"		
260447K001	"6-1191905-0"		
419463-000	"2-1193160-4", "44A9091-14-ELC4-9CS2746"		
061901K001	"1-1190468-9"		
005879K001	"9-1190044-0"		
306639-000	"1192323-7", "44AM1121-22-9/90-9"		
CP7130-000	"44A0311-14-9CS3030"		
CS1898-000			
259645K001	"5-1191899-5"		
061267K001	"8-1190463-3"		

212599-000	"1-1191538-8", "345/45B-22-38-0CS1913"		
282071-000	"1-1192101-3", "44A0112-20-9"		
241267K001	"5-1191772-8"		
306188-001	"7-1192318-9", "44AM1121-22-6/9-9"		
D66575-000	"3-1201692-4", "44A0111-10-9-1"		
CS2764-000	"44A0311-10-9-F871"		
331145K001	"1-1192502-0"		
817861K001	"1-1196373-7"		
282660-000	"9-1192121-8", "44A0111-22-914-US"		
CP1025-000	"FLDWC0311-20-9CS2736"		
027877K001	"7-1190215-7"		
384084-000	"1192881-3", "44A0121-26-9/91"		
791752-000	"44AM1111-18-966-9-1KF", "2-1199380-9"		
258985K001	"8-1191894-1"		
643247-000	"5-1195082-6", "EPD52961A"		
CY1455-000	"EPD-DND-21461"		
CM0557-000	"44B1121-18-9/96-9CS2994", "4-1899386-8"		
CX5921-000	"EPD38848A-US-L016"		

476013K001	"3-1193565-0"		
414156-000	"9-1198838-5", "44A0111-10-9-L017"		
301051-001	"3-1192280-2", "44AM1111-22-9-5"		
172649-000	"6-1191255-8", "EPD51035A-22-0"		
CU8788-000	"EPD-DND-21535-L146"		
D01557K001	"6-1200976-8"		
799405-000	"5-1196180-3", "EPD-RWC-15755"		
183511-000	"9-1191332-3", "EPD8486B"		
492593K001	"4-1193684-1"		
348563-000	"9-1192622-9", "EPD-RWC-11709"		
282304-000	"5-1200823-7", "44A0112-12-9-US"		
CM1059-000			
976059-000	"3-1197542-4", "EPD-ADD-10161"		
387025-000	"1-1192904-5", "44A2111-22-9-9-US"		
CA6440-000	"44A9748-16-9-9CS3185"		
404013K001	"9-1193049-4"		
314993K001	"7-1192383-8"		
555926-000	"44A9605-16-9CS2979", "9-1199777-0"		
CJ6932-000	"44A1321-16-9/9-9CS3030"		

729271-000	"44A9674-20-9-9CS2746", "8-1195697-7"		
663049-000	"2-1195226-1", "EPD52626A-X-0"		
688453-000	"6-1195407-1", "EPD52978A"		
E12045-000	"3-1200571-0", "EPD4710-US-L076"		
503543-000	"44/2414-24-9-9CS1222", "9-1193789-4"		
CL7172-000	"44AM1131-20-MST3-9CS3209"		
CA4481-000	"FB-44-4624-0201CS3186", "2-1899114-4"		
365213-000	"9-1192738-0", "44AM1111-18-921-9"		
838039-000	"4-1196540-9", "FB-44-7026A-0208CS896"		
927767-000	"44AM1111-18-94-9", "5-1197194-2"		
208705K001	"6-1191512-3"		
043911K001	"4-1190337-8"		
CA6432-000	"44A0112-20-9CS3184"		
736933K001	"1195754-5"		
CU9566-000			
383472-000	"3-1192875-1", "44A1121-26-9/96-9"		

E83427-000	"1200691-5", "EPD-RWC-17922"		
383342-000	"1192874-3", "44A1121-22-0/9-91"		
447703K001	"2-1193364-5"		
570437-000	"44AM2111-22-9-9", "6-1194521-5"		
CA9977-000	"EPD-RWC-19734-L149"		
EM7717-000	"EPD-RWC-23542"		
247197K001	"2-1191813-3"		
461023-000	"7-1193457-8", "EPD52797A-22-0"		
CX2616-000	"44A0321-16-9/9CS3030"		
408403-000	"7-1193080-3", "44AM3121-22-6/96"		
384526-000	"6-1192885-2", "44A0121-26-4/9-US"		
CJ1976-000	"EPD-RWC-17741CS2979", "6-1899257-6"		
906223K001	"8-1197040-4"		
025247-000	"9-1190195-1", "CMC-0576-18-0CS2327"		
644753-000	"7-1195092-8", "EPD52958A"		
EK8652-000	"44A1221-12-0/9-9-L386"		
382468-000	"8-1192863-7", "44A1141-22-0/2/5/9-9-MX"		

CP4318-000	"44B1121-12-927/928-9C3018"		
497657K001	"1193721-3"		
153229K001	"1-1191107-2"		
CS3449-000	"44A0311-12-9CS3030"		
782209-000	"44A9586-26-9-3", "6-1196075-6"		
369962-000	"4-1201422-3", "44A0331-20-0/2/9-US"		
886415-000	"7-1196896-9", "EPD52842A-22-0"		
534687-001	"44A2131-22-1/6/9-9CS453", "9-1194196-3"		
376304-000	"1-1201203-7", "44A1321-22-0/9-9-US"		
417905-000	"4-1193149-7", "44A9966-10-90CS2745"		
383347-000	"2-1192874-2", "44A1121-22-9/90-9"		
495421K001	"3-1193705-2"		
471607-000	"6-1193533-3", "EPD51685A-22-0"		
804127-000	"44/2421-22-9/90-9CS1506", "3-1196216-5"		
468999-000	"1193515-5", "EPD-ADD-10092"		
376432-000	"8-1201014-1", "44A0122-20-0/9"		
929925-001	"2-1197209-2"		

208121-000	"5-1191508-3", "EPD-RYM-93421"		
EL6400-000	"44AM1131-18-0/2/9-9CS3451"		
447003-000	"4-1193359-6", "EPD-RWC-14219"		
757749-000	"3-1197857-9", "EPD52988A"		
494819-000	"44B9536-22-MST3-9CS1728", "4-1193700-2"		
CW5034-000	"EPD-RWC-22254-L012"		
242697-000	"6-1191780-2", "44B9537-12-MST4-9CS3023"		
730249-000	"1195705-4", "EPD-RWC-13837"		
283007-000	"2-1192130-7", "44AM1151-22-2/3/5/6/9-9"		
306338-001	"3-1192320-6", "44AM1131-22-0/2/9-9"		
CF7333-000	"44AM1121-20-9/96-9CS3209"		
E47785-000	"2-1201885-2", "44A0114-22-9-L095-US"		
597815-000	"44A9650-14-0/9-0", "8-1194726-4"		
259135K001	"8-1191895-5"		
CS7765-000			
C03875-000	"1200693-6", "EPD-RWC-10946-L087"		

564837K001	"5-1194461-2"		
CA4835-000	"EPD20077D-US"		
738987K001	"6-1195768-1"		
005615-000	"8-1190042-7", "44B1821-20-92/96-9CS2018"		
871161-000	"1-1196780-1", "EPD52373A-18-0"		
517051-000	"9-1194059-2", "EPD52666A"		
454595-000	"1-1193412-4", "EPD40250A"		
CP5935-000	"44A0112-18-9CS3184"		
CS3450-000	"44A0321-12-9/9CS3030"		
D36727-000	"1201138-7", "EPD100539 A-ISR-L099"		
274705K001	"7-1192034-8"		
059325K001	"1-1190450-7"		
383470-000	"2-1192875-6", "44A1131-22-9/93/96-9"		
159073K001	"4-1191149-4"		
247092-000	"5-1199505-7", "EPD-RWC-17079"		
C46472-000	"6-1200354-4", "EPD-RWC-17607"		
487335-000	"5-1193646-5", "EPD52956A"		

523160-001	"44A9441-22-MST3-9CS527", "2-1194110-9"		
EM7722-000	"EPD-RWC-22037"		
EG4835-000	"EPD-RWC-22985CS1584"		
483539-000	"1193619-3", "EPD-RWC-14918"		
828081-000	"44A9605-16-96", "9-1196466-2"		
A09640K001			
CN2442-000	"4J3N-10-F6-0"		
E78744-000	"3-1202129-2", "EPD37262A-US"		
654485-000	"7-1195163-7", "FLDWC0311-22-9"		
595493K001	"1-1194709-9"		
999214-000	"44A0122-22-0/9", "8-1201014-7"		
CP7521-000	"FLDWC0311-16-9CS2736"		
287807-000	"2-1192183-8", "44A0111-18-964"		
722947K001	"2-1195652-8"		
759446-000	"44B1121-22-G058-9CS3018", "9-1199950-2"		
933989-000	"44A0211-16-90", "7-1197237-6"		
109363-000	"9-1190798-5", "EPD47319A-18-0CS2829"		

707893K001	"9-1195548-0"		
032869-000	"8-1190254-5", "44AM1121-22-9/90-9CS1726"		
170841K001	"2-1191243-6"		
818063K001	"1196376-1"		

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.