



19-Jan-2022

**PCN #:** P-22-022030

**Subject :** Spec 44 and FLDW Wires

**Description of Change :** TE Connectivity was informed by one of its material supplier on a consolidation in their manufacturing plant for PVDF based Color Concentrates (CC). TE Wire and Cable plants in Tijuana and Redwood City use PVDF CCs as colorant for outer insulation layer in spec 44 and FLDW primary wires. TE has evaluated the PVDF CCs from the supplier's new manufacturing location and no change to Form, Fit and Function of finished parts has been observed.

**Reason :** Part status change. TE was notified by its material supplier that except for Black PVDF CC, no change has been made in material formulation and recipe for PVDF CCs produced from their new manufacturing site. Due to health and safety policy of vendor's new manufacturing site with respect to handling raw carbon black pigments, this CC has undergone a change of one raw material component. TE evaluated these changes on the key characteristics of the CCs and the finished goods and no impact on the properties and performance of finished parts has been observed. Test reports on the wire characteristics can be provided upon request. In addition to the evaluation conducted by TE, FAIs will be performed on the first manufactured primary wire lot per each gauge for validation.

**Key Dates :**

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
383147-000	"8-1192871-8", "44A1141-22-0/2/4/6-9-US"		
CM8767-000			
881217K001	"2-1196860-2"		
305609-000	"1192314-9", "EPD52955B"		
328823-000	"5-1192486-3", "EPD-RWC-15751"		
595650K001	"7-1197890-4"		

514579K001	"2-1194042-4"		
CP6359-000			
A35414K001	"8-1201055-9", "EPD-ROK-10512-COD-KIT-1"		
D89002-000	"5-1201653-8", "EPD86559B-US"		
832563K001	"4-1196500-9"		
CU7740-000	"EPD-DND-22861-L277"		
187239-000	"2-1191359-1", "EPD-RWC-15756"		
003239K001	"6-1190024-4"		
CZ8809-000			
306492-000	"1192322-3", "44AM1121-22-0/9-95"		
506460-000	"44AM1121-26-0/96-9CS356", "2-1197928-6"		
358676K001	"7-1200815-2"		
C55508K001	"7-1200082-4"		
EG5997-000	"EPD-DND-23326-L016"		
902491K001	"9-1197013-6"		
908535-000	"3-1197057-7", "FB-44-7026A-0205CS896"		
529072K001	"1-1200906-6"		
CJ5177-000	"EPD94314A-US"		
223771-000	"4-1191648-9", "44AM1121-22-0/9-9CS561"		

004545-000	"7-1190034-4", "EPD51068A-22-0"		
357754-000	"4-1198846-4", "EPD93546A-US"		
CU1805-000	"EPD-DND-21543-L016"		
797461-000	"44B1121-16-0/9-93CS2025", "5-1196170-7"		
A26532-000	"1-1200691-3", "EPD-ROK-10332-L086"		
CP2426-000	"EPD-DND-21459-L108"		
070738K001	"4-1199943-7"		
400505-000	"3-1193024-1", "EPD51033A-22-0"		
583265-000	"345M09B-22-14-0CS2041", "9-1194619-3"		
CS7757-000			
CB6884-000	"EPD37260A-US-CS3207-L099"		
EL6392-000	"44AM1121-20-0/9-9CS3451"		
384935-000	"44A1141-18-0/2/6/9-9-MX"		
694141-000	"345M06B-22-36-0CS2041", "5-1195446-6"		
416405K001	"1-1193138-1"		
EM8824-000			
531395K001	"1-1194173-1"		

239471-000	"1191760-7", "EPD43500G- US"		
307714-000	"9-1198286- 8", "WXA- 0101-18-0"		
CX8760-000			
CF2252-000	"EPD-RWC- 18798CS3092 "		
429932K001	"1-1197928- 6"		
556403K001	"3-1194389- 6"		
145877-000	"4-1191054- 1", "EPD- ROK-10030"		
282212-004	"2-1192108- 6", "81044/12-22- 0"		
270465K001	"2-1192001- 3"		
625849-000	"6-1194955- 4", "EPD52983A "		
346085-000	"2-1192605- 0", "FB-44- 7026A- 0223CS896"		
223239-000	"7-1191644- 9", "44A0111- 26-0CS289"		
244321K001	"2-1191792- 6"		
CR2146-000	"44A1121-24- 0/9-0-US"		
CJ8693-000	"FB-RWC- 20698"		
475891-001	"4-1193564- 7", "44A7559- 24-0/9- 94CS448"		
CA7393-000	"EPD-RWC- 18522CS3127 -L155"		
797627-000	"345M12B- 26-84- 0CS2041", "6- 1196171-6"		

EG8490-000			
778796-000	"7-1200714-6", "EPD-RWC-17612"		
688004-000	"2-1195404-1", "FB-44-7026A-0239CS896"		
747166-000	"7-1199941-6", "EPD95433A-US"		
A75280-000	"7-1200524-1", "EPD62607A-MTI"		
CX2065-000	"EPD106254 A-US"		
CB6785-000	"EPD52957A-CS2979", "1899181-5"		
384980-000	"8-1192888-9", "44A1121-22-0/4-9-US"		
306416-001	"2-1192321-1", "44AM1141-22-0/2/5/9-9"		
368775-000	"7-1192763-0", "EPD-RWC-10302"		
579419-000	"44A2124-26-0/9-9CS457", "6-1194592-3"		
EK7097-000	"FLDWD031 1-10-0CS3422"		
EH8644-000	"400R0311-20-0"		
C52967-000	"44AM1141-22-F003-9CS2979", "1199658-1"		
EH9623-000			
E77037-000	"7-1201250-6", "44A0211-16-0CS3030"		

192707-000	"9-1191397-4", "EPD22878C-X-0"		
850645-000	"44AM1111-18-09-9", "4-1196632-6"		
EP7409-000	"400R1121-20-0/1-9"		
057087-000	"1-1190434-2", "44A9086-16-0/9/90"		
822103K001	"5-1196411-7"		
CF2172-000	"44A9605-16-0-L183"		
F69455-000	"5-1201566-2", "EPD-ROK-10543"		
284478-001	"9-1192149-6", "81044/13-26-0"		
944541K001	"2-1197311-4"		
022623-000	"1-1190175-5", "44A4121-18-0/2-9"		
CS7469-000			
CY1877-000	"EPD-DND-21451"		
EM0371-000	"EPD108173 A-US"		
CP4118-000	"44B1121-20-0/9-0"		
654795-001	"345/63B-26-48-0CS1913", "9-1195165-4"		
436341K001	"2-1193280-1"		
EG5966-000	"EPD62289A-US"		
282411-011	"7-1192115-0", "44A0211-16-0-MX"		
CN6857-000	"EPD108704 A-US"		

306369-002	"6-1192320-7", "44AM1131-24-0/2/9-9"		
CU4067-000			
A51320K001	"2-1201000-7"		
EK3061-000	"400R1141-20-0/2/6/9-0"		
276655-000	"1192049-2", "44B1121-24-0/9-98CS2024"		
857305K001	"4-1196681-7"		
EL5758-000	"EPD-RWC-24466"		
158935-000	"4-1191148-9", "EPD-RWC-15748"		
383484-000	"4-1192875-4", "44A1121-20-0/9-91"		
652389K001	"7-1195149-3"		
675487-000	"44A7712-22-0CS2230", "2-1195312-3"		
383831-000	"9-1192878-2", "44A0121-16-0/2-MX"		
C27760-000	"1-1201142-8", "EPD100538 A-ISR-L099"		
CS2019-000	"44A4121-20-0/2-8"		
306015-000	"1192317-4", "44AM1121-16-0/2-9"		
CY3978-000	"EPD-RWC-20307-L314"		
252587-000	"7-1191848-8", "44AM1141-20-F002-9CS356"		
CU7730-000	"EPD-DND-22841-L274"		

764896-000	"44B1121-20-0/2-3CS356", "9-1195954-4"		
CN5814-000			
214734K001	"8-1199130-7"		
692547-000	"5-1195436-6", "EPD53083A-X-0"		
231114-000	"3-1199818-7", "44A0713-20-0CS2979"		
F94083K001	"9-1200815-3"		
E30311-000	"6-1202097-9", "PRO-EPD-RWC-19272"		
CB4564-000	"EPD37262A-US-L099"		
968261-000	"1-1197486-9", "EPD24359A-US"		
185869-000	"8-1191349-2", "EPD-RWC-10937"		
631711-000	"44AM1131-20-0/2/9-9CS561", "5-1194998-8"		
126462K001	"3-1199106-3"		
EM6399-000	"400R4141-20-0/2/6/9-0-WIP"		
373457K001	"3-1192797-2"		
343503K001	"6-1192587-7"		
CX8617-000			
E52048K001	"6-1201151-9"		
297777K001	"1-1192255-8"		
961923K001	"6-1197441-6"		



358339-000	"1192689-2", "EPD51041A- 18-0"		
983729-000	"44B1121-26- MBD2- 9CS2275", "2- 1197600-5"		
CR9509-000	"44A1821-18- 0/9-3"		
E95762-000	"8-1199703- 6", "WXA- 0085-16-0- SPL"		
306031-000	"2-1192317- 7", "44AM1121- 18-0/9-9"		
230171-000	"4-1191691- 3", "345M16J-18- 2-0CS2041"		
549207-000	"44A0111-18- 0CS448", "9- 1194321-3"		
306601-000	"7-1192322- 5", "44AM1141- 20-0/2/6/9-9"		
CP8076-000	"EPD-RWC- 21804-L245"		
CU9754-000	"44AM1723- 20-0/2-6"		
300079F003	"1192273-1"		
241489-000	"3-1197909- 6", "EPD- ROK-10428"		
461439-000	"2-1193461- 6", "EPD- RWC-10949"		
584597K001	"8-1197827- 0"		
306605-000	"7-1192322- 7", "44AM1141- 22-0/2/4/6-9"		
610237K001	"4-1194825- 6"		
217484-003	"4-1191587- 4", "EPD4760C"		

EH8642-000	"400R0311-18-0"		
382503-000	"3-1192864-7", "44A1141-22-0/1/2/9-9"		
CA7738-000	"EPD-NAV-85108"		
CU5740-000			
355879K001	"5-1192671-1"		
306139-000	"2-1192318-8", "44AM1121-22-0/9-3"		
362449K001	"7-1192717-3"		
095465K001	"8-1190699-7"		
CB6849-000	"EPD-RWC-18864"		
E10891-000	"44A1241-20-G090-0", "9-1200974-0"		
591119-000	"345M15B-22-60-0CS2041", "9-1194675-7"		
418753-000	"2-1193155-3", "FB-44-7024A-0203"		
628370K001	"7-1198866-1"		
573584-000	"6-1198926-0", "EPD-RWC-16534"		
384222-000	"5-1192882-8", "44A0121-22-0/3-US"		
CF1583-000	"44A0112-22-0CS3184"		
CB7185-000	"EPD-RWC-20307"		
940855-000	"1-1197285-4", "EPD-RWC-15750"		
703793-000	"44A1231-18-0/2/9-9", "3-1195521-9"		

957177K002	"9-1197409-5"		
CY1679-000	"EPD-ROK-10545-L044"		
384219-000	"4-1192882-6", "44A0121-22-0/6-US"		
EH8646-000	"400R0311-22-0"		
054027K001	"5-1190412-0"		
536167-000	"44A9586-22-0", "1194209-6"		
C31664K001	"6-1200540-8"		
CM1921-000			
282309-000	"8-1192112-2", "44A0211-10-0-MX"		
262997K001	"9-1191935-5"		
238089-000	"3-1191750-1", "EPD-RWC-13951"		
CU2244-000	"CEC-RWC-22525"		
D62282-000	"7-1201003-3", "EPD65195A-US"		
303851-000	"3-1192301-4", "EPD86150A-US"		
3823313006	"6-1192861-8", "44A0121-22-0/9"		
013879-000	"8-1190108-2", "EPD25528C-US"		
CN5822-000			
719123K001	"8-1195624-4"		
CN5902-000			
CB7023-000	"44A3121-16-0/9"		

240049K001	"2-1191764-5"		
CZ2711-000	"EPD-RWC-23535CS3372"		
389942-000	"8-1192927-1", "44A7985-X-9"		
475821K001	"9-1193563-5"		
F01967-000	"EPD-ROK-10512-L022", "7-1201069-6"		
763911-000	"5-1195947-0", "EPD51023A-22-0"		
CM0918-000			
376827-000	"2-1201787-0", "44A1121-16-0/6-9-MX"		
903895-000	"2-1197024-1", "EPD37964A"		
409455K001	"9-1193087-7"		
751855-000	"4-1195862-7", "EPD52974A"		
CS7801-000	"EPD40650D-US-L011"		
383223-000	"5-1192872-6", "44A0121-26-0/2-US"		
321139-000	"7-1192433-7", "EPD-ROK-10043"		
311529-000	"7-1192357-5", "EPD-RWC-14228"		
084523-000	"1-1197970-5", "EPD86205A-US"		
EM7725-000	"EPD-RWC-22038"		
062351K001	"6-1190471-8"		

705083-000	"44A9678-22-0/9CS2747", "2-1195530-9"		
CW0107-000	"EPD-RWC-19939-L321"		
CU4945-000	"EPD-DND-22844"		
302103K001	"5-1192288-1"		
344389-000	"6-1192593-6", "EPD-ROC-10041"		
383094-000	"1-1192871-8", "44A0131-16-0/2/9-MX"		
EH8650-000	"400R0311-26-0"		
377911-000	"8-1192829-7", "EPD-RWC-15747"		
404725K001	"7-1193054-3"		
351433-000	"1192642-2", "44A9677-18-ELC4-9CS2746"		
C20979-000			
565058-001	"44AM1121-22-0/9-96", "1194463-3"		
CX8742-000			
204313-000	"9-1191480-7", "345M15B-22-48-0CS2041"		
438535-000	"9-1193295-5", "44AM1141-22-ELC4-9CS262"		
678405K001	"2-1195333-8"		
EG0849-000	"44A1123-20-0/9-9"		
3W0627-000	"2-1193019-2", "EPD20023C"		

944871K001	"4-1197313-3"		
482171K002	"3-1193609-4"		
920815-000	"9-1197144-2", "WXA-0085-20-0"		
CS4715-000	"44AM1121-18-0/4-9"		
307767-000	"3-1192331-9", "44AM1121-26-0/9-9CS356"		
029343K001	"2-1190227-8"		
008299-000	"3-1190064-3", "EPD50319A-X-0"		
3W0625-000	"1-1193019-7", "EPD20020C"		
867417-000	"5-1196753-1", "FB-44-7026A-0229CS896"		
415923-001	"9-1193134-6", "44AM1131-22-0/2/9-9CS356"		
019513-000	"2-1190152-5", "44AM1121-22-0/1-9"		
887047-000	"4-1196901-7", "EPD40386B"		
433723-000	"1-1193262-7", "EPD73549A"		
D19844K001	"2-1201652-8"		
CU8710-000	"EPD-DND-21445-L280"		
420403K002	"2-1193167-1"		

883828-000	"44B1121-24-0/9-95", "6-1196878-0"		
816255K001	"2-1196361-3"		
694917-000	"44A0124-20-0/9-US", "5-1197861-3"		
573913-001	"44A0114-26-0CS448", "7-1194555-2"		
045049-000	"1190346-8", "EPD-ROK-10023"		
226865K001	"6-1191670-1"		
012091-000	"4-1190095-8", "44A9650-12-0/9-0"		
507113-000	"1197832-4", "EPD61896B-US"		
F34059-000	"9-1201151-6", "EPD-IRL-85111"		
382800-000	"6-1201654-2", "44A1141-24-0/2/4/6-9-US"		
898093-000	"6-1196981-0", "EPD51070A-22-0"		
825869K001	"9-1196450-2"		
EG8796-000	"400R0111-20-0"		
CF2249-000			
191327-000	"8-1191387-1", "EPD51034A-22-0"		
492433-000	"44A9586-18-0", "1-1193683-6"		
CN8019-000	"EPD90506A-US-L044"		
540478K001	"1197957-4"		
CS2143-000	"81044/12-16-0-BRL-L117"		

275174-000	"FLDWD031 1-12-0"		
320213-000	"1192428-3", "EPD30623A- US"		
CX4708-000	"EPD-DND- 21541"		
003455-000	"1-1190026- 7", "44A1161- 20- 0/2/3/5/6/9-9"		
E18349-000	"7-1202031- 1", "EPD- IRL-35503- L106"		
545863K001	"7-1194295- 9"		
CX1051-000	"EPD-RWC- 16867-L253"		
061345-000	"3-1190464- 0", "EPD4776F"		
CS5228-000	"EPD-RWC- 18864-L106"		
CB7177-000	"EPD-RWC- 19938"		
EK5306-000	"44A4131-20- 0/2/9-8"		
CZ8810-000	"EPD106324 A-US"		
CS2760-000	"44A4121-16- 0/9-9-F871"		
387084-000	"1192905-9", "44A1111-22- 0-9"		
CU6642-000	"EPD-DND- 22842"		
595241-000	"4-1194707- 3", "EPD51388A- 22-0-F599"		
498469K001	"8-1193726- 3"		
372345-000	"8-1192788- 7", "EPD74283A- US"		



247785-000	"3-1191817-7", "44B1131-22-0/1/2-9CS356"		
179520-000	"3-1201662-5", "44A0811-16-0CS3030"		
100987K001	"2-1190739-5"		
068579-000	"6-1190516-4", "44A0111-22-0-9-GRN-BLK"		
382232-015	"2-1192858-6", "44A1131-20-0/2/9-9-MX"		
571817-000	"44A9650-18-0/9-0", "4-1194534-5"		
725389-000	"44A9625-12-0"		
CN2362-000	"EPD-RWC-21433"		
F566273001	"2-1201228-1", "44A0111-16-0CK0001"		
488933-000	"1-1193658-5", "EPD-RWC-15761"		
512405K001	"6-1194026-3"		
382528-000	"8-1192864-8", "44A4131-22-0/2/9-9"		
168653-000	"7-1197915-6", "EPD-NAV-32502"		
707583-000	"8-1195546-3", "EPD-RWC-14232"		
CW4986-000	"EPD40417A-US-L012"		
742211K001	"1195792-1"		
EG8812-000	"400R1111-18-0-9"		
EM5643-000	"EPD-RWC-24980"		
CZ1119-000	"EPD-DND-23478"		

925003-000	"44A1131-22-0/2/9-93", "1197175-1"		
EM0485-000			
065887-000	"9-1190496-3", "EPD51190A-16-0"		
509813K001	"6-1194007-5"		
376085-000	"1192817-9", "44A0121-12-0/2-MX"		
453451K001	"2-1193404-4"		
CS7451-000			
618949-000	"10525-X-8CS1405", "9-1194889-9"		
D69701-000	"2-1201652-9", "EPD-ROK-10545"		
896412-000	"9-1198925-9", "EPD-RWC-16529"		
977469-000	"44AM1131-26-0/2/5-9", "1-1197552-7"		
EG1448-000	"44A1341-16-0/2/6/9-9"		
058513K001	"1-1190444-4"		
451033K001	"4-1193387-1"		
547099-000	"9-1197893-4", "EPD-ROK-10431"		
763353-000	"44A9665-16-0/2/5/9-0", "7-1195943-5"		
177393-000	"4-1191289-5", "44B1121-24-0/9-902CS2024"		
382331-008	"6-1192861-2", "44A0121-22-0/9-MX"		

CS2962-000	"44A1141-20-ELC4-9-F871"		
277566K001	"3-1198867-9"		
032895-000	"1-1190255-0", "EPD-RWC-12814"		
564059K001	"9-1194455-7"		
438393K001	"8-1193294-9"		
CS5793-000			
617885K001	"4-1194882-8"		
101654K001	"4-1197928-9"		
861777-000	"4-1197927-5", "EPD70023A-ING"		
382582-000	"6-1192865-4", "44A1131-14-0/2/9-9"		
237535-000	"2-1191746-7", "EPD42652A-US"		
D87947K001			
803403K001	"1-1196211-1"		
622507-000	"4-1194920-9", "EPD-RWC-14756"		
A85309-000	"5-1201073-7", "EPD-RWC-18313CS3092"		
EK5756-000	"ATFC0311-20-0-L380"		
884487K002	"4-1196883-8"		
634589K001	"9-1197889-7"		
098362K001	"7-1199501-0"		

D86741-000	"8-1200691-2", "EPD-RWC-10945-L087"		
592342K001	"6-1198926-8"		
852113K001	"1196643-7"		
EH2501-000	"44A9089-16-0/9-9CS3433"		
F06647-000	"ASC-RWC-18072", "6-1200829-7"		
017722-000	"2-1199625-3", "44AM1171-24-MSL7-9"		
C24263K001	"7-1200522-7"		
920823-000	"9-1197144-8", "EPD50914A-24-0"		
730730-001	"44A0111-22-0CS448", "4-1195708-5"		
256469-000	"8-1191876-8", "EPD-RWC-14216"		
CJ5175-000			
EG8808-000	"400R1111-14-0-9"		
645263-000	"4-1195096-1", "FB-44-7026-0225CS2527"		
941538-001	"44AM1121-20-0/9-9CS356", "2-1197290-1"		
376077-000			
CJ8983-000	"ASC15865-20-0-LEADED"		
310237K001	"8-1192348-1"		
584893-000	"44B1121-24-0/9-91", "5-1194631-1"		

401497-000	"5-1193031-1", "EPD52987A"		
D94660-000	"2-1201872-9", "44A0111-20-0-G135"		
016530-000	"3-1190129-0", "44AM4144-26-ELC4-0CS356"		
090309-000	"1190662-9", "FB-44-7026A-0217CS896"		
CN4744-000	"EPD48861A-US-L077"		
802849K001	"7-1196206-0"		
565913K001	"7-1197828-1"		
CU3928-000	"EPD27743A-L099"		
CU8798-000	"EPD-DND-21492-L067"		
282220-000	"8-1192108-2", "81044/12-16-0"		
165603K001	"4-1191195-8"		
295894K001	"3-1199501-6"		
778756-000	"44A0111-16-0-L030", "8-1199384-1"		
504667-000	"345M09A-22-38-0CS2041", "9-1193811-9"		
257418-000	"3-1199730-2", "44A1141-22-0/2/6/9-0-US"		
EG3927-000	"EPD100242 A-US-L012"		
C72503K001	"3-1200524-7"		
255375K001	"5-1191869-7"		

540384K001	"5-1199501-2"		
049085K001	"5-1190376-1"		
CX8464-000			
282000-015	"3-1192090-0", "44A0111-16-0-MX"		
857825-000	"3-1196685-9", "EPD-RWC-15512"		
240783K001	"1191769-6"		
EG9418-000	"EPD117803 A-US"		
381063-000	"1-1192849-6", "EPD52675A-22-0"		
282010-010	"8-1192091-8", "44A0111-18-0-MX"		
D66115K001	"7-1201127-6"		
CY2223-000	"EPD-DND-21461-L016"		
C01255K001	"2-1200384-2"		
EK0690-000	"EPD-DND-21745-L016"		
279195-000	"5-1192066-1", "345M15B-22-28-0CS2041"		
058015K001	"4-1190440-9"		
CL9784-000	"EPD-ROK-10476-L212"		
282020-018	"6-1192093-2", "44A0111-20-0-MX"		
355389-000	"2-1192668-4", "44B1121-24-0/9-93"		
CN2359-000			
CN8571-000			

501315-000	"1-1193748-4", "EPD86148A"		
F05946-000	"6-1200827-8", "44A1121-18-0/2-0-MX"		
CS2960-000	"44A1141-18-ELC4-9-F871"		
562567-000	"345M05B-20-20-0CS2041", "1194445-1"		
EM1354-000	"400R1141-14-0/2/5/9-0"		
375219-000	"1192811-5", "44A9664-18-0/2/9-0"		
123093-000	"3-1190895-8", "44A0111-20-0CS289"		
724720-001	"345/63B-26-84-0CS1913", "9-1195664-6"		
4652323001	"44A0111-22-0CK0001", "3-1198932-7"		
CF9539-000			
740419K001	"2-1195779-5"		
023386-000	"6-1199501-2", "EPD-NAV-88411"		
F65965-000	"EPD97242A-US", "6-1200521-9"		
CR8081-000	"44A1101-20-A048-9"		
229779-000	"9-1191688-2", "ASC15864-20-0"		
526227-000	"4-1194135-7", "EPD52979A"		

384182-000	"9-1192881-6", "44A1121-18-0/2-9-US"		
763311-000	"4-1195943-2", "EPD48807B-US"		
EK9402-000	"EPD-RWC-24327"		
382735-000	"2-1192867-6", "44A1221-22-0/9-9-MX"		
548533-000	"3-1194317-8", "EPD52884A-18-0"		
257767K001	"1-1191886-2"		
CM4937-000	"EPD-RWC-21091"		
768421-000	"1-1195988-0", "FLDWC0311-12-0"		
306845-001	"3-1192324-9", "44AM4121-16-0/9-9"		
980337-000	"44A3131-20-0/2/9", "4-1197575-3"		
6367803001	"44A1121-20-0/9-9CK0001", "8-1198932-3"		
CA2668-000			
996599K001	"2-1197706-4"		
538793K001	"4-1194228-0"		
322673-000	"6-1192442-1"		
CB8759-000	"EPD52955B-L179CS2979", "1899194-5"		
CX1155-000	"EPD40652C-L099"		
380633K001	"3-1192846-3"		



375861-000	"5-1192815-0", "EPD51030A-22-0"		
817429-000	"9-1196369-3", "EPD-RWC-13948"		
498373K001	"2-1193726-1"		
CY7496-000	"EPD87062A-US"		
037889-000	"7-1190292-3", "EPD32371B"		
CQ52553001	"44A1121-18-0/9-9CK0612"		
606723-000	"6-1194799-3", "EPD43502D-US"		
060347K001	"4-1190457-7"		
559207-000	"3-1194414-3", "EPD-ROK-10285"		
873187K001	"6-1196794-3"		
C22417-000	"1-1200803-4", "EPD46193A-US"		
073241-000	"4-1190548-1", "EPD52962A"		
303511K001	"6-1192298-9"		
377749K001	"6-1192828-4"		
CS7761-000	"EPD-DND-21462-L099"		
325553-000	"5-1192463-3", "44A1131-16-0/5/9-0"		
EK4593-000	"FLDWC6004-14-0"		
600329-000	"9-1194747-2", "EPD5840-20-0CS1898"		

524921-000	"345/25B-20-12-0CS1913", "4-1194123-1"		
330825-000	"3-1192499-9", "CSC-0188-22-0"		
CS8296-000	"EPD-DND-21459-L016"		
203597K001	"9-1191475-8"		
298129-000	"6-1192257-6", "44A0121-24-0/9-S166"		
D84899-000	"3-1200594-7", "FB-44-4022-0001-L082"		
241737K001	"3-1197909-8"		
850179-000	"9-1196628-0", "EPD51160A"		
CF1044-000	"EPD-RWC-19272-L140"		
A69162-000	"3-1201851-4", "PRO-345M18B-72-0C2925L027"		
836211K001	"6-1196527-0"		
801295K001	"1196195-3"		
EH2548-000	"44A9675-20-0/9-9CS3433"		
A81239-000	"7-1201263-5", "EPD-RWC-18456"		
192117K001	"4-1191393-5"		
634367K001	"3-1195017-8"		
900375K001	"7-1196998-6"		
119482K001	"9-1198863-7"		
290509-000	"3-1192202-8", "EPD51486A-16-0"		

377477K001	"6-1192826-1"		
CN8274-000	"EPD-RWC-21402-L004"		
466115K001	"3-1193494-2"		
CS6991-000	"44A1821-18-0/9-3-1KF/1"		
CR8494-000	"44/7004-20-0-US"		
768140-000	"44A0121-24-0/6CS356", "7-1199212-7"		
CA7493-000	"EPD-NAV-32507"		
746037-000	"44A9675-22-0/9-9CS2746", "2-1195820-6"		
CX8628-000	"EPD-DND-23325"		
CU6383-000			
709341-000	"6-1195558-0", "FB-44-7026A-0201CS896"		
383762-000	"8-1192877-4", "44A0121-24-0/4-US"		
ER0344-000	"44A1221-14-0/2-9-MX"		
D92382-000	"5-1201134-7", "EPD73248A-US"		
128276-000	"7-1199199-8", "EPD-ROK-10425"		
863693-000	"2-1196726-1", "EPD8492B"		
CB6883-000	"EPD37259A-US-CS3207-L099"		
CX6374-000	"EPD-RWC-23210-L201"		
718375K002	"3-1195619-6"		

604761-000	"44A9678-20-0/9CS2747", "1-1194785-3"		
CF3585-000			
511741-000	"44A9665-12-0/2/5/9-0", "2-1194022-2"		
CS7461-000	"EPD-DND-21441-L099"		
EL5756-000	"EPD-RWC-24465"		
EG8848-000	"400R1131-18-0/6/9-9"		
276995-000	"2-1192051-4", "44AM4141-12-ELC4-9CS356"		
CU7290-000	"81044/12-22-0CS3334"		
EG8832-000	"400R1121-20-0/9-9"		
988081-000	"345M15B-22-6-0CS2041", "9-1197633-8"		
CS2766-000	"44A1131-18-0/2/9-9-F871"		
382509-002	"5-1192864-1", "44A1141-20-0/2/5/9-9-MX"		
CZ3911-000	"44A1121-24-0/9-9-L004"		
CA2667-000			
600369K001	"2-1194748-5"		
553105-000	"1-1194371-1", "PRO-EPD-RWC-15689"		
306040-001	"3-1192317-6", "44AM1121-20-0/2-9"		
EG8800-000	"400R0111-24-0"		
EG2808-000	"44A0111-24-0-E626"		

116883K001	"5-1190851-0"		
251629-002	"9-1197925-2", "EPD68645A-ING"		
764866-000	"44B1121-16-0/9-91CS2025", "7-1195954-1"		
439579-000	"4-1193303-3", "EPD48861A-US"		
306428-002	"3-1192321-3", "44AM1141-24-0/2/5/9-9"		
CZ9873-000	"EPD-DND-21489"		
CR9269-000	"81044/12-12-0-BARREL"		
CA3514-000			
737555-000	"44AM1122-16-0/9-9", "3-1195758-2"		
CS7475-000	"EPD-DND-21445-L099"		
CS2605-000			
E18525W001	"8-1202035-9"		
CF3606-000	"44/7004-26-0CS2979", "6-1899213-5"		
D50710-000	"44A9605-18-0"		
883341-000	"44A0111-18-0CS289", "1-1196875-4"		
386298-000	"1192898-3", "44A7662-20-8"		
CB6848-000			
282030-013	"9-1192095-9", "44A0111-22-0-MX"		
2820953001	"7-1192103-4", "44A0211-22-0"		

843347K001	"1196579-5"		
518763K002	"4-1194071-9"		
378003F003	"5-1192830-3"		
853825K001	"2-1196656-5"		
532133K001	"6-1194178-0"		
704479K002	"1195526-2"		
948781-000	"44A1331-18-0/2/9-9CS2746", "7-1197340-5"		
116757-000	"6-1190850-9", "EPD-ROK-10309-L027"		
289789-000	"2-1192197-9", "EPD-RWC-15760"		
866117K001	"2-1196744-8"		
379414-000	"9-1192837-8", "EPD4762D"		
CS9467-000	"EPD40420A-US"		
258597-000	"1191892-2", "EPD-RWC-10303"		
166221-000	"9-1191199-5", "FLDWC0311-22-0"		
CZ7562-000	"44A0161-22-G239"		
512851K001	"7-1194029-3"		
CX1606-000	"EPD-DND-21535"		
539365-000	"44A9111-X-9-9CS1663", "2-1194232-4"		
383333-000	"8-1192873-5", "44A1121-20-0/9-93"		
CB8618-000			

493921K001	"2-1193694-4"		
387724-000	"8-1192911-7", "44A1111-18-0-9-MX"		
CX0035-000			
127923-000	"7-1190929-2", "EPD51050A-18-0"		
951623K002	"9-1197368-7"		
998655K001	"5-1197721-6"		
194551-000	"4-1191411-5", "EPD52246A-X-0"		
CB9481-000	"EPD43500G-US-CS3210", "9-1899196-2"		
383059-000	"6-1192870-6", "44A0131-22-0/2/9-MX"		
382581-000	"44A1121-14-0/9-9-MX"		
458231-000	"345M16B-18-38-0CS2041", "1193438-2"		
293251K001	"7-1192222-2"		
E72147-000	"7-1200816-3", "EPD94682A-US"		
CX0662-000			
232588K001	"9-1197925-0"		
606621-000	"44A0111-16-0CS2896", "6-1197826-4"		
CY1332-000			
282400-000	"1202062-7", "81044/11-20-0"		
054649-000	"1190417-3", "EPD32071B-US"		

905489K001	"9-1197035-5"		
051356-004	"1197970-4", "EPD23928A-US"		
E17748K001	"4-1201922-1"		
374303-000	"5-1192803-9", "44A0141-18-0/2/6/9"		
467469-000	"345M09B-22-38-0CS2041", "9-1193503-5"		
383344-000	"1-1192874-1", "44A1121-22-0/9-95"		
271306-000	"2-1199104-6", "EPD-RWC-16559CS2965"		
750339-000	"6-1195851-8", "EPD-RWC-13952"		
947973-000	"44AM1121-22-0/9-93", "2-1199509-2"		
068949K001	"4-1190519-0"		
545849K001	"6-1194295-8"		
EG8838-000	"400R1121-26-0/9-9"		
336085K001	"1-1192538-9"		
474636-000	"4-1199869-2", "EPD-ROK-10477"		
753415K001	"8-1195873-0"		
152126K001	"8-1199172-7"		
CS2762-000	"44A4121-18-0/9-9-F871"		
387086-000	"1-1192905-6", "44A1111-24-0-9-MX"		



383455-000	"1-1192875-3", "44A0121-18-0/2"		
982369K001	"9-1197589-8"		
CX1604-000	"EPD-DND-21452"		
EK0689-000			
386637-000	"1192900-6", "44A4121-12-0/9-9"		
465321-000	"8-1193488-9", "EPD20019C"		
536791-000	"5-1194213-6", "EPD-RWC-12643"		
374403-000	"4-1200973-3", "44A0151-24-0/2/4/6/9-US"		
CU6480-000	"EPD-DND-21489-L099"		
CS2818-000	"44A1121-20-0/9-9-F871"		
573674-001	"7-1194553-9", "EPD23571B"		
950351-000	"44AM1111-24-0-9CS356", "8-1197349-3"		
229138-000	"9-1199130-1", "EPD95158A-US"		
A72650-000	"2-1200876-0", "EPD20323B-US-L099"		
EJ0477-000	"FLDWC0311-20-0CS2736"		
357841K002	"7-1192684-9"		
CP3495-000	"EPD-RWC-20754"		
CU8701-000	"EPD-DND-21441-L279"		

265094-000	"5-1191953-7", "44A0811-10-0-MX"		
CX0038-000	"EPD-DND-21485-L099"		
572841-000	"1-1194548-2", "EPD48809B-X-0"		
050887-000	"1-1190390-0", "FLDWC6000-1.5-0"		
CU8795-000			
CU0504-000	"44AM1141-24-ELC4-9CS262"		
339355K001	"2-1192561-0"		
E73954-000	"3-1201859-1", "EPD5841-20-0-5CF/1"		
C66832K001	"4-1201235-7"		
035871K002	"1190277-1"		
CY7493-000			
CP6418-000	"EPD-RWC-21574"		
A41319K001	"9-1201055-0"		
308931K001	"8-1192339-2"		
C87639-000	"44AM1121-20-0/2-3", "8-1200571-0"		
EG8818-000	"400R1111-24-0-9"		
940073-000	"81044/12-26-02", "5-1197279-5"		
757949-000	"8-1195905-9", "EPD-ADD-10002"		
892519-000	"44A0141-22-0/2/6/9CS356", "5-1196942-1"		

CS2552-000	"44A4121-20-0/9-9-F871"		
CU3841-000	"EPD40654D-L099"		
127643-000	"8-1190927-4", "44A9675-18-0/9-9CS2746"		
036633K001	"9-1190282-4"		
529509K001	"9-1197830-2"		
228501-000	"1-1191681-2", "81044/12-24-0CS294"		
005800K001	"8-1198262-3"		
EH7673-000	"EPD-DND-21444"		
382524-002	"7-1192864-9", "44A1141-20-0/2/6/9-9-MX"		
349257K001	"8-1192627-1"		
378315-000	"1199022-3", "44A0131-22-0/2/6-US"		
124861K001	"8-1190907-1"		
793615-000	"7-1196144-0", "EPD37112B"		
973667K001	"2-1197525-1"		
382361-000	"1-1192862-3", "44A1131-18-0/2/9-9-MX"		
EF4917-000	"EPD-RWC-19939-L027"		
CF3682-000	"44AM1111-18-0-9CS356"		
CU3945-000	"EPD27742A-L099"		
175355K001	"1191275-7"		

427387-000	"8-1193215-6", "44A9675-20-0/9-9CS2746"		
557219-000	"44AM1111-16-05-9", "4-1194395-5"		
CN6735-000			
EK9471-000			
CU8799-000			
791909-000	"44B1121-24-0/9-901", "1-1196133-5"		
215711-000	"1-1191558-0", "44A9676-18-0/2/9-9CS2746"		
EG9468-000			
240078-000	"6-1200334-4", "44A1141-24-0/3/6/9-9-US"		
090423-000	"1190663-6", "EPD-RWC-11286"		
482431-000	"1193611-8", "EPD45287B-US"		
327123K001	"1192475-4"		
CX8626-000			
EH7672-000			
285308-000	"6-1201266-5", "81044/12-20-09"		
CY1270-000	"EPD-DND-21508"		
628672K001	"2-1198862-8"		
893403-000	"1196949-1", "CMC-0403-X-0"		
630881K001	"5-1194992-8"		
D39425K001			
448670-000	"1199808-6", "44A0111-10-0CS2979"		

EL6427-000	"44AM1131-20-0/2/9-9CS3451"		
156695-000	"2-1191132-8", "EPD32266A-US"		
CU3830-000	"EPD40616C-L099"		
382279-000	"5-1192859-9", "44A0124-26-0/9"		
382382-000	"4-1192862-7", "44A0121-20-0/9-MX"		
425961K001	"9-1193205-6"		
769933K001	"2-1195999-0"		
CN5823-000			
CU6385-000			
373039-000	"1-1192794-2", "44A1121-22-0/2-3-US"		
394149-002	"6-1198260-4", "EPD32867A-US"		
664823-000	"6-1195238-6", "EPD51051A-18-0"		
A41350K001	"1-1200541-7"		
331895-000	"9-1192507-5", "44A1161-22-A973-9"		
572215K001	"1-1194542-5"		
619471-000	"7-1194893-4", "EPD-RWC-12813"		
306610-000	"8-1192322-2", "44AM1141-22-0/2/6/9-9"		
CL6050-000			
767991K001	"8-1195984-6"		

732160-001	"44AM4131-22-0/2/9-9", "5-1195719-0"		
489417K001	"6-1193661-9"		
F23108-000	"5-1202052-3", "WXA-0101-18-0CS2979"		
602393-000	"44A0111-10-04", "4-1194768-4"		
CL4519-000	"EPD-RWC-20307-L208"		
383020-000			
839587K001	"1-1196551-4"		
CW7557-000	"EPD-DND-22784-L016"		
801107-000	"8-1196193-6", "EPD43504G-US"		
777517-000	"44A9664-14-0/2/9-0", "5-1196052-8"		
754399-000	"1195881-2", "EPD52957A"		
CA9994-000	"EPD-RWC-20161-L009"		
CL4461-000	"EPD-RWC-19272"		
CX8470-000			
838545-000	"1-1196544-1", "EPD52970A"		
F47024-000	"44AM1151-20-G100-9CS356", "7-1201052-7"		
EH2507-000	"44A9091-16-ELC4-9CS3433"		
CN5815-000			
D22391-000	"44AM1121-16-0/9-0", "1200395-3"		

CN6734-000			
CU8794-000	"EPD-DND-21447-L281"		
396167K001	"5-1192971-9"		
749353-000	"5-1195844-6", "EPD-RWC-14231"		
E24553-000	"8-1201396-5", "ATFC0311-18-0CS2979"		
938147-000	"7-1197267-4", "EPD38848A"		
CS8049-000	"EPD-DND-21535-L016"		
035943-000	"4-1190277-8", "EPD52975A"		
049571-000	"8-1190379-0", "EPD51016A-20-0"		
CX1183-000	"EPD-DND-21451-L016"		
389504-003	"7-1201439-6", "44A0161-22-0/2/3/4/6/9-US"		
EF5951-000	"EPD-RWC-23973"		
993261-000	"9-1201542-9", "44A1121-18-0/1-9-MX"		
980455K001	"4-1197576-4"		
741043K001	"6-1195783-7"		
351359K001	"4-1192641-8"		
306812-000	"2-1192324-4", "44AM4121-20-0/9-9"		
EF7262-000	"44A1131-22-0/2/9-9CS3068"		

3822293013	"1-1192858-0", "44A1121-20-0/9-9"		
605659-000	"345/41B-22-20-0CS1913", "1194792-2"		
061388-000	"9-1198713-5", "FLDWD0311-10-0"		
631661K001	"2-1194998-0"		
C96830-000	"44AM1121-24-0/1-9CS356", "3-1200704-9"		
D13045-000			
CS5207-000	"EPD-ROK-10545-L106"		
091565-000	"2-1190671-6", "44A0171-20-F989-US"		
477227-000	"1-1193574-0", "WXA-0165-14-0"		
757079-000	"5-1195899-7", "EPD-ROK-10315"		
383487-000	"5-1192875-3", "44A1121-20-0/9-95"		
605546K001	"8-1198866-1"		
CR3182-000	"EPD-RWC-18510-L012"		
290450-001	"9-1192201-9", "345M15B-22-20-0CS2041"		
062845-000	"2-1190475-8", "EPD51037A-22-0"		
671259-000	"4-1195282-1", "EPD-RWC-15758"		
981947K001	"8-1197586-1"		



826363-000	"1196455-9", "EPD64090A "		
CX8475-000			
756261K001	"8-1195893- 2"		
732467K001	"8-1195721- 5"		
D99786-000	"6-1201493- 8", "FLDWD031 1-10- 0CS2979"		
067979K001	"2-1190512- 7"		
CF6956-000	"44AM1121- 18-0/9- 9CS2979", "3- 1899230-2"		
941085-000	"8-1197286- 8", "EPD23067B- X-0"		
CP6360-000	"EPD-DND- 22022"		
572291-000	"44B1121-16- 0/9- 92CS2025", "7-1194542- 5"		
692451K002	"9-1195435- 3"		
393043K001	"1192949-9"		
810853-000	"1-1196301- 8", "EPD52980A "		
CB6784-000	"EPD52955B- CS2979", "1899181-4"		
320017-000	"8-1192426- 5", "44AM1131- 16-0/2/6-0"		
211143K001	"7-1191529- 8"		
C65146-000	"44A0111-20- 0CS2896", "3- 1200881-0"		
CU3940-000			

517333-000	"8-1194061-2", "EPD-RWC-15749"		
CU9603-000	"EPD-DND-22022-L016"		
307099-000	"2-1192326-0", "EPD70319A-22-0"		
263902-000	"2-1191942-8", "81044/12-24-01"		
EG8844-000	"400R1131-14-0/6/9-9"		
719795-000	"1-1195629-8"		
382751-000	"4-1192867-0", "44A1121-22-0/2-9-MX"		
218481-000	"7-1200521-8", "ASC15865-20-0"		
3C0583-000	"6-1193002-0", "EPD5908-14-0"		
D00524-000	"2-1201883-0", "44A0114-18-0-L095"		
CS7452-000	"EPD-DND-21440-L099"		
187647-000	"9-1191361-8", "44AM1121-22-0/9-92"		
250461K001	"1191836-6"		
374188-000	"8-1201170-5", "44A0121-14-0/2-US"		
046343-000	"9-1190355-2", "EPD51484A-22-0"		
539574K001	"6-1201055-4"		
241041K001	"8-1191770-9"		
EH8634-000	"400R0311-10-0"		

867961-000	"44AM1121-22-0/9-0", "1-1196757-7"		
178811-000	"9-1191299-6", "44A9664-16-0/2/9-0"		
C919163001	"2-1201336-5", "44A0111-18-0CK0001"		
979152K001	"3-1197870-9"		
CJ4658-000	"EPD51047A-18-0CS2979", "6-1899288-9"		
104997-000	"6-1190767-5", "44T1121-20-0/9-9"		
026283K001	"1190204-3"		
CU6274-000			
452149-000	"1-1193395-8", "EPD-RWC-14596"		
794805K001	"9-1196152-0"		
CX5292-000	"EPD-DND-21488-L016"		
306017-001	"1192317-7", "44AM1121-16-0/9-9"		
384443-002	"7-1192884-7", "44A1321-20-0/9-9"		
383345-000	"1-1192874-5", "44A1121-22-0/9-96"		
815573-000	"1196356-3", "FB-44-5022-0146"		
CZ0629-000	"EPD-DND-21447"		
422451-000	"4-1193181-3", "44A0111-16-0CS289"		
477735-000	"44A9665-18-0/2/5/9-0", "8-1193577-4"		
631136K001	"1-1199953-6"		

382602-000	"8-1192865-9", "44A1121-24-0/2-9-MX"		
547345-000	"44A9681-18-0/9-9CS2748", "1-1194309-7"		
328367-000	"5-1192483-1", "EPD37111B-US"		
CR9507-000	"44A1821-18-0/9-2"		
CA5242-000	"44A0111-10-0-L032CS2979", "7-1899120-8"		
306265-000	"4-1192319-6", "44AM1121-26-0/2-9"		
102537-000	"3-1190750-8", "81044/12-16-0-1KF/1"		
C03812-000	"1201127-6", "EPD60087A-US"		
353153-000	"6-1192652-5", "FB-44-7026A-0220CS896"		
CX1589-000	"EPD-DND-21536"		
275373K001	"5-1192039-9"		
CN5901-000			
382229-019	"9-1192857-6", "44A1121-20-0/9-9-MX"		
810980-000	"44A9615-26-0/9", "3-1200151-8"		
343093-000	"7-1192584-7", "44A9650-16-0/9-0"		
EG8822-000	"400R1121-10-0/9-9"		

064179-000	"1-1190485-5", "44AM1131-26-0/2/9-9CS356"		
EH2586-000	"44A9676-20-0/2/9-9CS3433"		
752573-000	"44AM1131-20-0/6/9-9", "1197820-4"		
009349-000	"6-1190072-3", "44A1171-20-A052"		
CU3840-000			
222379-000	"1-1191638-1", "EPD90236A-US"		
704989K001	"6-1195529-4"		
C56890K001	"4-1200976-7"		
000933K001	"1190007-5"		
778763K001	"1-1196061-9"		
870367K002	"7-1196774-1"		
CB7021-000			
306810-000	"2-1192324-0", "44AM4121-24-0/9-9"		
963939K001	"7-1197455-8"		
226488-001	"7-1191667-0", "44AM4121-16-0/9-9CS356"		
539649K001	"1194234-7"		
349952K001	"2-1198867-9"		
276095K001	"1192045-1"		
565381K001	"2-1194465-2"		
295559K001	"3-1192239-0"		

133361K001	"5-1190968-4"		
CR3724-000			
CX8743-000	"EPD-DND-23309"		
CX9743-000			
991911-000	"2-1197672-9", "44AM1141-20-ELC4-9CS262"		
922724K001	"8-1199500-1"		
770373K001	"1-1196002-3"		
CA7492-000			
099809K001	"3-1190731-7"		
946509K001	"4-1197324-7"		
F31876-000	"EPD-ROK-10511-L022", "8-1201069-4"		
CP3789-000	"EPD20323B-US"		
EG4280-000			
104007-000	"8-1190760-5", "44B1141-16-0/1/7/8-9CS356"		
383263-000	"9-1192872-7", "44A0121-18-0/9-MX"		
274959-000	"5-1192036-0", "EPD40415A-US"		
CS7460-000			
873305-002	"9-1198253-9", "EPD32868A-US"		
A60275K001	"1-1200695-1"		
CM2771-000	"44B1121-12-0/9-9"		

520397-000	"44AM1121-24-0/6-9CS356", "8-1194090-8"		
EF5981-000	"EPD-RWC-13644-L342"		
CA5436-000	"FLDWC0311-26-0CS2979", "7-1899120-5"		
054882-000	"7-1190418-2", "EPD23070B"		
285750-010	"2-1192161-8", "44A0111-26-0-US"		
CS2606-000			
172013-000	"4-1191251-1", "FLDWC0311-24-0"		
382252-000	"1192859-7", "44A1131-22-0/1/9-9"		
601735-000	"6-1194763-7", "EPD-RWC-10650"		
379165-000	"44A1124-24-0/4-9"		
022892-000	"9-1199499-1", "EPD-NAV-85409"		
240755-000	"8-1191768-7", "EPD-ROK-10173"		
E56239-000	"ATFC0311-22-0"		
195507-000	"8-1191417-5", "ATFC0611-20-0"		
200981K001	"2-1191457-8"		
F83260-000	"ASC15865A-20-0", "7-1199617-1"		
3L0660-000	"4-1193010-5", "EPD9836-US"		

378004F003	"5-1192830-6"		
626838-000	"3-1194964-1", "EPD20019C-CS2231"		
CR3657-000			
334415-000	"2-1192526-7", "81044/12-26-03"		
028809K001	"2-1190223-6"		
235355-000	"1-1191731-4", "EPD51036A-22-0"		
F14435-000	"EPD-ROK-10512", "9-1201056-3"		
009923K001	"8-1190076-7"		
EM3775-000	"44AM1121-22-0/9-9-L227"		
EG3894-000	"EPD96868A-US"		
969387K001	"6-1197494-2"		
588329K001	"3-1194655-3"		
816382-000	"3-1197982-4", "EPD-RWC-16409"		
EH8638-000	"400R0311-14-0"		
D11588K001	"9-1200523-8"		
CX1596-000	"EPD-DND-21547"		
833054-000	"8-1197956-2", "EPD-RWC-16329"		
362999-000	"345M15B-22-74-0CS2041", "6-1192721-0"		
906255-000	"44A9698-14-F955-0", "1197041-6"		



397351-000	"1-1192980-3", "EPD-RWC-15762"		
359729K001	"1-1192699-7"		
265201-000	"8-1191955-7", "81044/9-22-0"		
636503-000	"44AM1121-22-0/9-2", "6-1195032-9"		
CY0039-000	"EPD-DND-23349"		
EG6684-000	"FLDWC0311-16-0CS3422"		
CR3721-000	"EPD-RWC-21564"		
CF3311-000	"44AM1121-26-0/6-9CS356"		
677314-000	"44A1221-14-0/9-9-1KF/1", "6-1198781-8"		
CS7758-000	"EPD-DND-21452-L099"		
056473K001	"9-1190429-7"		
784905K001	"1196092-7"		
3421363001	"1198932-1", "44A0111-20-0CK0001"		
CA9992-000			
628179-000	"5-1194973-3", "FLDWC0311-26-0"		
382091-000	"7-1192856-5", "44A7663-20-8"		
335111K001	"5-1192531-2"		
294597K001	"1192232-8"		
EH2690-000	"44A4331-22-0/2/9-9CS3433"		
CX7190-000	"EPD-RWC-23210-L296"		

690105K001	"2-1195419-2"		
EG8816-000	"400R1111-22-0-9"		
436581-000	"8-1193281-6", "EPD-RWC-10815"		
834191-000	"9-1196512-4", "EPD51208A-16-0"		
CP2439-000	"EPD-DND-21508-L108"		
047291K001	"4-1190363-6"		
CU3927-000			
CJ3703-000			
840927K001	"7-1196560-9"		
EG8854-000	"400R1131-24-0/6/9-9"		
CN2375-000	"EPD68126A-US"		
CU7741-000	"EPD-DND-22842-L278"		
281047-000	"7-1192081-3", "EPD-RWC-14597"		
EG8196-000	"44A0131-20-0/2/6"		
CJ1644-000	"EPD100584 A-US"		
EK8675-000	"ATFC0311-20-0-SPL"		
860612K001	"2-1199501-5"		
381971-000	"2-1201719-1", "345M04J-20-30-0CS2041"		
158506K001	"4-1198927-9"		
958182K001	"5-1201236-1"		
388811-000	"345M18B-18-57-0CS2041", "1192919-3"		

210941-000	"1-1191528-6", "44A9647-14-0"		
175263-000	"3-1191274-7", "44B1121-24-0/9-901CS2024"		
CS7986-000	"EPD-DND-21508-L016"		
928727-000	"44AM1131-22-0/6/9-9", "9-1197200-0"		
D64889-000	"ASC-RWC-18073", "1-1200830-6"		
CB7184-000			
EK9399-000			
E52107-000	"44AM1121-20-0/2-6", "3-1200571-9"		
CX8423-000			
355395-000	"2-1192668-8", "EPD-RWC-14212"		
E30566-000	"7-1199874-2", "EPD37109B-US-CS2979"		
816667-000	"44A9663-18-0-0", "3-1196364-6"		
376113-000	"2-1192817-5", "44A1122-22-0/2-9"		
374700-000	"2-1192806-9", "44A9089-16-0/9-9"		
CY2156-000	"EPD-DND-21440-L013"		
CF2169-000	"EPD-RWC-20322CS3092"		
407253-000	"5-1193072-0", "44A2134-26-0/1/9-9CS706"		
A45242K001	"5-1200803-9"		

CU8692-000	"EPD-DND-21440-L177"		
804539-000	"44AM1111-18-04-9", "3-1196219-0"		
562363K002	"4-1194443-6"		
CW7556-000			
D78389K001	"5-1201378-4"		
282557-000	"7-1192118-2", "81044/11-22-0"		
C56267-000	"EPD-RWC-19902"		
142764-000	"1-1199126-1", "FLDWC0311-14-0CS2722"		
306309-000	"1192320-4", "44AM1131-18-0/2/9-9"		
A99211-000	"6-1201663-3", "EPD-RWC-18194"		
958907K001	"9-1197422-4"		
EL6394-000	"44AM1121-18-0/9-9CS3451"		
C95456K001	"4-1201391-9"		
374135-000	"3-1192802-0", "44A3131-22-0/2/9"		
CS2816-000	"44A1121-18-0/9-9-F871"		
EK7993-000	"EPD-RWC-17035-L012"		
CU8805-000	"EPD-DND-21488-L067"		
CZ4486-000			
847565-000	"4-1196610-0", "EPD83494B-US"		

973697-000	"7-1201747-0", "44AM4141-20-0/2/5/9-9"		
CJ3710-000	"EPD-RWC-20562-L192"		
CZ3294-000	"FLDWC0311-16-0CS2736"		
CS5794-000	"EPD-RWC-21427"		
128959-000	"7-1190936-2", "EPD-ROK-10024"		
457813-000	"345M09A-22-48-0CS2041", "2-1193435-8"		
389624K001	"7-1198260-4"		
679281K002	"1-1195340-5"		
CN5909-000			
D32329K001	"2-1200576-8"		
CX8627-000			
ER4103-000	"44A1241-18-0/2/7/9-9"		
CU5268-000			
CB8619-000			
737807K001	"1-1195760-3"		
894855-003	"6-1197970-1", "EPD68620A-ING"		
050667-000	"4-1190388-8", "44A1121-22-0/9-9CS406"		
F54924-000	"7-1201860-1", "EPD101773 A-US"		
CS2956-000	"44A1131-20-0/2/9-9-F871"		
EK9020-000	"44A0131-18-0/2/8"		

284853-000	"5-1192153-1", "44A0111-18-04-US"		
C41659K001	"2-1201127-6"		
672221K001	"3-1195289-3"		
CN3402-000	"EPD90234A-US"		
CZ4536-000	"81044/9-10-0CS3209"		
282262-000	"2-1192111-6", "44A0111-12-0-MX"		
771801K001	"2-1196012-9"		
717075-000	"5-1195609-6", "EPD-RWC-10950"		
224867-000	"3-1191656-8", "44A1831-10-0/2/9-9"		
327969-000	"1-1192481-4", "44A9676-22-0/2/9-9CS2746"		
825591K001	"8-1196448-2"		
F58387-000	"7-1201380-7", "EPD-RWC-18490"		
715081-000	"1195596-2", "EPD52977A"		
172855-000	"2-1191257-0", "44B1121-24-0/9-96"		
025568-000	"3-1190198-9", "44B1121-24-0/9-91CS2024"		
EG5996-000			
E11076-000	"44AM1121-20-0/2-4", "9-1200571-6"		
279775-000	"5-1192070-7", "44A9079-22-A389CS806"		

921581-000	"44A9681-20-0/9-9CS2748", "3-1197150-9"		
CP3572-000			
011009-000	"9-1190086-6", "EPD7369A-US"		
CX1647-000	"EPD-DND-21441-L289"		
308883K001	"5-1192339-6"		
CU6634-000			
CS4976-000	"44A1821-18-0/9-2-1KF/1"		
588961-000	"44B1121-24-0/9-93CS2024", "5-1194660-4"		
344409K001	"8-1192593-3"		
592945-000	"9-1194688-9", "EPD51072A-22-0"		
670355-000	"1195277-9", "44AM1131-24-0/2/9-9CS262"		
224428-000	"1200572-7", "44AM1121-20-0/2-5"		

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.